

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

HOBBS OCD

OCD-HOBBS

JUL 11 2011

FORM APPROVED
OMB No. 1004-0137
Expires July 31, 2010

SUNDRY NOTICES AND REPORTS ON WELLS
Do not use this form for proposals to drill or to re-enter an abandoned well. Use Form 3160-3 (APD) for such proposals.

RECEIVED

5. Lease Serial No.
NMNM-81633

6. If Indian, Allottee or Tribe Name

SUBMIT IN TRIPLICATE - Other instructions on page 2.

1. Type of Well

☒ Oil Well ☐ Gas Well ☐ Other

2. Name of Operator
DEVON ENERGY PRODUCTION COMPANY, LP

3a. Address
PO BOX 250, ARTESIA, NM 88211

3b. Phone No (include area code)
575-748-3371

4. Location of Well (Footage, Sec., T., R., M., or Survey Description)
UNIT O, 760' FSL & 1980' FEL, SEC 24, T22S, R32E

7. If Unit of CA/Agreement, Name and/or No.

8. Well Name and No.
CHECKERS 24 FEDERAL #7

9. API Well No.
30-025-34023

10. Field and Pool or Exploratory Area
RED TANK BONE SPRINGS

11. Country or Parish, State
LEA COUNTY, NM

12. CHECK THE APPROPRIATE BOX(ES) TO INDICATE NATURE OF NOTICE, REPORT OR OTHER DATA

TYPE OF SUBMISSION	TYPE OF ACTION			
<input type="checkbox"/> Notice of Intent	<input type="checkbox"/> Acidize	<input type="checkbox"/> Deepen	<input type="checkbox"/> Production (Start/Resume)	<input type="checkbox"/> Water Shut-Off
<input checked="" type="checkbox"/> Subsequent Report	<input type="checkbox"/> Alter Casing	<input type="checkbox"/> Fracture Treat	<input checked="" type="checkbox"/> Reclamation	<input type="checkbox"/> Well Integrity
<input type="checkbox"/> Final Abandonment Notice	<input type="checkbox"/> Casing Repair	<input type="checkbox"/> New Construction	<input type="checkbox"/> Recomplete	<input type="checkbox"/> Other
	<input type="checkbox"/> Change Plans	<input type="checkbox"/> Plug and Abandon	<input type="checkbox"/> Temporarily Abandon	
	<input type="checkbox"/> Convert to Injection	<input type="checkbox"/> Plug Back	<input type="checkbox"/> Water Disposal	

13. Describe Proposed or Completed Operation: Clearly state all pertinent details, including estimated starting date of any proposed work and approximate duration thereof. If the proposal is to deepen directionally or recompleat horizontally, give subsurface locations and measured and true vertical depths of all pertinent markers and zones. Attach the Bond under which the work will be performed or provide the Bond No. on file with BLM/BIA. Required subsequent reports must be filed within 30 days following completion of the involved operations. If the operation results in a multiple completion or recompleat in a new interval, a Form 3160-4 must be filed once testing has been completed. Final Abandonment Notices must be filed only after all requirements, including reclamation, have been completed and the operator has determined that the site is ready for final inspection.)

RE: REJECTION BY JIM AMOS WITH THE BLM OF FIRST INSPECTION OF WELL LOCATION ON 3/25/2011
(PLEASE SEE ATTACHED NOTES FROM JIM AMOS)

ADDITIONAL RECLAMATION RECOMMENDED BY BLM ON 3/25/2011 HAS BEEN COMPLETED AND IS READY FOR A SECOND INSPECTION.

14. I hereby certify that the foregoing is true and correct. Name (Printed/Typed)

JERRY MATHEWS (575-748-0161)

Title COMPLETIONS FOREMAN

Signature

Date 6/3/2011

ACCEPTED FOR RECORD

THIS SPACE FOR FEDERAL OR STATE OFFICE USE

Approved by

Title

Office

Conditions of approval, if any, are attached. Approval of this notice does not warrant or certify that the applicant holds legal or equitable title to those rights in the subject lease which would entitle the applicant to conduct operations thereon.

Title 18 U.S.C. Section 1001 and Title 43 U.S.C. Section 1212, make it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.

(Instructions on page 2)

JUL 11 2011

Devon Energy Production Company, LP
P. O. Box 250
Artesia, NM 88211

RE: NMNM81633; Checkers 24 Federal No. 7
760' FSL & 1980" FEL, Sec. 24, T22S-R32E
Lea County, New Mexico

The Sundry Notice dated 12/17/2010 has been "Rejected" for the following reasons: There is excess caliche on the access road and the well pad. The access road and pad have been ripped down the slope instead of across the slope. The location was not contoured to the original landform. Need to push the fill side of the location to the north and tie into the revegetated area of the pit. This will also cover the area in the middle of the location where caliche was removed, and the contractor ripped into virgin caliche pulling up chunks. Need to remove the well sign at the entrance, a flowline located on the west side of the location and mic. trash/debris around the edges of the location. Place a fence or barricade across the entrance (prefer a fence). Will need to seed with BLM #2. Notify Jim Amos @ 575-234-5909 when work is complete or if any questions.