Submit One Copy To Appropriate District State of New Mexico	Form C-103
Office Francis Minerals and Natural Recourses	January 20, 2011
1625 N. French Dr., Hobbs, NM 884688 OCD	WELL API NO. / 30-025-06836
1301 W. Grand Ave., Artesia, NM 88210 OIL CONSERVATION DIVISION	5. Indicate Type of Lease
District III 26 2011 1220 South St. Francis Dr. 1000 Rio Brazos Rd., Aztec, NM 874102 South St. Francis Dr.	STATE FEE
District IV Sama Fe, NWI 67505	6. State Oil & Gas Lease No.
1220 S. St. Francis Dr., Santa Fe, NM 87505	
SUNDRY NOTICES AND REPORTS ON WELLS	7. Lease Name or Unit Agreement Name
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)	J.N. CARSON NCT-C
1. Type of Well: ⊠Oil Well ☐ Gas Well ☐ Other	8. Well Number 9
2. Name of Operator CHEVRON U.S.A. INC.	9. OGRID Number 4323
3. Address of Operator	10. Pool name or Wildcat
15 SMITH ROAD, MIDLAND, TEXAS 79705	
4. Well Location	
Unit Letter I: 2086 feet from the SOUTH line and 766 feet from the EAST line	
Section 28 Township 21-S Range 37-E NMPM County LEA	
11. Elevation (Show whether DR, RKB, RT, GR, etc.)	
12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data	
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:	
PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK ALTERING CASING	
TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLING OPNS. P AND A	
PULL OR ALTER CASING MULTIPLE COMPL CASING/CEMENT JOB	
OTHER:	
All pits have been remediated in compliance with OCD rules and the terms of the Operator's pit permit and closure plan.	
Rat hole and cellar have been filled and leveled. Cathodic protection holes have been properly abandoned. A steel marker at least 4" in diameter and at least 4' above ground level has been set in concrete. It shows the	
A steel marker at least 4" in diameter and at least 4' above ground level has been set in concrete. It shows the OPERATOR NAME , LEASE NAME, WELL NUMBER, API NUMBER, QUARTER/QUARTER LOCATION OR	
UNIT LETTER; SECTION, TOWNSHIP, AND RANGE. All INFORMATION HAS BEEN WELDED OR	
PERMANENTLY STAMPED ON THE MARKER'S SURFACE.	
The location has been leveled as nearly as possible to original ground contour and has been cleared of all junk, trash, flow lines and other production equipment.	
Anchors, dead men, tie downs and risers have been cut off at least two feet below ground level.	
If this is a one-well lease or last remaining well on lease, the battery and pit location(s) have been remediated in compliance with	
OCD rules and the terms of the Operator's pit permit and closure plan. All flow lines, production equipment and junk have been removed from lease and well location.	
All metal bolts and other materials have been removed. Portable bases have been removed. (Poured onsite concrete bases do not have	
to be removed.)	
All other environmental concerns have been addressed as per OCD rules.	
Pipelines and flow lines have been abandoned in accordance with 19.15.35.10 NMAC. All fluids have been removed from non-	
retrieved flow lines and pipelines. If this is a one-well lease or last remaining well on lease, all electrical service, poles and lines, not to include primary service	
company equipment, has been removed from lease and well location.	
When all work has been completed, return this form to the appropriate District office to schedule an inspection.	
. /	
SIGNATURE SWLY J. Hu TITLE PRODUCTION TEA	AM LEADER DATE 07-25-2011
TYPE OR PRINT NAME BOBBY HILL E-MAIL: bobbyhill@chevron.com	PHONE: 575-394-1245
APPROVED BY: Wash Withalam TITLE Compliance Of	Picar DATE 07-27-11
Conditions of Approval (if any):	<u> </u>