

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

RECEIVED

By JKeys at 12:15 pm, Jan 05, 2016

Revised August 8, 2011

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Submit 1 Copy to appropriate District Office in accordance with 19.15.29 NMAC.

Release Notification and Corrective Action

OPERATOR

Initial Report Final Report

Name of Company	Chevron USA Inc.	Contact	Stephen Gwin
Address	15 Smith Rd, Midland, TX.	Telephone No.	575-263-0427 Cell - 575-408-0073
Facility Name	Red Hill 2 Battery	Facility Type	Battery
Surface Owner	Mineral Owner	API No. 30-025-41546 and 30-025-41907	

LOCATION OF RELEASE


Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
P	2	25S	33E	330	South Line	340	East Line	Lea

Latitude 32.153237 N Longitude 103.535237W

NATURE OF RELEASE

Type of Release	Flare	Volume of Release	3,102 mcf	Volume Recovered	
Source of Release	Flare	Date and Hour of Occurrence	11/1/2015 - 12/31/2015	Date and Hour of Discovery	11/1/2015
Was Immediate Notice Given?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom?			
By Whom?	Stephen Gwin	Date and Hour			
Was a Watercourse Reached?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.			
If a Watercourse was Impacted, Describe Fully.*					
Describe Cause of Problem and Remedial Action Taken.* Flaring is due to DCP intermittent compressor issues at their Antelope Ridge Facility. The flare is operated as a safety device.					
Describe Area Affected and Cleanup Action Taken.* N/A					

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: 	OIL CONSERVATION DIVISION		
Printed Name: Stephen Gwin	Approved by Environmental Specialist: 		
Title: Health and Environment Specialist	Approval Date: 01/05/2016	Expiration Date: ///	
E-mail Address: Stephen.gwin@chevron.com	Conditions of Approval: ///		Attached <input type="checkbox"/> nJXK1600544024
Date: 1/4/2016 Phone: 575-263-0427			

* Attach Additional Sheets If Necessary