

**From:** [Robinson, Gary, EMNRD](#)  
**To:** [Yu, Olivia, EMNRD](#)  
**Cc:** [Brown, Maxey G, EMNRD](#)  
**Subject:** Cameron - Leak  
**Date:** Monday, July 24, 2017 2:47:32 PM

---

Olivia, pictures of the leak on the Cameron Oil & Gas – Langlie Mattix 4 Fed #1 (32743) are on the L drive. It looks like they had a flowline leak by the heater in a poly line & replaced it w/ steel pipe. Most everything is covered up on the road & location. There is still recent staining around the heater, there are more issues you can see in RBDMS & in the pictures.

Gary Robinson  
NMOCD  
Compliance Officer  
Hobbs, NM

KEITH

Cameron Oil & Gas

GOCCORP.

Roswell NM

Mike 575-263-3028  
David 575-420-1108

LANGLIE MATTIX 4 FED

SEC. 4, T23S, R37E

1650' FSL & 660' FWL

LEA CO., NM LC-032452 "A"





500  
1-0  
500  
SWEET















