

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Form C-141
Revised April 3, 2017

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Submit 1 Copy to appropriate District Office in accordance with 19.15.29 NMAC.

Release Notification and Corrective Action

OPERATOR Initial Report Final Report

Name of Company Marathon Oil Permian LLC	Contact Raquel Chacon
Address 5555 San Felipe Street, Houston, Texas 77056	Telephone No. 281-910-0441 (cell) 575-297-0988 (office)
Facility Name: Rusty Anchor 7 Fed Com 1H	Facility Type: Oil and gas drilling facility

Surface: Owner: Federal	Mineral: Owner: Federal	API No. : 30-025-43240
-------------------------	-------------------------	------------------------

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
M	07	20S	33E	420	South	996	West	Lea

Latitude 32.581481 Longitude -103.707441

NATURE OF RELEASE

Type of Release : Fire	Volume of Release: NA	Volume Recovered : NA
Source of Release: Flare	Date and Hour of Occurrence 12/4/2017 8:30 pm	Date and Hour of Discovery 12/4/2017 8:30 pm
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? S. Tucker BLM, Olivia Yu NMOCD	
By Whom? Raquel Chacon	Date and Hour 12/5/2017 10:20 am	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

RECEIVED
By Olivia Yu at 8:42 am, Dec 18, 2017

If a Watercourse was Impacted, Describe Fully.*
Not applicable.

Describe Cause of Problem and Remedial Action Taken.*
High fluid level occurred in the separator causing fluid to enter gas line while gas was being sent to flare. When fluid evacuated flare, fluid ignited causing small fire at base of flare. Unit was shut down and fire was self-extinguished. Fluid evacuated from gas line. Repairs were made to the gas and fluid dumps to help manage the gas to fluid ratio in the separator.

Describe Area Affected and Cleanup Action Taken.*
Fire was located at the base of the flare. Contaminated soil cleaned and disposed of properly. .

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: Raquel Chacon	OIL CONSERVATION DIVISION	
Printed Name: Raquel Chacon	Approved by Environmental Specialist:	
Title: Sr. HES Environmental Professional	Approval Date: 12/18/2017	Expiration Date:
E-mail Address: rchacon@marathonoil.com	Conditions of Approval:	Attached <input type="checkbox"/>
Date: 12/12/2017 Phone: 281-910-0441(cell) 575-297-0988 (office)		

* Attach Additional Sheets If Necessary

nOY1735231495

From: Chacon, Raquel (MRO)
To: stucker@blm.gov
Cc: [Yu, Olivia, EMNRD](#)
Subject: Rusty Anchor 7 Fed Com 1 Fire
Date: Tuesday, December 5, 2017 10:20:28 AM

Had another fire at the Rusty Anchor 7 Fed Com 1 last night at approximately 8:30 pm. A contractor reported it and the unit was immediately shut down and the fire self-extinguished. The fire was on location directly under the flare. I will have a C-141 submitted as soon as we finish investigating.

Raquel Chacon
HES Environmental Professional
2423 Bonita St.
Carlsbad, NM 88220

Office: (575)297-0988

Cell: (281)910-0441