

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Form C-141
Revised April 3, 2017

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Submit 1 Copy to appropriate District Office in
accordance with 19.15.29 NMAC.

Release Notification and Corrective Action

OPERATOR

X Initial Report ☐ Final Report

Name of Company	Vanguard Operating, LLC	Contact	Chuck Johnston
Address	4001 Penbrooke Ste 201 Odessa, TX 79762	Telephone No.	432-202-4771
Facility Name	W. H. Turner Tank Battery (on #3 pad)	Facility Type	Tank Battery

Surface Owner	Fee	Mineral Owner	Private	API No.	30-025-37161
---------------	-----	---------------	---------	---------	--------------

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
K	29	21S	37E	2310	South	2270	West	Lea

Latitude 32.4489708 Longitude -103.1862488 NAD83

NATURE OF RELEASE

Type of Release	Oil and Produced Water	Volume of Release	150	Volume Recovered	150 bbls
Source of Release	Tank Battery ran over	Date and Hour of Occurrence	12-11-2017	Date and Hour of Discovery	12-11-2017 9:30 am
Was Immediate Notice Given?	X Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom?	Maxi Brown - left voice mail 12-11-2017 10:15 am		
By Whom?		Date and Hour			
Was a Watercourse Reached?	<input type="checkbox"/> Yes X No	If YES, Volume Impacting the Watercourse.			

If a Watercourse was Impacted, Describe Fully.*

RECEIVED

By Olivia Yu at 3:46 pm, Dec 20, 2017



Describe Cause of Problem and Remedial Action Taken.*

Water transfer pump malfunctioned and alarms failed allowing the tanks to run over inside of a lined containment. Vacuum trucks removed the standing fluid.

Describe Area Affected and Cleanup Action Taken.*

Fluid spilled into the lined containment. A vacuum truck removed the standing fluid. The liner and equipment will be pressure washed and a vacuum truck will removed the fluid for disposal.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: 	OIL CONSERVATION DIVISION	
Printed Name: Chuck Johnston	Approved by Environmental Specialist: 	
Title: EHS Specialist	Approval Date: 12/20/2017	Expiration Date:
E-mail Address: cjohnston@vnreneregy.com	Conditions of Approval:	Attached <input type="checkbox"/>
Date: 12-12-2017 Phone: 432-202-4771	Please inspect liner in question. Provide NMOCD with a concise report of the inspection with affirmation the liner has and will continue to contain liquids.	

* Attach Additional Sheets If Necessary

nOY1735456975