

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised August 8, 2011

Submit 1 Copy to appropriate District Office in
accordance with 19.15.29 NMAC.

Release Notification and Corrective Action

OPERATOR

☒ Initial Report ☐ Final Report

Name of Company: COG Operating LLC OGRID # 229137	Contact: Robert McNeill	
Address: 600 West Illinois Avenue, Midland TX 79701	Telephone No. 432-683-7443	
Facility Name: Federal USA L #006	Facility Type: Flowline	
Surface Owner: Federal	Mineral Owner:	API No. 30-025-33902

LOCATION OF RELEASE

Unit Letter K	Section 14	Township 19S	Range 33E	Feet from the 1650	North/South Line South	Feet from the 330	East/West Line West	County Lea
-------------------------	---------------	-----------------	--------------	-----------------------	---------------------------	----------------------	------------------------	---------------

Latitude 32.65821 Longitude -103.63804

NATURE OF RELEASE

Type of Release: Oil (Lightning Strike)	Volume of Release: Est. 3 bbls	Volume Recovered: 0 bbls
Source of Release: Flowline	Date and Hour of Occurrence: June 1, 2017 11:00 am	Date and Hour of Discovery: June 1, 2017 11:00 am
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Ms. Yu - NMOCD / Ms. Tucker - BLM	
By Whom? Rebecca Haskell	Date and Hour: June 2, 2017 Time of this Email	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

RECEIVED

By Olivia Yu at 11:35 am, Jun 02, 2017

If a Watercourse was Impacted, Describe Fully.*

Describe Cause of Problem and Remedial Action Taken.*

Lightning struck a poly flowline during a storm causing the release of fluid from the flowline and burned a section of the flowline. The section of flowline that was impacted during this event will be replaced.

Describe Area Affected and Cleanup Action Taken.*

The release was on the side of the lease road and within a pasture. A vacuum truck was dispatched to remove all freestanding fluids. Concho will have the spill area sampled to delineate any possible impact from the release and we will present a remediation work plan to the NMOCD for approval prior to any significant remediation activities.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: <i>Rebecca Haskell</i>	OIL CONSERVATION DIVISION	
Printed Name: Rebecca Haskell	Approved by Environmental Specialist: <i>gy</i>	
Title: Senior HSE Coordinator	Approval Date: 6/2/2017	Expiration Date:
E-mail Address: rhaskell@concho.com	Conditions of Approval:	Attached <input type="checkbox"/>
Date: June 2, 2017 Phone: 432-683-7443		

* Attach Additional Sheets If Necessary

nOY1715340682