

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Form C-141
Revised August 8, 2011

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Submit 1 Copy to appropriate District Office in
accordance with 19.15.29 NMAC.

Release Notification and Corrective Action

OPERATOR

Initial Report Final Report

Name of Company EOG Y Resources, Inc.	OGRID Number 25575	Contact Robert Asher
Address 104 S. 4 th Street	Facility Name Atoka Bank & Heartthrob Battery	Telephone No. 575-748-1471
Facility Type Battery	Facility Type Battery	
Surface Owner State	Mineral Owner State	API No. 30-025-41055

unknown battery location.

LOCATION OF RELEASE

Unit Letter B/C	Section 17	Township 24S	Range 33E	Feet from the	North/South Line	Feet from the	East/West Line	County Lea
---------------------------	---------------	-----------------	--------------	---------------	------------------	---------------	----------------	---------------

Latitude **32.22485** Longitude **-103.59429**

NATURE OF RELEASE

Type of Release Produced water	Volume of Release 130 B/PW	Volume Recovered 129 B/PW
Source of Release 3' water fill line	Date and Hour of Occurrence 1/10/2017; AM	Date and Hour of Discovery 1/10/2017; AM
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Kristen Lynch & Tomas Oberding/NMOCD I	
By Whom? Robert Asher/Yates Petroleum Corporation	Date and Hour 1/11/2017; AM (Email)	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

REVISED
2:12 pm, Mar 14, 2018

RECEIVED
By Olivia Yu at 2:45 pm, Mar 01, 2017

If a Watercourse was Impacted, Describe Fully.*

Describe Cause of Problem and Remedial Action Taken.*

A 3" water line from the heater treater developed a hole, causing the release. Vacuum truck(s) and roustabout crews were called.

Describe Area Affected and Cleanup Action Taken.*

An approximate area of 20' X 25' and 30' X 50' within the lined/bermed battery. Vacuum truck recovered 129 bbls of the released produced water (99%), the remaining produced water was removed with the gravel (gravel disposed at an NMOCD approve facility). The water line was repaired. **Depth to Ground Water: 50-99' (approximately 50', per ChevronTexaco Trend Map), Wellhead Protection Area: No, Distance to Surface Water Body: >1000', SITE RANKING IS 10. Based on the battery being lined/bermed, repairs made and 99% released produced water recovered, EOG Resources, Inc. requests closure.**

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: 	OIL CONSERVATION DIVISION	
Printed Name: Robert Asher	Approved by Environmental Specialist: 	
Title: Environmental Supervisor	Approval Date: 3/1/2017	Expiration Date:
E-mail Address: Robert_Asher@eogresources.com	Conditions of Approval:	Attached <input type="checkbox"/>
Date: January 19, 2017 Phone: 575-748-4217	Please inspect liner in question. Provide NMOCD with a concise report of the inspection with affirmation the liner has and will continue to contain liquids.	

nOY1807353035

* Attach Additional Sheets If Necessary