<u>District I</u>
1625 N. French Dr., Hobbs, NM 88240
<u>District II</u>
811 S. First St., Artesia, NM 88210
<u>District III</u>
1000 Rio Brazos Rd, Aztec, NM 87410
District IV

1220 S. St. Francis Dr., Santa Fe, NM 87505

## State of New Mexico Energy, Minerals and Natural Resources

Form C-141 Revised August 8, 2011

Oil Conservation Division 1220 South St. Francis Dr. Santa Fe, NM 87505 Submit 1Copy to appropriate District Office in accordance with 19.15.29 NMAC.

Release Notification and Corrective Action X Initial Report X Final Report **OPERATOR** Name Contact **XTO ENERGY INC.** Patty Urias Address Telephone No. 6401 Holiday Hill Road, Bldg 5, Midland, TX 79707 432.620.4318 **Facility Name** Facility Type PERLA VERDE 31 STATE BATTERY Well Mineral Owner API No. Surface Owner State State 30-025-42063 LOCATION OF RELEASE Unit Letter Feet from the North/South Line Feet from the East/West Line Section Township Range M 31 198 35E 170 South 330 West Lea Latitude 32.610118580258 -103.504215280 Longitude NATURE OF RELEASE Volume of Release Type of Release FLARE Volume Recovered 135 avg Date and Hour of Discovery 5/13/18 Source of Release Date and Hour of Occurrence 5/10/18 If YES, To Whom? Was Immediate Notice Given? X No Yes Not Required By Whom? Date and Hour Was a Watercourse Reached? If YES, Volume Impacting the Watercourse. Yes X No If a Watercourse was Impacted, Describe Fully. \* RECEIVED By Olivia Yu at 8:04 am, Jun 05, 2018 Describe Cause of Problem and Remedial Action Taken. \* Unexpected SI by Targa resulting in us flaring at Perla Verde 31 State Bty. PERLA VERDE 31 STATE #001H, 30-025-42063, #002H, 30-025-41861, 003H, 30-025-41862, #004H, 30-025-41863 Describe Area Affected and Cleanup Action Taken. \* XTO flared a total of 95 hrs and 538 mcf I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state or local laws and/or regulations. OIL CONSERVATION DIVISION Signature: Approved by Environmental Specialist: Printed Name: Patty Urias 6/5/2018 Title: Regulatory Analyst Approval Date: **Expiration Date:** patty\_urias@xtoenergy.com E-mail Address: Conditions of Approval: Attached 5/15/18 432.620.4318 Phone:

<sup>\*</sup> Attach Additional Sheets If Necessary