

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised August 8, 2011

Submit 1 Copy to appropriate District Office in
accordance with 19.15.29 NMAC.

Release Notification and Corrective Action

OPERATOR

☒ Initial Report

☒ Final Report

Name of Company: COG Operating LLC OGRID # 229137	Contact: Robert McNeill
Address: 600 West Illinois Avenue, Midland TX 79701	Telephone No. 432-683-7443
Facility Name: Monet Federal Com #003H Tank Battery	Facility Type: Tank Battery

Surface Owner: Federal	Mineral Owner:	API No. 30-025-42763
------------------------	----------------	----------------------

LOCATION OF RELEASE

Unit Letter C	Section 04	Township 25S	Range 33E	Feet from the 190	North/South Line North	Feet from the 1980	East/West Line West	County Lea
------------------	---------------	-----------------	--------------	----------------------	---------------------------	-----------------------	------------------------	---------------

Latitude 32.16674599 Longitude -103.5793769

NATURE OF RELEASE

Type of Release: Oil (Fire)	Volume of Release: EST. 0.25 bbls	Volume Recovered: 0 bbls
Source of Release: Flare	Date and Hour of Occurrence: May 31, 2017 6:00 am	Date and Hour of Discovery: May 31, 2017 6:00 am
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Ms. Yu NMOCD / Ms. Tucker BLM	
By Whom? Rebecca Haskell	Date and Hour: May 31, 2017 Time of this Email	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.*

RECEIVED

By Olivia Yu at 8:08 am, Jun 02, 2017

Describe Cause of Problem and Remedial Action Taken.*

This release was caused by fluids going to the flare from the gas scrubber.

Describe Area Affected and Cleanup Action Taken.*

The release occurred on location. No fluid was recovered due to the fire burning off any standing fluid.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: <i>Rebecca Haskell</i>	OIL CONSERVATION DIVISION	
Printed Name: Rebecca Haskell	Approved by Environmental Specialist: <i>gy</i>	
Title: Senior HSE Coordinator	Approval Date: 6/2/2017	Expiration Date:
E-mail Address: rhaskell@concho.com	Conditions of Approval:	Attached <input type="checkbox"/>
Date: May 31, 2017 Phone: 432-683-7443		

* Attach Additional Sheets If Necessary

nOY1715329154