

UNITED STATES  
DEPARTMENT OF THE INTERIOR  
BUREAU OF LAND MANAGEMENT

FORM APPROVED  
OMB NO. 1004-0137  
Expires: January 31, 2018

**SUNDRY NOTICES AND REPORTS ON WELLS**  
*Do not use this form for proposals to drill or to re-enter an abandoned well. Use form 3160-3 (APD) for such proposals.*

5. Lease Serial No.  
NMLC064118

6. If Indian, Allottee or Tribe Name

7. If Unit or CA/Agreement, Name and/or No.

**SUBMIT IN TRIPLICATE - Other instructions on page 2**

1. Type of Well <input checked="" type="checkbox"/> Oil Well <input type="checkbox"/> Gas Well <input type="checkbox"/> Other		8. Well Name and No. E C HILL B FED 20
2. Name of Operator OXY USA INCORPORATED		9. API Well No. 30-025-33495-00-S1
3a. Address P O BOX 4294 HOUSTON, TX 77210-4294		10. Field and Pool or Exploratory Area TEAGUE
3b. Phone No. (include area code) Ph: 713-215-7000		11. County or Parish, State LEA COUNTY, NM
4. Location of Well (Footage, Sec., T., R., M., or Survey Description) Sec 34 T23S R37E SWSE 1300FSL 2280FEL		

**12. CHECK THE APPROPRIATE BOX(ES) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA**

TYPE OF SUBMISSION	TYPE OF ACTION			
<input checked="" type="checkbox"/> Notice of Intent	<input type="checkbox"/> Acidize	<input type="checkbox"/> Deepen	<input type="checkbox"/> Production (Start/Resume)	<input type="checkbox"/> Water Shut-Off
<input type="checkbox"/> Subsequent Report	<input type="checkbox"/> Alter Casing	<input type="checkbox"/> Hydraulic Fracturing	<input type="checkbox"/> Reclamation	<input type="checkbox"/> Well Integrity
<input type="checkbox"/> Final Abandonment Notice	<input type="checkbox"/> Casing Repair	<input type="checkbox"/> New Construction	<input type="checkbox"/> Recomplete	<input type="checkbox"/> Other
	<input type="checkbox"/> Change Plans	<input type="checkbox"/> Plug and Abandon	<input checked="" type="checkbox"/> Temporarily Abandon	
	<input type="checkbox"/> Convert to Injection	<input type="checkbox"/> Plug Back	<input type="checkbox"/> Water Disposal	

13. Describe Proposed or Completed Operation: Clearly state all pertinent details, including estimated starting date of any proposed work and approximate duration thereof. If the proposal is to deepen directionally or recomplete horizontally, give subsurface locations and measured and true vertical depths of all pertinent markers and zones. Attach the Bond under which the work will be performed or provide the Bond No. on file with BLM/BIA. Required subsequent reports must be filed within 30 days following completion of the involved operations. If the operation results in a multiple completion or recompletion in a new interval, a Form 3160-4 must be filed once testing has been completed. Final Abandonment Notices must be filed only after all requirements, including reclamation, have been completed and the operator has determined that the site is ready for final inspection.

TD-5958?MD PBD-5888?MD Perfs-5266? ? 5773?MD

12 3/4? hole, 8 5/8? csg @ 1190? w/ 630 sx, TOC-surf  
7 7/8? hole, 5 1/2? csg @ 5958? w/ 1580 sx, TOC~4339?  
DV Tool @ 4339?

OXY USA Inc. respectfully requests to temporarily abandon this well. The TA is planned for March 2021. OXY is currently evaluating potential and therefore would like to TA the producing interval for future prospect and to remain in compliance.

1. POOH with production equipment. RIH and set CIBP @ +/- 5166?, dump 35sx CI C cement on top.
2. Notify NMOCD of casing integrity test 24 hours in advance.
3. RU pump truck, circulate well with treater water, pressure test casing to 500# for 30 min. RDMO.

14. I hereby certify that the foregoing is true and correct.

**Electronic Submission #524122 verified by the BLM Well Information System  
For OXY USA INCORPORATED, sent to the Hobbs  
Committed to AFMSS for processing by PRISCILLA PEREZ on 08/04/2020 (20PP3250SE)**

Name (Printed/Typed) APRIL SANTOS

Title REGULATORY SPECIALIST

Signature (Electronic Submission)

Date 08/04/2020

**THIS SPACE FOR FEDERAL OR STATE OFFICE USE**

Approved By JONATHON SHEPARD

Title PETROELUM ENGINEER

Date 08/14/2020

Conditions of approval, if any, are attached. Approval of this notice does not warrant or certify that the applicant holds legal or equitable title to those rights in the subject lease which would entitle the applicant to conduct operations thereon.

Office Hobbs

Title 18 U.S.C. Section 1001 and Title 43 U.S.C. Section 1212, make it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.

(Instructions on page 2)

**\*\* BLM REVISED \*\* BLM REVISED \*\* BLM REVISED \*\* BLM REVISED \*\* BLM REVISED \*\***

Accepted - KMS NMOCD

## Revisions to Operator-Submitted EC Data for Sundry Notice #524122

	<b>Operator Submitted</b>	<b>BLM Revised (AFMSS)</b>
Sundry Type:	TA NOI	TA NOI
Lease:	NMLC064118	NMLC064118
Agreement:		
Operator:	OXY USA INC 5 GREENWAY PLAZA SUITE110 HOUSTON, TX 77046 Ph: 713-215-7000	OXY USA INCORPORATED P O BOX 4294 HOUSTON, TX 77210-4294 Ph: 713.366.5303
Admin Contact:	APRIL SANTOS REGULATORY SPECIALIST E-Mail: APRIL_HOOD@OXY.COM  Ph: 713-366-5771	APRIL SANTOS REGULATORY SPECIALIST E-Mail: APRIL_HOOD@OXY.COM  Ph: 713-215-7000
Tech Contact:	APRIL SANTOS REGULATORY SPECIALIST E-Mail: APRIL_HOOD@OXY.COM  Ph: 713-366-5771	APRIL SANTOS REGULATORY SPECIALIST E-Mail: APRIL_HOOD@OXY.COM  Ph: 713-215-7000
Location:		
State:	NM	NM
County:	LEA	LEA
Field/Pool:	TEAGUE; PADDOCK-BLINEBRY	TEAGUE
Well/Facility:	E C HILL B FEDERAL 020 Sec 34 T23S R37E Mer NMP SWSE 1300FSL 2280FEL 32.257122 N Lat, 103.149605 W Lon	E C HILL B FED 20 Sec 34 T23S R37E SWSE 1300FSL 2280FEL

## BUREAU OF LAND MANAGEMENT

Carlsbad Field Office  
620 East Greene Street  
Carlsbad, New Mexico 88220  
575-234-5972

### Conditions of Approval for Temporary Abandonment of Wells

**Definition:** A temporarily abandoned well is a completion that is not capable of production in paying quantities, but which may have future value. Pursuant to 43 CFR 3162.3-4 (c), no well may be temporarily abandoned for more than 30 days without the prior approval of the authorized officer.

1. TA status will be effective for a period of up to one year from the date of sundry approval and can be renewed annually thereafter per IM NM-2016-017.
2. A bridge plug (CIBP) must be installed 50 to 100 feet above any open perforations or open hole. The CIBP must be capped with either a minimum of 25 sacks of cement if placed with tubing or 35 feet of cement if placed with a bailer. The top of the cement must be verified by tagging.
3. The wellbore must be filled with corrosion inhibited fluid and pressure tested to 500 psi. The casing shall be capable of holding this pressure for at least 30 minutes. If the well does not pass the casing integrity test, then the operator shall, within 30 days, submit a procedure to either repair the casing or to plug and abandon the well.
4. Contact the appropriate BLM office at least 24 hours prior to the scheduled Casing Integrity Test. For wells in Eddy County, 575-361-2822; Lea County 575-393-3612.
5. All downhole production/injection equipment (tubing, rods, etc.) shall be removed from the casing if it is not isolated by a packer.
6. A bradenhead test must be conducted. If the test indicates a problem, a remedial plan and time frame for remediation shall be submitted within ninety (90) days of the test.
7. Submit a subsequent Sundry Notice (Form 3160-5) with the following information:
  - a. A well bore diagram with all perforations, CIBP's, and tops of cement on CIBP's.
  - b. A description of the temporary abandonment procedure.
  - c. A clear copy or the original of the pressure test chart.