#### **UNITED STATES** DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT

**SUNDRY NOTICES AND REPORTS ON WELLS** Do not use this form for proposals to drill or to re-enter an abandoned well. Use form 3160-3 (APD) for such proposals.

FORM AP	PROVED
OMB NO. 1	1004-0137
Expires: Janua	ary 31, 2018
. Lease Serial No.	

NMLC034711 6. If Indian, Allottee or Tribe Name

SUBMIT IN TRIPLICATE - Other instructions on page 2			7.	7. If Unit or CA/Agreement, Name and/or No.			
Type of Well     ☐ Gas Well ☐ Other				Well Name and No.     BAYLUS CADE FED 07			
Name of Operator Contact: APRIL SANTOS     OXY USA INCORPORATED E-Mail: APRIL_HOOD@OXY.COM				9. API Well No. 30-025-33649-00-S1			
3a. Address P O BOX 4294 HOUSTON, TX 77210-4294  3b. Phone No. (include area code) Ph: 713-215-7000				10. Field and Pool or Exploratory Area TEAGUE			
4. Location of Well (Footage, Sec., T., R., M., or Survey Description)			11.	11. County or Parish, State			
Sec 35 T23S R37E NWSW 1890FSL 360FWL				LEA COUNTY, NM			
12. CHECK THE AP	PROPRIATE BOX(ES) TO IN	DICATE NATURE OF	NOTICE, RE	PORT, OR OTHER	DATA		
TYPE OF SUBMISSION	TYPE OF ACTION						
Notice of Intent	☐ Acidize	□ Deepen	☐ Production (	Start/Resume)	Water Shut-Off		
■ Notice of Intent	☐ Alter Casing	☐ Hydraulic Fracturing	☐ Reclamation		Well Integrity		
☐ Subsequent Report	☐ Casing Repair	■ New Construction	☐ Recomplete		) Other		
☐ Final Abandonment Notice	☐ Change Plans	□ Plug and Abandon		arily Abandon			
	☐ Convert to Injection	☐ Plug Back	☐ Water Dispo	Disposal			
If the proposal is to deepen directionally or recomplete horizontally, give subsurface locations and measured and true vertical depths of all pertinent markers and zones. Attach the Bond under which the work will be performed or provide the Bond No. on file with BLM/BIA. Required subsequent reports must be filed within 30 days following completion of the involved operations. If the operation results in a multiple completion or recompletion in a new interval, a Form 3160-4 must be filed once testing has been completed. Final Abandonment Notices must be filed only after all requirements, including reclamation, have been completed and the operator has determined that the site is ready for final inspection.  TD-9877?MD PBTD-9812?MD Perfs-9252? ? 9412?MD  17 ?? hole, 13 3/8? csg @ 370? w/ 330 sx, TOC-surf 11? hole, 8-5/8? csg @ 3005? w/ 550sx, TOC-11? 7-7/8? hole, 5-1/2? csg @ 9877? w/ 2155 sx, TOC~6021? 5 ?? DV Tool @ 6021?  OXY USA Inc. respectfully requests to temporarily abandon this well. The TA is planned for March 2021. OXY is currently evaluating potential and therefore would like to TA the producing interval for future prospect and to remain in compliance.  1. POOH with production equipment. RIH and set CIBP @ +/- 9152?, dump 35sx CI C cement on top.							
Electronic Submission #524062 verified by the BLM Well Information System For OXY USA INCORPORATED, sent to the Hobbs Committed to AFMSS for processing by PRISCILLA PEREZ on 08/03/2020 (20PP3236SE)							
Name(Printed/Typed) APRIL SA	NIOS	Title REGULA	Title REGULATORY SPECIALIST				
Signature (Electronic S	ubmission)	Date 08/03/20	Date 08/03/2020				
	THIS SPACE FOR FE	DERAL OR STATE (	OFFICE USE				
	rant or lease Office Hobbs r any person knowingly and v	Office Hobbs  TitlePETROELUM ENGINEER  Date 08/14/2020  Office Hobbs  Troon knowingly and willfully to make to any department or agency of the United					
States any false, fictitious or fraudulent s					-		

# Additional data for EC transaction #524062 that would not fit on the form

## 32. Additional remarks, continued

- 2. Notify NMOCD of casing integrity test 24 hours in advance.3. RU pump truck, circulate well with treater water, pressure test casing to 500# for 30 min. RDMO.

## Revisions to Operator-Submitted EC Data for Sundry Notice #524062

**Operator Submitted BLM Revised (AFMSS)** 

TA NOI TA NOI Sundry Type:

NMLC034711 NMLC034711 Lease:

Agreement:

Operator: **OXY USA INCORPORATED** 

OXY USA INC 5 GREENWAY PLAZA SUITE110 HOUSTON, TX 77046 P O BOX 4294 HOUSTON, TX 77210-4294

Ph: 713-215-7000 Ph: 713.366.5303

Admin Contact:

APRIL SANTOS REGULATORY SPECIALIST E-Mail: APRIL\_HOOD@OXY.COM APRIL SANTOS REGULATORY SPECIALIST E-Mail: APRIL\_HOOD@OXY.COM

Ph: 713-366-5771 Ph: 713-215-7000

Tech Contact:

APRIL SANTOS REGULATORY SPECIALIST E-Mail: APRIL\_HOOD@OXY.COM APRIL SANTOS REGULATORY SPECIALIST E-Mail: APRIL\_HOOD@OXY.COM

Ph: 713-366-5771 Ph: 713-215-7000

Location:

NM LEA State: County:  $\mathsf{NM}$ LEA

Field/Pool: TEAGUE; SIMPSON **TEAGUE** 

BAYLUS CADE FEDERAL COM 007 Sec 35 T23S R37E Mer NMP NWSW 1890FSL 360FWL Well/Facility: **BAYLUS CADE FED 07** 

Sec 35 T23S R37E NWSW 1890FSL 360FWL 32.258743 N Lat, 103.141678 W Lon

#### **BUREAU OF LAND MANAGEMENT**

Carlsbad Field Office 620 East Greene Street Carlsbad, New Mexico 88220 575-234-5972

## **Conditions of Approval for Temporary Abandonment of Wells**

**Definition:** A temporarily abandoned well is a completion that is not capable of production in paying quantities, but which may have future value. Pursuant to 43 CFR 3162.3-4 (c), no well may be temporarily abandoned for more than 30 days without the prior approval of the authorized officer.

- 1. TA status will be effective for a period of up to one year from the date of sundry approval and can be renewed annually thereafter per IM NM-2016-017.
- 2. A bridge plug (CIBP) must be installed 50 to 100 feet above any open perforations or open hole. The CIBP must be capped with either a minimum of 25 sacks of cement if placed with tubing or 35 feet of cement if placed with a bailer. The top of the cement must be verified by tagging.
- 3. The wellbore must be filled with corrosion inhibited fluid and pressure tested to 500 psi. The casing shall be capable of holding this pressure for at least 30 minutes. If the well does not pass the casing integrity test, then the operator shall, within 30 days, submit a procedure to either repair the casing or to plug and abandon the well.
- 4. Contact the appropriate BLM office at least 24 hours prior to the scheduled Casing Integrity Test. For wells in Eddy County, 575-361-2822; Lea County 575-393-3612.
- 5. All downhole production/injection equipment (tubing, rods, etc.) shall be removed from the casing if it is not isolated by a packer.
- 6. A bradenhead test must be conducted. If the test indicates a problem, a remedial plan and time frame for remediation shall be submitted within ninety (90) days of the test.
- 7. Submit a subsequent Sundry Notice (Form 3160-5) with the following information:
  - a. A well bore diagram with all perforations, CIBP's, and tops of cement on CIBP's.
  - b. A description of the temporary abandonment procedure.
  - c. A clear copy or the original of the pressure test chart.