Submit One Copy To Appropriate District Office	State of New		Form C-10	_
District I	Energy, Minerals and	Natural Resources	Revised November 3, 201 WELL API NO.	11
1625 N. French Dr., Hobbs, NM 88240 District II			30-025-33404	
811 S. First St., Artesia, NM 88210 District III	OIL CONSERVATION DIVISION 1220 South St. Francis Dr.		5. Indicate Type of Lease	
1000 Rio Brazos Rd., Aztec, NM 87410	Santa Fe, Ni		STATE FEE	
<u>District IV</u> 1220 S. St. Francis Dr., Santa Fe, NM	2 11110 1 2, 1 1		6. State Oil & Gas Lease No.	
87505	ES AND REPORTS ON WE	7110	7. Lagge Name on Unit Agreement Name	
(DO NOT USE THIS FORM FOR PROPOSAL DIFFERENT RESERVOIR. USE "APPLICAT	LS TO DRILL OR TO DEEPEN C	OR PLUG BACK TO A	7. Lease Name or Unit Agreement Name WEST DOLLARHIDE DRINKARD Unit 8. Well Number	
PROPOSALS.) 1. Type of Well: Oil Well Gas Well Other INJECTION			8. Well Number	
1. Type of Well: Oil Well Gazarta. 2. Name of Operator	is well \(\sum \) Other INJECT.	ION	9. OGRID Number	
CHEVRON USA INC			4323	
3. Address of Operator			10. Pool name or Wildcat	
6301 Deauville Blvd., Midland, TX 79706			DOLLARHIDE; Tubb-Drinkard	
4. Well Location:				
Unit Letter_P_:_10_feet from				
	4-S Range 38-E NMPM)	_
	11. Elevation <i>(Show whether</i> 3,133' GL	r DR, RKB, RT, GR, etc.,		
12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data				
NOTICE OF INTE	ENTION TO:		SEQUENT REPORT OF:	
<u>—</u>	PLUG AND ABANDON 🔲	REMEDIAL WOR	_] '
	CHANGE PLANS	COMMENCE DR		
PULL OR ALTER CASING	MULTIPLE COMPL	CASING/CEMEN	T JOB 📙	
OTHER:			eady for OCD inspection after P&A	
All pits have been remediated in co				
Rat hole and cellar have been filled				
☐ A steel marker at least 4" in diame	ter and at least 4 above gro	ound level has been set if	i concrete. It snows the	
			JARTER/QUARTER LOCATION OR	
UNIT LETTER, SECTION, TOWNSHIP, AND RANGE. All INFORMATION HAS BEEN WELDED OR				
PERMANENTLY STAMPED ON THE MARKER'S SURFACE.				
	early as possible to original	ground contour and has	been cleared of all junk, trash, flow lines and	d
other production equipment.	. 1 1	C . 1 1		
Anchors, dead men, tie downs and risers have been cut off at least two feet below ground level. If this is a one-well lease or last remaining well on lease, the battery and pit location(s) have been remediated in compliance with				
OCD rules and the terms of the Operator's pit permit and closure plan. All flow lines, production equipment and junk have been removed				
from lease and well location.	1 1 1	,1	1 1 3	
	have been removed. Portab	ole bases have been remo	oved. (Poured onsite concrete bases do not ha	ave
to be removed.)	have been addressed as ner	OCD rules		
All other environmental concerns have been addressed as per OCD rules. Pipelines and flow lines have been abandoned in accordance with 19.15.35.10 NMAC. All fluids have been removed from non-				
retrieved flow lines and pipelines.				
		lectrical service poles an	d lines have been removed from lease and w	ell
location, except for utility's distribution	infrastructure.			
When all work has been completed, retr			•	
			Project ManagerDATE10.16.20	
TYPE OR PRINT NAMEKatherine For State Use Only	Papageorge_E-MAIL: _Ka	atherine.Papageorge@ch	nevron.com PHONE:832-854-5291	-
	Y	_		
APPROVED BY: Xuy 3	TITL TITL	E Compliance Office	DATE 10/27/20	_