Submit One Copy To Appropriate District Office	State of New Me		Form C-103 Revised November 3, 201	
<u>District I</u> 1625 N. French Dr., Hobbs, NM 88240 <u>District II</u>	Energy, Minerals and Natu		WELL API NO. 30-025-33413	
811 S. First St., Artesia, NM 88210 <u>District III</u> 1000 Rio Brazos Rd., Aztec, NM 87410	OIL CONSERVATION DIVISION 1220 South St. Francis Dr.		5. Indicate Type of Lease STATE FEE	
<u>District IV</u> 1220 S. St. Francis Dr., Santa Fe, NM	Santa Fe, NM 87505		6. State Oil & Gas Lease No.	
87505 SUNDRY NOTICES (DO NOT USE THIS FORM FOR PROPOSALS)	S AND REPORTS ON WELLS		7. Lease Name or Unit Agreement Name	
DIFFERENT RESERVOIR. USE "APPLICATI PROPOSALS.)			WEST DOLLARHIDE DRINKARD Unit 8. Well Number	
1. Type of Well: Oil Well Gas 2. Name of Operator	s Well Other INJECTION		9. OGRID Number	
CHEVRON USA INC		4323		
3. Address of Operator 6301 Deauville Blvd., Midland, TX 79706			10. Pool name or Wildcat DOLLARHIDE; Tubb-Drinkard	
4. Well Location:	en the COLITILLine and 1200 fo	at from the EAST line		
	m the <u>SOUTH</u> line and 1200_fe -S Range <u>38-E</u> NMPM	et from the <u>EAST</u> im County <u>LEA</u>	ie	
17	1. Elevation <i>(Show whether DR)</i> 163' GL	, RKB, RT, GR, etc.)		
12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data				
	NTION TO: LUG AND ABANDON ☐ HANGE PLANS ☐	SUBS REMEDIAL WORK COMMENCE DRIL	_	
PULL OR ALTER CASING M	ULTIPLE COMPL	CASING/CEMENT	JOB 🗆	
OTHER: All pits have been remediated in co	mpliance with OCD rules and t		ady for OCD inspection after P&A	
 ✓ All pits have been remediated in compliance with OCD rules and the terms of the Operator's pit permit and closure plan. ✓ Rat hole and cellar have been filled and leveled. Cathodic protection holes have been properly abandoned. ✓ A steel marker at least 4" in diameter and at least 4' above ground level has been set in concrete. It shows the 				
OPERATOR NAME, LEASE NAME, WELL NUMBER, API NUMBER, QUARTER/QUARTER LOCATION OR				
<u>UNIT LETTER, SECTION, TOWNSHIP, AND RANGE. All INFORMATION HAS BEEN WELDED OR PERMANENTLY STAMPED ON THE MARKER'S SURFACE.</u>				
☐ The location has been leveled as neother production equipment.	arly as possible to original grou	nd contour and has b	peen cleared of all junk, trash, flow lines and	
Anchors, dead men, tie downs and risers have been cut off at least two feet below ground level.				
If this is a one-well lease or last remaining well on lease, the battery and pit location(s) have been remediated in compliance with OCD rules and the terms of the Operator's pit permit and closure plan. All flow lines, production equipment and junk have been removed				
from lease and well location. All metal bolts and other materials have been removed. Portable bases have been removed. (Poured onsite concrete bases do not have				
to be removed.) All other environmental concerns have been addressed as per OCD rules.				
Pipelines and flow lines have been abandoned in accordance with 19.15.35.10 NMAC. All fluids have been removed from non-retrieved flow lines and pipelines.				
☐ If this is a one-well lease or last remaining well on lease: all electrical service poles and lines have been removed from lease and we location, except for utility's distribution infrastructure.				
When all work has been completed, retu	rn this form to the appropriate I	District office to sche	edule an inspection.	
SIGNATURE <u>Katherine Papageorge</u> TITLE Decommissioning Project Manager DATE 10.16.20				
•			evron.com PHONE:832-854-5291	
APPROVED BY: Yeng For	TITLE C	Compliance Office	er A DATE 10/27/20	