Form 3160-5 (June 2015)

UNITED STATES DEPARTMENT OF THE INTERIOR

FORM APPROVED
OMB NO. 1004-0137
Expires: January 31, 201

D D	FIDERILLOR LAND MARKA	CEMENIT	L.	151145. Surfactif 51, 2010	
SUNDRY NOTICES AND REPORTS ON WELLS				al No. 534C	
Do not use this form for proposals to drill or to re-enter an abandoned well. Use form 3160-3 (APD) for such proposals.			6. If Indian, A	Allottee or Tribe Name	
SUBMIT IN TRIPLICATE - Other instructions on page 2				CA/Agreement, Name and/or No.	
Type of Well	her		8. Well Name FEDERAL		
Name of Operator LEGACY RESERVES OPERA	MELANIE REYES egacyreserves.com	9. API Well N 30-025-0	√o. 7991-00-D1		
3a. Address 303 W WALL SUITE 1600 MIDLAND, TX 79702		3b. Phone No. (include area code) Ph: 432-221-6358	10. Field and D-K	10. Field and Pool or Exploratory Area D-K	
4. Location of Well (Footage, Sec., T		11. County or	11. County or Parish, State		
Sec 30 T20S R39E SWNW 19		LEA COL	LEA COUNTY, NM		
12. CHECK THE A	PPROPRIATE BOX(ES)	TO INDICATE NATURE O	F NOTICE, REPORT, O	R OTHER DATA	
TYPE OF SUBMISSION	TYPE OF ACTION				
☐ Notice of Intent	☐ Acidize	Deepen	☐ Production (Start/Resu	ime) Water Shut-Off	
	☐ Alter Casing	☐ Hydraulic Fracturing	☐ Reclamation	■ Well Integrity	
Subsequent Report	□ Casing Repair	■ New Construction	☐ Recomplete	☐ Other	
☐ Final Abandonment Notice	☐ Change Plans	Plug and Abandon	▼ Temporarily Abandon		
	☐ Convert to Injection	☐ Plug Back	■ Water Disposal		
If the proposal is to deepen directions Attach the Bond under which the wor following completion of the involved testing has been completed. Final Abdetermined that the site is ready for fi We are requesting the subject the oil industry is in. 9-17-20 Ran MIT, pressured us Katherine Jess. Chart is attact.	rk will be performed or provide to perations. If the operation respondonment Notices must be file final inspection. It well be placed in TA state up casing to 500#. BLM no	the Bond No. on file with BLM/BIA sults in a multiple completion or record only after all requirements, including the state of the currence of	. Required subsequent reports mpletion in a new interval, a Fing reclamation, have been content situation	must be filed within 30 days orm 3160-4 must be filed once	
11/6/202	20 - PM NMOCD		RECORD ON	LY	
· · · · · · · · · · · · · · · · · · ·				\(\) \(\) \(\)	
14. I hereby certify that the foregoing is Com Name (Printed/Typed) MELANIE	Electronic Submission #5 For LEGACY RES nmitted to AFMSS for proce	530901 verified by the BLM Well SERVES OPERATING LP, sent essing by PRISCILLA PEREZ or Title COMPI	to the Hobbs		
Namo(17 mice 19 pea) WELMINE	INLILO	THE COMPL	MINITUR COUNDINATOR		
Signature (Electronic S	Submission)	Date 09/21/20)20		
	THIS SPACE FO	R FEDERAL OR STATE (OFFICE USE		
Approved By JONATHON SHEPA	TitlePETROEL	UM ENGINEER	Date 10/30/202		
Conditions of approval, if any, are attached. Approval of this notice does not warrant or certify that the applicant holds legal or equitable title to those rights in the subject lease which would entitle the applicant to conduct operations thereon.		not warrant or			
Title 18 U.S.C. Section 1001 and Title 43	U.S.C. Section 1212 make it a	crime for any person knowingly and	willfully to make to any depart	ment or agency of the United	

States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.

Additional data for EC transaction #530901 that would not fit on the form

Wells/Facilities, continued

Agreement NMNM0634C NMNM0634C Lease NMNM0634C NMNM0634C Well/Fac Name, Number FEDERAL 12 FEDERAL 12 **API Number** 30-025-07991-00-D1 30-025-07991-00-D2 **Location**Sec 30 T20S R39E SWNW 1980FNL 660FWL
Sec 30 T20S R39E SWNW 1980FNL 660FWL

Revisions to Operator-Submitted EC Data for Sundry Notice #530901

Operator Submitted

BLM Revised (AFMSS)

Sundry Type:

TA SR

NMNM0634C Lease:

TA SR

NMNM0634C

Agreement:

Operator:

LEGACY RESERVES OPERATING LP 303 WEST WALL SUITE 1800 MIDLAND, TX 79701

Ph: 432-689-5200

Admin Contact:

MELANIE REYES

COMPLIANCE COORDINATOR E-Mail: mreyes@legacyreserves.com

Ph: 432-221-6358

Tech Contact:

MELANIE REYES COMPLIANCE COORDINATOR E-Mail: mreyes@legacyreserves.com

Ph: 432-221-6358

Ph: 432-221-6358

MELANIE REYES

MELANIE REYES COMPLIANCE COORDINATOR E-Mail: mreyes@legacyreserves.com

LEGACY RESERVES OPERATING LP

303 W WALL SUITE 1600 MIDLAND, TX 79702 Ph: 432-682-2516 Fx: 432.686. 8318

COMPLIANCE COORDINATOR E-Mail: mreyes@legacyreserves.com

Ph: 432-221-6358

Location:

State:

LEA COUNTY County:

Field/Pool:

D-K

LEA

D-K


Well/Facility:

FEDERAL 12

Sec 30 T20S R39E SWNW 1980FNL 660FWL

FEDERAL 12

Sec 30 T20S R39E SWNW 1980FNL 660FWL



BUREAU OF LAND MANAGEMENT

Carlsbad Field Office 620 East Greene Street Carlsbad, New Mexico 88220 575-234-5972

Conditions of Approval for Temporary Abandonment of Wells

Definition: A temporarily abandoned well is a completion that is not capable of production in paying quantities, but which may have future value. Pursuant to 43 CFR 3162.3-4 (c), no well may be temporarily abandoned for more than 30 days without the prior approval of the authorized officer.

- 1. TA status will be effective for a period of up to one year from the date of sundry approval and can be renewed annually thereafter per IM NM-2016-017.
- 2. A bridge plug (CIBP) must be installed 50 to 100 feet above any open perforations or open hole. The CIBP must be capped with either a minimum of 25 sacks of cement if placed with tubing or 35 feet of cement if placed with a bailer. The top of the cement must be verified by tagging.
- 3. The wellbore must be filled with corrosion inhibited fluid and pressure tested to 500 psi. The casing shall be capable of holding this pressure for at least 30 minutes. If the well does not pass the casing integrity test, then the operator shall, within 30 days, submit a procedure to either repair the casing or to plug and abandon the well.
- 4. Contact the appropriate BLM office at least 24 hours prior to the scheduled Casing Integrity Test. For wells in Eddy County, 575-361-2822; Lea County 575-393-3612.
- 5. All downhole production/injection equipment (tubing, rods, etc.) shall be removed from the casing if it is not isolated by a packer.
- 6. A bradenhead test must be conducted. If the test indicates a problem, a remedial plan and time frame for remediation shall be submitted within ninety (90) days of the test.
- 7. Submit a subsequent Sundry Notice (Form 3160-5) with the following information:
 - a. A well bore diagram with all perforations, CIBP's, and tops of cement on CIBP's.
 - b. A description of the temporary abandonment procedure.
 - c. A clear copy or the original of the pressure test chart.

Melanie Reyes

From:

Shepard, Jonathon W < jshepard@blm.gov>

Sent:

Tuesday, November 3, 2020 2:55 PM

To:

Melanie Reyes

Subject:

Re: [EXTERNAL] RE: Well FEDERAL 12

Sorry about that! The well is in TA status till 10/30/2021

Jonathon Shepard Petroleum Engineer Carlsbad Field Office Phone: 575-234-2237

From: Melanie Reyes <mreyes@legacyreserves.com>

Sent: Tuesday, November 3, 2020 1:37 PM
To: Shepard, Jonathon W <jshepard@blm.gov>
Subject: [EXTERNAL] RE: Well FEDERAL 12

This email has been received from outside of DOI - Use caution before clicking on links, opening attachments, or responding.

Hi Jonathon,

I couldn't find a TA expiration or "approved until" date for the subject well, API 30-025-07991, WIS ID #530901. Could you please provide the date for me?

Thanks, Melanie

----Original Message----

From: jshepard@blm.gov [mailto:jshepard@blm.gov]

Sent: Friday, October 30, 2020 3:35 PM

To: Melanie Reyes <mreyes@legacyreserves.com>

Subject: Well FEDERAL 12

The sundry for Temporary Abandonment you submitted has been approved by the BLM. Your original Electronic Commerce (EC) transmission was assigned ID 530901. Please be sure to open and save all attachments to this message, since they contain important information.