

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENTFORM APPROVED
OMB NO. 1004-0137
Expires: January 31, 2018**SUNDRY NOTICES AND REPORTS ON WELLS**
*Do not use this form for proposals to drill or to re-enter an abandoned well. Use form 3160-3 (APD) for such proposals.*5. Lease Serial No.
NMNM077002

6. If Indian, Allottee or Tribe Name

7. If Unit or CA/Agreement, Name and/or No.

SUBMIT IN TRIPLICATE - Other instructions on page 28. Well Name and No.
NELLIS FEDERAL 39. API Well No.
30-025-26091-00-S110. Field and Pool or Exploratory Area
BUFFALO VALLEY11. County or Parish, State
LEA COUNTY, NM**12. CHECK THE APPROPRIATE BOX(ES) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA**

TYPE OF SUBMISSION	TYPE OF ACTION				
☐ Notice of Intent	☐ Acidize	☐ Deepen	☐ Production (Start/Resume)	☐ Water Shut-Off	
☒ Subsequent Report	☐ Alter Casing	☐ Hydraulic Fracturing	☐ Reclamation	☐ Well Integrity	
☐ Final Abandonment Notice	☐ Casing Repair	☐ New Construction	☐ Recomplete	☐ Other	
	☐ Change Plans	☐ Plug and Abandon	☒ Temporarily Abandon		
	☐ Convert to Injection	☐ Plug Back	☐ Water Disposal		

13. Describe Proposed or Completed Operation: Clearly state all pertinent details, including estimated starting date of any proposed work and approximate duration thereof. If the proposal is to deepen directionally or recompleat horizontally, give subsurface locations and measured and true vertical depths of all pertinent markers and zones. Attach the Bond under which the work will be performed or provide the Bond No. on file with BLM/BIA. Required subsequent reports must be filed within 30 days following completion of the involved operations. If the operation results in a multiple completion or recompleat in a new interval, a Form 3160-4 must be filed once testing has been completed. Final Abandonment Notices must be filed only after all requirements, including reclamation, have been completed and the operator has determined that the site is ready for final inspection.

We are requesting the subject well be placed in TA status for one year due to the current situation the oil industry is in.

9-17-20 Ran MIT, pressured casing to 520#. BLM notified, chart witnessed by BLM representative, Katherine Jess. Chart is attached.

Received 11/6/20

11/6/2020 - PM NMOC

FOR RECORD ONLY

K 7

14. I hereby certify that the foregoing is true and correct.

Electronic Submission #530910 verified by the BLM Well Information System
For LEGACY RESERVES OPERATING LP, sent to the Hobbs
Committed to AFMSS for processing by PRISCILLA PEREZ on 09/22/2020 (20PP2968SE)

Name (Printed/Typed) MELANIE REYES

Title COMPLIANCE COORDINATOR

Signature (Electronic Submission)

Date 09/21/2020

THIS SPACE FOR FEDERAL OR STATE OFFICE USE

Approved By JONATHON SHEPARD

Title PETROELUM ENGINEER

Date 10/30/2020

Conditions of approval, if any, are attached. Approval of this notice does not warrant or certify that the applicant holds legal or equitable title to those rights in the subject lease which would entitle the applicant to conduct operations thereon.

Office Hobbs


Title 18 U.S.C. Section 1001 and Title 43 U.S.C. Section 1212, make it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.

(Instructions on page 2)

**** BLM REVISED ** BLM REVISED ** BLM REVISED ** BLM REVISED ** BLM REVISED ****

Revisions to Operator-Submitted EC Data for Sundry Notice #530910

	Operator Submitted	BLM Revised (AFMSS)
Sundry Type:	TA SR	TA SR
Lease:	NMNM077002	NMNM077002
Agreement:		
Operator:	LEGACY RESERVES OPERATING LP 303 WEST WALL SUITE 1800 MIDLAND, TX 79701 Ph: 432-689-5200	LEGACY RESERVES OPERATING LP 303 W WALL SUITE 1600 MIDLAND, TX 79702 Ph: 432-682-2516 Fx: 432.686. 8318
Admin Contact:	MELANIE REYES COMPLIANCE COORDINATOR E-Mail: mreyes@legacyreserves.com Ph: 432-221-6358	MELANIE REYES COMPLIANCE COORDINATOR E-Mail: mreyes@legacyreserves.com Ph: 432-221-6358
Tech Contact:	MELANIE REYES COMPLIANCE COORDINATOR E-Mail: mreyes@legacyreserves.com Ph: 432-221-6358	MELANIE REYES COMPLIANCE COORDINATOR E-Mail: mreyes@legacyreserves.com Ph: 432-221-6358
Location:		
State:	NM	NM
County:	LEA COUNTY	LEA
Field/Pool:	BUFFALO VALLEY	BUFFALO VALLEY
Well/Facility:	NELLIS FEDERAL 3 Sec 6 T19S R33E SENW 1980FNL 1980FWL	NELLIS FEDERAL 3 Sec 6 T19S R33E SENW 1980FNL 1980FWL



BUREAU OF LAND MANAGEMENT

Carlsbad Field Office
620 East Greene Street
Carlsbad, New Mexico 88220
575-234-5972

Conditions of Approval for Temporary Abandonment of Wells

Definition: A temporarily abandoned well is a completion that is not capable of production in paying quantities, but which may have future value. Pursuant to 43 CFR 3162.3-4 (c), no well may be temporarily abandoned for more than 30 days without the prior approval of the authorized officer.

1. TA status will be effective for a period of up to one year from the date of sundry approval and can be renewed annually thereafter per IM NM-2016-017.
2. A bridge plug (CIBP) must be installed 50 to 100 feet above any open perforations or open hole. The CIBP must be capped with either a minimum of 25 sacks of cement if placed with tubing or 35 feet of cement if placed with a bailer. The top of the cement must be verified by tagging.
3. The wellbore must be filled with corrosion inhibited fluid and pressure tested to 500 psi. The casing shall be capable of holding this pressure for at least 30 minutes. If the well does not pass the casing integrity test, then the operator shall, within 30 days, submit a procedure to either repair the casing or to plug and abandon the well.
4. Contact the appropriate BLM office at least 24 hours prior to the scheduled Casing Integrity Test. For wells in Eddy County, 575-361-2822; Lea County 575-393-3612.
5. All downhole production/injection equipment (tubing, rods, etc.) shall be removed from the casing if it is not isolated by a packer.
6. A bradenhead test must be conducted. If the test indicates a problem, a remedial plan and time frame for remediation shall be submitted within ninety (90) days of the test.
7. Submit a subsequent Sundry Notice (Form 3160-5) with the following information:
 - a. A well bore diagram with all perforations, CIBP's, and tops of cement on CIBP's.
 - b. A description of the temporary abandonment procedure.
 - c. A clear copy or the original of the pressure test chart.

Melanie Reyes

From: jshepard@blm.gov
Sent: Friday, October 30, 2020 4:05 PM
To: Melanie Reyes
Subject: Well NELLIS FEDERAL 3
Attachments: TA COA.docx; EC530910.pdf

The sundry for Temporary Abandonment you submitted has been approved by the BLM. Your original Electronic Commerce (EC) transmission was assigned ID 530910. Please be sure to open and save all attachments to this message, since they contain important information.

TA till 10/30/2021