Form 3160-5 (June 2015)

# **UNITED STATES** DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT

FORM APPROVED
OMB NO. 1004-0137
Expires: January 31, 2018

SUNDRY NOTICES AND REPORTS ON WELLS Do not use this form for proposals to drill or to re-enter an abandoned well. Use form 3160-3 (APD) for such proposals.						NMLC058514      If Indian, Allottee or Tribe Name		
SUBMIT IN TRIPLICATE - Other instructions on page 2						7. If Unit or CA/Agreement, Name and/or No.		
Type of Well     ☐ Gas Well ☐ Other						Well Name and No.     MultipleSee Attached		
Name of Operator Contact: MELANIE REYES LEGACY RESERVES OPERATING LPE-Mail: mreyes@legacyreserves.com						9. API Well No. MultipleSee Attached 30-025-30696		
3a. Address 303 W WALL MIDLAND, TX		3b. Phone No. (include area code) Ph: 432-221-6358			10. Field and Pool or Exploratory Area PEARSALL-QUEEN			
4. Location of Well (Footage, Sec., T., R., M., or Survey Description)				11. County or Parish, State				
MultipleSee /	Attached				LEA COUNTY, NM			
12. C	HECK THE A	PPROPRIATE BOX(ES)	TO INDICA	TE NATURE O	F NOTICE,	REPORT, OR OTH	ER DATA	
TYPE OF SUE	TYPE OF SUBMISSION TY				ACTION			
☐ Notice of Intent		☐ Acidize	☐ Dee	☐ Deepen		ion (Start/Resume)	☐ Water Shut-Off	
_		☐ Alter Casing	☐ Hyd	Iraulic Fracturing	□ Reclam	ation	■ Well Integrity	
Subsequent Report		□ Casing Repair	☐ Nev	v Construction	□ Recomplete		☐ Other	
☐ Final Abandonment Notice		☐ Change Plans	☐ Plug	g and Abandon	□ Tempor	arily Abandon		
		☐ Convert to Injection	Plug	g Back	ck Water Disposal			
Attach the Bond u following complet testing has been of determined that the We are reques the oil industry	nder which the wor ion of the involved ompleted. Final Ab e site is ready for fi ting the subject is in.	ally or recomplete horizontally, it will be performed or provide operations. If the operation repandonment Notices must be fil inal inspection.  well be placed in TA statements of the pl	the Bond No. or sults in a multiplied only after all tus for a year	n file with BLM/BIA e completion or reco requirements, include due to the currer	. Required sul mpletion in a r ing reclamation nt situation	osequent reports must be to new interval, a Form 3160	filed within 30 days 0-4 must be filed once	
			Received 1	1/6/20				
11/6/2020 - PM NMOCD FOR R				RECORD O	NLY	XX		
14. I hereby certify the Name (Printed/Type)	Com	# Electronic Submission For LEGACY RE: nmitted to AFMSS for proc	SERVES OPE	RATING LP, sent to SCILLA PEREZ or	to the Hobbs 1 09/21/2020			
Signature	gnature (Electronic Submission) Date 09/21/2020							
	(======================================	THIS SPACE FO	OR FEDERA			SE		
				<u> </u>				
Approved By_JONATHON SHEPARD				TitlePETROELUM ENGINEER Date 10/30/20				
Conditions of approval, if any, are attached. Approval of this notice does not warrant or certify that the applicant holds legal or equitable title to those rights in the subject lease which would entitle the applicant to conduct operations thereon.				Office Hobbs				
itle 1911 C Caction	1001 and Title 42 1	II C Section 1212 make it a	orima for one no	rean knowingly and	willfully to me	lea to anu donartment	sangu of the United	

Title 18 U.S.C. Section 1001 and Title 43 U.S.C. Section 1212, make it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.

#### Additional data for EC transaction #530751 that would not fit on the form

Wells/Facilities, continued

Agreement NMLC058514 NMLC058514 Lease NMLC058514 NMLC058514 Well/Fac Name, Number PEARSALL BX 04 PEARSALL BX 04 **API Number** 30-025-30696-00-C1 30-025-30696-00-C2

**Location** Sec 34 T17S R32E NENE 330FNL 330FEL Sec 34 T17S R32E NENE 330FNL 330FEL

#### Revisions to Operator-Submitted EC Data for Sundry Notice #530751

**Operator Submitted** 

**BLM Revised (AFMSS)** 

Sundry Type:

TA SR

Lease:

NMLC058514

NMLC058514

TA SR

Agreement:

Operator:

LEGACY RESERVES OPERATING LP 303 WEST WALL SUITE 1800 MIDLAND, TX 79701 Ph: 432-689-5200

Admin Contact:

**MELANIE REYES** 

COMPLIANCE COORDINATOR E-Mail: mreyes@legacyreserves.com

Ph: 432-221-6358

Tech Contact:

MELANIE REYES COMPLIANCE COORDINATOR E-Mail: mreyes@legacyreserves.com

Ph: 432-221-6358

Location:

State:

NM LEA COUNTY County:

Field/Pool:

PEARSALL-QUEEN

Well/Facility:

PEARSALL BX 4

Sec 34 T17S R32E NENE 330FNL 330FEL

LEGACY RESERVES OPERATING LP 303 W WALL SUITE 1600 MIDLAND, TX 79702 Ph: 432-682-2516 Fx: 432.686.8318

**MELANIE REYES** 

COMPLIANCE COORDINATOR E-Mail: mreyes@legacyreserves.com

Ph: 432-221-6358

**MELANIE REYES** 

COMPLIANCE COORDINATOR E-Mail: mreyes@legacyreserves.com

Ph: 432-221-6358

NM LEA


PEARSALL-QUEEN

PEARSALL BX 04

Sec 34 T17S R32E NENE 330FNL 330FEL

PEARSALL BX 04

Sec 34 T17S R32E NENE 330FNL 330FEL



#### **BUREAU OF LAND MANAGEMENT**

Carlsbad Field Office 620 East Greene Street Carlsbad, New Mexico 88220 575-234-5972

### **Conditions of Approval for Temporary Abandonment of Wells**

**Definition:** A temporarily abandoned well is a completion that is not capable of production in paying quantities, but which may have future value. Pursuant to 43 CFR 3162.3-4 (c), no well may be temporarily abandoned for more than 30 days without the prior approval of the authorized officer.

- 1. TA status will be effective for a period of up to one year from the date of sundry approval and can be renewed annually thereafter per IM NM-2016-017.
- 2. A bridge plug (CIBP) must be installed 50 to 100 feet above any open perforations or open hole. The CIBP must be capped with either a minimum of 25 sacks of cement if placed with tubing or 35 feet of cement if placed with a bailer. The top of the cement must be verified by tagging.
- 3. The wellbore must be filled with corrosion inhibited fluid and pressure tested to 500 psi. The casing shall be capable of holding this pressure for at least 30 minutes. If the well does not pass the casing integrity test, then the operator shall, within 30 days, submit a procedure to either repair the casing or to plug and abandon the well.
- 4. Contact the appropriate BLM office at least 24 hours prior to the scheduled Casing Integrity Test. For wells in Eddy County, 575-361-2822; Lea County 575-393-3612.
- 5. All downhole production/injection equipment (tubing, rods, etc.) shall be removed from the casing if it is not isolated by a packer.
- 6. A bradenhead test must be conducted. If the test indicates a problem, a remedial plan and time frame for remediation shall be submitted within ninety (90) days of the test.
- 7. Submit a subsequent Sundry Notice (Form 3160-5) with the following information:
  - a. A well bore diagram with all perforations, CIBP's, and tops of cement on CIBP's.
  - b. A description of the temporary abandonment procedure.
  - c. A clear copy or the original of the pressure test chart.

## **Melanie Reyes**

From:

jshepard@blm.gov

Sent:

Friday, October 30, 2020 4:20 PM

To:

Melanie Reyes

Subject:

Well PEARSALL BX 04 and others

**Attachments:** 

TA COA.docx; EC530751.pdf

The sundry for Temporary Abandonment you submitted has been approved by the BLM. Your original Electronic Commerce (EC) transmission was assigned ID 530751. Please be sure to open and save all attachments to this message, since they contain important information.

TA till 10/30/2021