Submit 1 Copy To Appropriate District	State of Nev	v Mexico		F	orm C-103	
Office <u>District I</u> – (575) 393-6161	Energy, Minerals and	Natural Resources			August 1, 2011	
1625 N French Dr., Hobbs, NM 88240			WELL API	NO.		
District II - (575) 748-1283	OIL CONSERVAT	TON DIVISION		30-005-20814		
811 S. First St., Artesia, NM 88210 District III – (505) 334-6178	, 1220 South St.			Type of Lease	- 11	
$\frac{DISULET III}{1000 Rio Brazos Rd., Aztec, NM.87418, A 201$	1220 South St.			FEE FEE	L ra	
1000 Rio Brazos Rd., Aztec, NM, 87419 4 20 District IV - (505) 476-3460 AUG 2 4 20	Santa Fe, N	M 87505	6. State Oil	& Gas Lease No.		
1220 S. St. Francis Dr., Santa Fe, NM 87505				NM-15016		
	AND REPORTS ON W	ELLS	7. Lease Na	me or Unit Agreer	nent Name	
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A				WATTAM FEDERAL		
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH				mber	/	
PROPOSALS.) 1. Type of Well: Oil Well Gas	Well 🔲 Other SWD	11		#6	/	
2. Name of Operator		/	9. OGRID I	Number		
DORAL ENERGY CORP.				261198		
3. Address of Operator			10. Pool nat	me or Wildcat		
22610 US HWY NORTH, SUITE 281	SAN ANTONIO, TX. 752	285	SV	WD, SAN ANDRE	s /	
4. Well Location				East	. /	
Unit Letter <u>A</u> : <u>64</u>	<u>3</u> feet from the]	NORTH_line and7	82 feet from	m the <u>SOUTH</u>	line	
Section 7	Township 7S	Range 31E	NMPM C	CHAVES County		
	. Elevation (Show whethe)			

12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:			SUBSEQUENT REPORT OF:		
PERFORM REMEDIAL WORK		PLUG AND ABANDON		REMEDIAL WORK	ALTERING CASING
TEMPORARILY ABANDON		CHANGE PLANS		COMMENCE DRILLING OPNS.	MOCD ABLESIA
PULL OR ALTER CASING		MULTIPLE COMPL		CASING/CEMENT JOB	AISTIN
DOWNHOLE COMMINGLE					NUS 22 2011
				🖾 SWD	1100 00 011
OTHER:					HEVEN -

13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates including estimated date of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.

7/15/11 Spotted TWS unit at well.

7/18/11 RU TWS unit, rig up BOP from D &L meter Lovington NM. Pull 20pts, Tbg weighting lite. Had no packer. Pulled 2929' 93 joints, 2 7/8 P.C. Tbg, found body break, shut down . Called TWS to get overshot; called Double "R" Pipe found 40 joints of 2 7/8 P.C. pipe new collars new coating white and yellow band. Shut down for the night.

7/19/11 Pipe on location unloaded 40 joints – 1286.25', from Double "R" Pipe, got overshot from TWS start in hole with overshot & pipe to fish Pipe and packer. Run in 15 extra joints tag up released packer started out. Landed packer AD-1 had 18 bad joints of pipe, send packer to Parker Packers Hobbs, NM. Replaced old packer with new packer.

7/25/11 Pick up redressed AD-1 Packer from Parker Packer Hobbs, NM - start in hole, replaced 20 joints 2 7/8 pipe, land Packer & pipe set packer, pull 15 pts in tension load, Press to 530# held ok, released Packer, wait 30 min. start pumping water and packer fluid, set packer after 30 BBLS, set packer pump 20 BBLS more, press up to 555#, held for 30 minutes. Packer set at 3559'; 83' above top perforation. Rig down move to Tom 36-1. Sent 20 joints 2 7/8 back to Double "R", picked up by Double "R" truck.

Spud Date:

Rig Release Date:

iched Chart

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Larry Risley		DATE_ <u>8/11/11</u>
Type or print name Larry Risley	_ E-mail address:larryr@xbres.com	PHONE: <u>210-226-6700</u>
For State Use Only		
APPROVED BY:		DATE
Conditions of Approval (if any): Ele 8-24	-2011	{

