## HOBBS OCD

Conditions of Approval (if any):

110000 000	
Submit One Copy To Appropriate District Office State of New Mexico	Form C-103
District I SEP & Entergy, Minerals and Natural Resources 1625 N French Dr., Hobbs, NM 88240	Revised August 1, 2011 WELL API NO.
District II 811 S. First St., Grand Ave., Artesia, NECEIVE IL CONSERVATION DIVISION 1220 South St. Francis Dr.	30-025-31425
88210 1220 South St. Francis Dr.	5. Indicate Type of Lease STATE X FEE
District III 1000 Rio Brazos Rd, Aztec, NM 87410 Santa Fe, NM 87505	6. State Oil & Gas Lease No.
District IV	0. 0 0 0 0 0
1220 S. St. Francis Dr , Santa Fe, NM 87505	
SUNDRY NOTICES AND REPORTS ON WELLS	7. Lease Name or Unit Agreement Name
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH	Eunice Monument South Unit  8. Well Number 625
PROPOSALS.)  1. Type of Well: X Oil Well  Gas Well  Other	8. Well Number 623
1. Type of Well: X Oil Well Gas Well Other  2. Name of Operator	9. OGRID Number
XTO Energy, Inc.	005380
3. Address of Operator	10. Pool name or Wildcat
200 North Loraine, Ste. 800, Midland, Texas 79701	Eunice Monument; Grayburg-San Andres
4. Well Location	
Unit Letter L: 2630 feet from the South line and 10 feet from the West line	
Section 4 Township 21 S Range 36 E NMPM County Lea  11. Elevation (Show whether DR, RKB, RT, GR, e.	
The Elevation (Show Whether Dr., 1915), 1915, 19	
12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data	
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:	
PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WO	
<u> </u>	RILLING OPNS. P AND A
PULL OR ALTER CASING ☐ MULTIPLE COMPL ☐ CASING/CEME	NT JOB
OTHER:	ready for OCD inspection after P&A
N/A All pits have been remediated in compliance with OCD rules and the terms of the Operator's pit permit and closure plan.	
N/A Rat hole and cellar have been filled and leveled. Cathodic protection holes have be	een properly abandoned.
X A steel marker at least 4" in diameter and at least 4' above ground level has been set in concrete. It shows the	
OPERATOR NAME, LEASE NAME, WELL NUMBER, API NUMBER, QUARTER/QUARTER LOCATION OR	
UNIT LETTER, SECTION, TOWNSHIP, AND RANGE. All INFORMATION HAS BEEN WELDED OR	
PERMANENTLY STAMPED ON THE MARKER'S SURFACE.	
X The location has been leveled as nearly as possible to original ground contour and has been cleared of all junk, trash, flow lines and	
other production equipment.	
X Anchors, dead men, tie downs and risers have been cut off at least two feet below ground level.  N/A If this is a one-well lease or last remaining well on lease, the battery and pit location(s) have been remediated in compliance with	
OCD rules and the terms of the Operator's pit permit and closure plan. All flow lines, production equipment and junk have been removed	
from lease and well location.	
X All metal bolts and other materials have been removed. Portable bases have been removed. (Poured onsite concrete bases do not have	
to be removed.)  X All other environmental concerns have been addressed as per OCD rules.	
X Pipelines and flow lines have been abandoned in accordance with 19.15.35.10 NMAC. All fluids have been removed from non-	
retrieved flow lines and pipelines.	
When all work has been completed, return this form to the appropriate District office to schedule an inspection.	
which all work has been completed, return this form to the appropriate District office to schedule an inspection.	
SIGNATURE SIGNATURE TITLE: Maintenance Foreman DATE: 09/02/2011	
TYPE OR PRINT NAME: Gene Hudson E-MAIL: richard_hudson@xtoenergy.com PHONE: 575-441-1634	
For State Use Only	Officer DATE 09/06/11
ADDROVED BY: Was to by take TITLE OWN FALCE	(Hicar DATE 09/06/11