

Submit 3 Copies To Appropriate District  
Office  
District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
1301 W. Grand Ave., Artesia, NM 88210  
District III  
1000 Rio Brazos Rd., Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM  
87505

State of New Mexico  
Energy, Minerals and Natural Resources

Form C-103  
June 19, 2008

HOBBS OGD  
OCT 24 2011

OIL CONSERVATION DIVISION  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

WELL API NO. 30-025-03673
5. Indicate Type of Lease STATE <input type="checkbox"/> FEE <input checked="" type="checkbox"/>
6. State Oil & Gas Lease No.
7. Lease Name or Unit Agreement Name MAYME W. GRAHAM
8. Well Number #1
9. OGRID Number 009569
10. Pool name or Wildcat devonion SWD
11. Elevation (Show whether DR, RKB, RT, GR, etc.) 3909 DF

SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)	
1. Type of Well: Oil Well <input checked="" type="checkbox"/> Gas Well <input type="checkbox"/> Other SWD <input type="checkbox"/>	
2. Name of Operator H&M Disposal	
3. Address of Operator P.O. Box 1544, Lovington, New Mexico 88260	
4. Well Location Unit Letter <u>N</u> : <u>620</u> feet from the <u>South</u> line and <u>1980</u> feet from the <u>West</u> line Section <u>9</u> Township <u>15 S</u> Range <u>36 E</u> NMPM County <u>Lea</u>	
11. Elevation (Show whether DR, RKB, RT, GR, etc.) 3909 DF	

12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐  
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐  
PULL OR ALTER CASING ☐ MULTIPLE COMPL ☐  
DOWNHOLE COMMINGLE ☐

OTHER: ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☒ ALTERING CASING ☐  
COMMENCE DRILLING OPNS. ☐ P AND A ☐  
CASING/CEMENT JOB ☐

OTHER: ☐

13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.

On 13 October a well service unit was moved on to the Mayme Graham #1 SWD to look for a tubing leak. The leak was located in the first sub below the tubing hanger. The leaking 8' sub was replaced with a new plastic coated 8' sub without opening the packer bypass or unseating the tool. The well was flanged back up the well service unit and other rental equipment released.

The packer is still set at 13,568.75', thirty-four feet above the end of the casing and the open hole disposal interval. There are: 293 jts of 2 7/8 lined pipe, 136 jts of 2 3/8 lined pipe a fiberglass lined change-over, a coated single grip model "R" packer and two subs installed in the well. On 20 Oct. an MIT test was conducted and the chart given to the OCD observer.

Spud Date:

Rig Release Date:

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE D M Harrod TITLE Manager DATE 24 Oct 2011

Type or print name D. M. Harrod E-mail address: d\_harrod@msn.com PHONE: 575-396-6862  
For State Use Only

APPROVED BY: [Signature] TITLE STATE MANAGER DATE 10-24-2011  
Conditions of Approval (if any)

OCT 24 2011

30-035-03673

GRAPHIC CONTROLS CORPORATION  
BUFFALO, NEW YORK

H+M disposal

Crane  
Graham #1-Swd.  
10/20/2011

BR 2221

Reviewed test  
after repairs  
performed by  
Chief Sweeney  
OCD 1 - FCD 1  
OK  
10/20/11

calibrated  
10/20/11

ASA 13568  
OH

#

Dm Hanod

