Submit I Copy To Appropriate District Office District I 1625 N. French Dr., Hobbs, NM 88240 District II 1301 W. Grand Ave., Artesia, NM 88210 District III 1300 Rio Brazos Rd., Aztec, NM 87410 District IV 1220 S. St. Francis Dr., Santa Fe, NM 87505  SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.) 1. Type of Well: Oil Well  Gas Well Other Injector 2. Name of Operator Celero Energy II, LP  3. Address of Operator 400 W. Illinois, Ste. 1601 Midland, TX 79701  4. Well Location	Form C-103 October 13, 2009  WELL API NO. 30-005-00906  5. Indicate Type of Lease STATE FEE X  6. State Oil & Gas Lease No.  7. Lease Name or Unit Agreement Name Rock Queen Unit  8. Well Number 102  9. OGRID Number 247128  10. Pool name or Wildcat Caprock; Queen
Unit Letter G: 1980 feet from the N line and 1980 feet from the E line	
Section 34 Township 13S Range 31E	NMPM CountyChaves
11. Elevation (Show whether DR, RKB, RT, GR, etc.)	
12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data	
NOTICE OF INTENTION TO:  PERFORM REMEDIAL WORK   PLUG AND ABANDON   REMEDIAL WORK  TEMPORARILY ABANDON   CHANGE PLANS   COMMENCE DRIL  PULL OR ALTER CASING   MULTIPLE COMPL   CASING/CEMENT  DOWNHOLE COMMINGLE	LING OPNS. P AND A
OTHER: OTHER: Convert to  13. Describe proposed or completed operations. (Clearly state all pertinent details, and	o injection  give pertinent dates, including estimated date
of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.	
6/9 - 6/15/11 TOH w/production equipment. TIH w/ 3 ¼" bit, 4- 3 ½" DC's & 93 jts 2 3/8" WS to 3055'. Drill from 3055'-3075'. TIH w/ 4 ½" csg scraper to 3028'. TOH w/ scraper. TIH w/ 4 ½" AS1-X pkr & 92 jts of 2 3/8" WS. Set pkr @ 2988'. Tried to test but had leak. Hole loaded w/ 22 bbls. PU 4 ½" RBP & pkr. TIH w/ 2 3/8" WS & set RBP @ 496'. Test RBP to 500#, held okay. Move pkr up & test csg from 135' up, okay. Moved pkr down to 146' & test. Had leak. Hole between 135' & 144'. Retrieve RBP & TOH. Run CIL & CBL. Loggers TD 3030'. TOC @ 2320'. TIH w/ 2 3/8" WS & set RBP @ 2950'. Test RBP to 500#, test okay. Move pkr up to 496' & test csg to 500#. Tested okay. NDBOP & WH. RIH w/ 80 grain shot to 167' (6") above collar. Fired shot & retrieving sub broke loose. Re-tightened sub & ran back in hole w/ 2nd shot to 167' (6") above collar. Fired shot & backed off. Pulled 5 jts, total 163.60'. Ran 4 jts 4 ½" 11.60# J-55 LTC. Total pipe 180.02'. Tag & screw into existing csg. NUWH & set 20K on slips. Cut off & weld on bell nipple. NUBOP & test csg to 500#. Tested okay. TIH w/ 93 jts WS & retrieve RBP. PU ASZ-X inj pkr & run 92 jts 2 3/8" 4.7# J55 IPC w/RC. Pump 50 bbls pkr fluid. Set pkr @ 2978'. Test csg to 500# for 30 mins. Tested ok. ND BOP & NU WH. RD. Installed AL-BR valve. Well SI.	
8/11/11 - Ran MIT. Tested for 30 mins from 520 # to 470#. Orignal chart is attached. Vapproval. Will submit WBS & injection order once approved by OCD Santa Fe.	Vell shut in pending injectio permit
Spud Date: Rig Release Date:	
	WFX-892
I hereby certify that the information above is true and complete to the best of my knowledge and belief.	
SIGNATURE LIA TITLE Regulatory Analyst	DATE 08/16/2011
Type or print name Lisa Hunt E-mail address: <a href="mailto:lhunt@celeroenerge">lhunt@celeroenerge</a> For State Use Only	gy.com PHONE: (432)686-1883
APPROVED BY:	
NOV 1.5. 201	

