Submit 3 Copies To Appropriate District Office	State of New Mexico	Form C-103
District, I	Energy, Minerals and Natural Resources	May 27, 2004
1625 N. French Dr., Hobbs, NM 88240 District II		WELL API NO. 30-025-29682
1301 W Grand Ave., Artesia, NM 88210	OIL CONSERVATION DIVISION	5. Indicate Type of Lease
District III	1220 South St. Francis Dr.	STATE X FEE \square
1000 Rio Brazos Rd., Aztec, NM 87410 District IV	Santa Fe, NM 87505	6. State Oil & Gas Lease No.
1220 S. St. Francis Dr., Santa Fe, NM		
87505	ES AND REPORTS ON WELLS	7. Lease Name or Unit Agreement Name
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A		Eunice Monument South Unit
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)		
1. Type of Well: Oil Well X Gas Well Other		8. Well Number 198
2. Name of Operator		9. OGRID Number
XTO Energy Inc.		005380
3. Address of Operator		10. Pool name or Wildcat
200 N. Loraine, Suite 800, Midland	, Tx 79701	Eunice Monument Grayburg San Andres
4. Well Location		
Unit Letter G: 179	01_feet from theNorth_ line and1980	_feet from theEastline
Section 5 Township 21-S Range 36-E NMPM Lea County New Mexico		
11. Elevation (Show whether DR, RKB, RT, GR, etc.)		
3559.5'		
Pit or Below-grade Tank Application or		
Pit typesteel_Depth to Groundwater		
Pit Liner Thickness: mil		onstruction Material
12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data		
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:		
PERFORM REMEDIAL WORK 🔲 PLUG AND ABANDON 🔲 🛛 REMEDIAL WORK 👘 🖓 🖓 🖓 🕅 REMEDIAL WORK		
TEMPORARILY ABANDON		
PULL OR ALTER CASING	MULTIPLE COMPL	IT JOB
OTHER:		
13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date		
of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.		
-	ervices PU (Richard). RU cable spoolers. ND v	wellhead. NU BOP. POOH w/2-7/8" tbg, 158
stage TD850 pmp, seal, 60 hp mtr & 4,100' #4 rd cable. Field inspection indicated cable good, mtr checked ok, top seal of pmp showed possible shaft problems. RD cable spoolers. PU & RIH w/4-3/4" bit,		
	, 6.5#, N-80, EUE, 8rd tbg, 5-1/2' csg scrap	
8rd tbg. Tagged fill	@ 3,820' (30' fill over perfs). POOH w/2-7,	/8" tbg & tools. SWI & SDON.
	7/5-1/2" CIBP on WL. Correlated WL depth to 1	
06/15/86. Set CIBP @ 3,754'. POOH w/WL & RD Jarrell. RU pipe tstrs. Tstd 2-7/8" tbg to 5,000 psig below slips. RIH w/5-1/2" BB AS1X pkr on 114 jts 2-7/8", 6.5#, N-80, EUE, 8rd tbg to 3,608'. Set pkr @ 3,608.		
RD pipe tstrs. RU pm	p trk. Loaded TCA w/30 BW & press tstd to 50	
	ces equipment. SWI & SDON.	
	5,000 psig. Held safety mtg. Frac'd Grayburg red by 72,000 gals slick wtr & 13,500# 20/40	
	2,790 psig. Flushed to top perf. ISIP 362 ps	
	pad pmpd, frac pmp failed. SD for 1.5 hrs to ost suction fr frac tanks, skipped .50# sd s	-
& SDON		5
I haraby continue that the information by	have is two and complete to the heat of my linewiled	an and holiaf the design of the state
grade tank has been/will be constructed or c	bove is true and complete to the best of my knowled losed according to NMOCD guidelines [], a general permit [or an (attached) alternative OCD-approved plan \Box .
SIGNATURE - July	TITLERegulatory Tec	hDATE_2/2/05
Type or print name	E-mail address:	Telephone No.
For State Use Only	N ORIGINAL SIGNED BY	APR 1 3 2005
	ORIGINAL SIGNED BY GARY W. WINK OCTFILE REPRESENTATIVE	
APPROVED BY: A any L Conditions of Approval (if any)	J. WMPOGTFIELED REPRESENTATIVE	APR 1 3 2005 CT APANA

EUNICE MONUMENT SO.UNIT #198. <= continued=>

12/24-27/04 SDF holiday.

• * - ^{- -}

- 12/28/04 SITP vac. Rel pkr & POOH w/2-7/8" tbg & pkr. RU Lucky rev unit. RIH w/4-3/4" bit, x-over, & 2 - 3-1/2" DCs on 2-7/8", 6.5#, N-80, EUE, 8rd tbg. Tagged sd @ 3,736'. Attempted to est circ, could not. POOH w/2-7/8" tbg & tools. SWI & SDON.
- 12/29/04 PU & RIH w/4-3/4" bit, tbg check valve, 5 jts 2-2/8", 6.5#, N-80, EUE, 8rd tbg & sd bailer on 2-7/8", 6.5#, N-80, EUE, 8rd tbg. Tagged fill @ 3,736'. Cleaned sd to 3,741' (CIBP). Dry drld on CIBP for 2 hrs & CIBP fell free. Pushed CIBP to 3,764' & could not get CIBP to go any lower. Suspect sd frac communicated below CIBP. POOH w/2-7/8" tbg & tools. RIH w/4-3/4" bit, x-over & 4 3-1/2" DCs on 108 jts 2-7/8" tbg to 3,530'. Left tools swinging. MIRU Key foam unit. SWI & SDON.
- 12/30/04 Hooked up blow dn line & frac tank. Est circ w/foam unit. Tagged CIBP @ 3,780'. RU swivel. Cleand fill to 3,847' (19' below btm perf) & quit making hole. Circ hole clean. POOH LD 2-7/8" tbg & tools. Changed BOP rams. SWI & SDON.
- 12/31/04 RU Centrilift spoolers. RIH w/Centrilift 60 hp, 1,505v, 27a UT mtr (same), seal section (same), RGS (same), 158 stg TD850 sub pmp (same), 70' mtr lead cable (new), 4,110' #4 round cable (same) on 118 jts 2-7/8", 6.5#, J-55, EUE, 8rd tbg (same). RD spoolers. ND BOP. NU WH. Sub pmpd up in 14". RWTP. Tbg & pmp landed @ 3,758'.
- 1/4/05 RU Centrilift. ND wellhead. POOH LD 3 jts 2-7/8" 6.5#, J-55, EUE, 8rd tbg. NU wellhead. RD Centrilift. Sub pmpd up in 13". RWTP. Tbg & pmp landed @ 3,665.78
- 1/6/05 In 24 hrs, well pmpd 11 BO, 612 BW & 5 mcf w/TD850 sub pmp. 100% run time. FL 797' FAP.
- 1/13/05 In 24 hrs, well pmpd 9 BO, 802 BW & 6 mcf w/TD850 sub pmp. 100% run time. FL 675' FAP.
- 1/14/05 In 24 hrs, well pmpd 13 BO, 804 BW & 6 mcf w/TD850 sub pmp. 100% run time. FL 697' FAP.
- 1/16/05 In 24 hrs, well pmpd 8 BO, 692 BW & 5 mcf w/TD850 sub pmp. 100% run time. FL 1,209' FAP.
- 1/21/05 In 24 hrs, well pmpd 26 BO, 812 BW & 6 mcf w/TD850 sub pmp. 100% run time.