Subsect One Const. To Ameroprote District	ico Form C-103
Submit One Copy To Appropriate District Office State of New Mexicon Office State of New Mexicon Office	
Energy, Minerals and Natura 1625 N French Dr., Hobbs, NM 88240 District II CONSERVATION F	WELL API NO.
811 S First St, Artesia, NM 88210 OIL CONSERVATION L	5 Indicate Type of Lease
District III 1000 Rio Brazos Rd, Aztec, NM 874 NOV 18 2011 1220 South St. Franc	is Dr. STATE STATE
District IV	6. State Oil & Gas Lease No. B-1553
1220 S St Francis Dr , Santa Fe, NM 87505	
SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG	7. Lease Name or Unit Agreement Name LOVINGTON PADDOCK UNIT
DIFFERENT RESERVOIR USE "APPLICATION FOR PERMIT" (FORM C-101) FOR	SUCH
PROPOSALS) 1. Type of Well: ⊠Oil Well ☐ Gas Well ☐ Other ☐ ☐ ☐ ☐	8. Well Number 45
2. Name of Operator	9. OGRID Number
Chevron Midcontinent L.P.	241333 //
3. Address of Operator 15 Smith Road, Midland TX. 79705	10. Pool name or Wildcat Lovington Paddock
4. Well Location	į į
Unit Letter \underline{A}' : 660 feet from the NORTH line and 330feet from the EAST line	
Section 2 Township 17S Range 36-E NMPM County LEA	
11. Elevation (Show whether DR, RKB, RT, GR, etc.) 3850	
12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data	
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:	
PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK ALTERING CASING	
TEMPORARILY ABANDON 🔲 CHANGE PLANS 🔲 COMMENCE DRILLING OPNS 🗌 P AND A 🛛	
PULL OR ALTER CASING	
OTHER: Discrete Location is ready for OCD inspection after P&A	
All pits have been remediated in compliance with OCD rules and the terms of the Operator's pit permit and closure plan.	
Rat hole and cellar have been filled and leveled. Cathodic protection holes have been properly abandoned. A steel marker at least 4" in diameter and at least 4" above ground level has been set in concrete. It shows the	
OPERATOR NAME, LEASE NAME, WELL NUMBER, API NUMBER, QUARTER/QUARTER LOCATION OR UNIT LETTER, SECTION, TOWNSHIP, AND RANGE. All INFORMATION HAS BEEN WELDED OR	
PERMANENTLY STAMPED ON THE MARKER'S SURFACE.	
The location has been leveled as nearly as possible to original ground contour and has been cleared of all junk, trash, flow lines and other production equipment.	
Anchors, dead men, tie downs and risers have been cut off at least two feet below ground level.	
If this is a one-well lease or last remaining well on lease, the battery and pit location(s) have been remediated in compliance with	
OCD rules and the terms of the Operator's pit permit and closure plan. All flow lines, production equipment and junk have been removed from lease and well location.	
All metal bolts and other materials have been removed. Portable base	es have been removed. (Poured onsite concrete bases do not have
to be removed.)	
 ✓ All other environmental concerns have been addressed as per OCD rules. ✓ Pipelines and flow lines have been abandoned in accordance with 19.15.35.10 NMAC. All fluids have been removed from non- 	
retrieved flow lines and pipelines.	
If this is a one-well lease or last remaining well on lease: all electrical service poles and lines have been removed from lease and well	
location, except for utility's distribution infrastructure.	
When all work has been completed, return this form to the appropriate District office to schedule an inspection.	
	A Actificial Lift and Corrosion Rep DATE 11/17/2011
TYPE OR PRINT NAME Danny Acosta E-MAIL: Acostde@Chevron.com PHONE: 575 631 9033 For State Use Only 0	
APPROVED BY: Malue Stown TITLE Compleance Office DATE 11/28/2011	
Conditions of Approval (if any):	NÓV 2 9 2011