Submit One Copy To Appropriate District  State of New Me:	xico Form C-103
Office District I Energy, Minerals and Natur	ral Resources Revised November 3, 2011
1625 N French Dr., Hobbs, NM 88240 BS OCD	WELL API NO.
811 S. First St., Artesia, NM 88210 OIL CONSERVATION	5 Indicate Type of Lease
District III 1000 Rio Brazos Rd., Aziec, NMM 41018 2011 1220 South St. Fran Santa Fe. NM 87	CIS Dr. STATE FEE
District IV 1220 S St Francis Dr., Santa Fe, NM	6. State Oil & Gas Lease No.
87505 <b>DECENTED</b>	
SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLU DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FO	
PROPOSALS.)  1. Type of Well:   Oil Well   Gas Well   Other - Injection	8. Well Number 37
2. Name of Operator  Chevron Midcontinent L.P.	9. OGRID Number 241333
3. Address of Operator	10. Pool name or Wildcat
15 Smith Road, Midland TX. 79705	Lovington; Grayburg - San Andres
4. Well Location	
Unit Letter A: 330 feet from the NORTH line and 990 feet from the EAST line  Section 6 Township 17-S Range 37-E NMPM County LEA	
11. Elevation (Show whether DR, RKB, RT, GR, etc.)	
12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data	
NOTICE OF INTENTION TO:	SUBSEQUENT REPORT OF:
PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐ TEMPORARILY ABANDON ☐ CHANGE PLANS ☐	REMEDIAL WORK ☐ ALTERING CASING ☐ ' COMMENCE DRILLING OPNS.☐ P AND A ☒
PULL OR ALTER CASING	CASING/CEMENT JOB
TOLE ON ALTEN CAGINO	
OTHER:    Description   Descri	
All pits have been remediated in compliance with OCD rules and the terms of the Operator's pit permit and closure plan.  Rat hole and cellar have been filled and leveled. Cathodic protection holes have been properly abandoned.	
A steel marker at least 4" in diameter and at least 4' above ground level has been set in concrete. It shows the	
OPERATOR NAME, LEASE NAME, WELL NUMBER, API NUMBER, QUARTER/QUARTER LOCATION OR	
UNIT LETTER, SECTION, TOWNSHIP, AND RANGE. All INFORMATION HAS BEEN WELDED OR	
PERMANENTLY STAMPED ON THE MARKER'S SURFACE.	
The location has been leveled as nearly as possible to original ground contour and has been cleared of all junk, trash, flow lines and	
other production equipment.  Anchors, dead men, tie downs and risers have been cut off at least two feet below ground level.	
If this is a one-well lease or last remaining well on lease, the battery and pit location(s) have been remediated in compliance with	
OCD rules and the terms of the Operator's pit permit and closure plan. All flow lines, production equipment and junk have been removed from lease and well location.	
All metal bolts and other materials have been removed. Portable bases have been removed. (Poured onsite concrete bases do not have	
to be removed.)  All other environmental concerns have been addressed as per OCD rules.	
Pipelines and flow lines have been abandoned in accordance with 19.15.35.10 NMAC. All fluids have been removed from non-	
retrieved flow lines and pipelines.  If this is a one-well lease or last remaining well on lease: all electrical service poles and lines have been removed from lease and well	
location, except for utility's distribution infrastructure.	
When all work has been completed, return this form to the appropriate District office to schedule an inspection	
SIGNATURE Danny Acosta TITLE: Artificial Lift and Corrosion Rep DATE 11/17/2011  TYPE OR PRINT NAME Danny Acosta E-MAIL: Acostde@Chevron.com PHONE: 575 631 9033	
For State Use Only	
APPROVED BY: Maley Shown TITLE Compliance Officer DATE 12/1/20/1 Conditions of Approval (if any)	
Conditions of Approval (if any)	$\omega$