Submit 1 Copy To	Appropriate Distr	ict	State of New	Mexico	)			Forr	n C-103	
Office <u>District 1</u> – (575) 39	93-6161	Energ	gy, Minerals and N	Vatural F	lesources			Revised Aug	ușt 1, 2011	
1625 N. French Dr., Hobbs, NM 88240						WELL API NO. 30-025-40250				
STI S. First St., Artesia, NM 88210						5. Indicate Type of Lease				
$\frac{\text{District III} - (505) 334-6178}{1000 \text{ Rio Brazos Rd.}, Aztec, NM 87 PPC 20 2011 1220 South St. Francis Dr.District IV - (505) 476-3460 Santa Fe, NM 87505$						STA		<u> </u>		
1220 S. St. Francis Dr., Santa Fe, NM						6. State Oi 37462	l & Gas Le	ase No.		
67505	SUNDRY	NOTICES AND	REPORTS ON WE	LLS				t Agreemen	t Name	
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS )							7 15 STAT	E		
1. Type of Well: Oil Well Gas Well Other							8. Well Number 3			
2. Name of Operator CML EXPLORATION, LLC							9. OGRID Number 256512			
3. Address of Operator P.O. BOX 890							10. Pool name or Wildcat LEAMEX; PADDOCK			
		SNYDER, TX 7	9550	``````	· · · · · · · · · · · · · · · · · · ·	LE	AMEX; PA	DDOCK		
4. Well Locatio		1080	fact for a the N		1	50 frot	in a second data	West	line	
Unit Lo Sectior			feet from theNo Township 17S	ortn Rang	line and16 ge 33E	NMPN	rom the		line ea	
Section	<u>1 13</u>	11 Eleva	·····		/		i Kanaka			
11. Elevation (Show whether DR, RKB, RT, GR, etc.) 4173' GR										
	12. Ch	eck Appropriat	te Box to Indicate	e Natur	e of Notice,	Report or (	Other Dat	a		
1	NOTICE O	F INTENTIO	N TO:	ł	SUB	SEQUEN		RT OF:		
PERFORM REMEDIAL WORK D PLUG AND ABANDON REMEDIAL WOR								ERING CAS	SING 🗌	
TEMPORARILY ABANDON 📋 CHANGE PLANS 🔲 COMMENCE DE							. PAI	ND A		
PULL OR ALTE			E COMPL	CA	SING/CEMEN	L JOB				
OTHER:				от	HER:					
			ions. (Clearly state							
		ed work). SEE R or recompletion.	ULE 19.15.7.14 NN	IAC. Fo	r Multiple Cor	npletions: At	tach wellbo	ore diagram	of	
propose	a completion (	n recompletion.		,						
SE	Е АТТАСН	ED COMPLE	TION REPORT							
011										
	ł									
	,						·			
Spud Date:	09/23	/2011	Rig Release	Date:	10/0	6/2011				
<u> </u>				l	10/0					
I hereby certify the	hat the inform	ation above is true	e and complete to th	e best of	my knowledge	e and belief.				
	11									
SIGNATURE	TITLE	TLEDA				_12/19/201	1			
Type or print nameNolan von Roeder For State Use Only			E-mail addr	E-mail address: _vonroedern@cmle			exp.com PHONE:325/573-1938			
							-			
APPROVED BY		Mary	TITLE	PETHR	LEUM ENG	VENDER 2	DATE	REP %	1 2011	
Conditions of Ap		):								

### PADDY 15 STATE NO. 3

## Sec. 15, T-17-S, R-33-E Lea County, New Mexico Property Code #37462 – API #30-025-40250

## DAILY COMPLETION REPORT

- 10/19/11 MIRUPU. NDWH. NUBOP w/2-3/8" pipe rams. Rigged up wireline truck & ran GR/CBL/CCL. Logged from PBTD @6321' to 5300' & 2000' to top of cement behind 5½" casing @1790'. Perforated Lower Paddock (6193' 6229') w/3-3/8" casing gun, 2 spf 120 phasing. Rigged down wireline truck. Ran in the hole with 5½" model "R" packer, SN & 2-3/8" used tubing. Landed packer @6246'. Rigged up acid truck w/4000 gals of 20% NEFE HCL w/additives & 100 ball sealers. Pumped 3 bbls 2% KCL to load tubing & establish circulation, switched to 20% HCL & spotted 100 gals across perforations. Tailed w/27 bbls 2% KCL water. Laid down 8 jts tubing. Set packer @5995'. Tested lines to 7000 psi. Pressured backside to 500 psi & held. Started w/water, loaded & broke down formation @2345 psi. Started on acid, pumped remaining 3500 gals of acid w/average 3210 psi & a rate of 3 bpm. Pumped 100 ball sealers evenly spaced w/moderate ball action, 20 to 30 differential. Flushed w/29 bbls 2% KCL water. ISIP = 2720 psi, 5 min = 2590 psi, 10 min = 2530 psi, 15 min = 2460 psi. SWIFN.
- 10/20/11 SITP = 200 PSI. Bled well down. IFL = surface. Made eight swab runs with 100% water. On ninth run, had 2% oil cut. Made 23 more runs & swabbed down to 3800'. Final oil cut 20%. Total load recovery = 178 bbls water & 16 bbls oil. SWIFN.
- 10/21/11 SITP = 150 psi. Made swab run, fluid level 3000' from the surface. Pulled 1500' of fluid, 1000' of free oil on top. Continued swabbing for 5 hours @rate of 15 bph, oil cut 20%. Fluid level remained @3800' from the surface. Had good gas show at the end of every swab run. Recovered a total of 75 bbls. Shut well in for the weekend.
- 10/24/11 SITP=150 psi. Made single swab run, fluid level 2800' from surface. Pulled 1500' of fluid, 750' of free oil on top, 750' water. Unset packer. Tripped out of the hole w/tubing. Tripped in the hole w/production assembly. Landed w/bottom of tubing 54' above perfs. NDBOP, NUWH & RDPU.

#### **TUBING DETAIL**

185 – jts 2-3/8" 4.7# J55 tubing 2-3/8" x 5-1/2" TAC @6061' 2 – jts 2-3/8" 4.7# J55 tubing 1 – 2-3/8" SN @6138' 4' x 2-3/8" perf sub 31' x 2-3/8" mud anchor w/bullplug

# PADDY 15 STATE NO. 3

Sec. 15, T-17-S, R-33-E Lea County, New Mexico Property Code #37462 – API #30-025-40250

## DAILY COMPLETION REPORT

12/01/11 MIRUPU. Ran in the hole with new rods & pump. Spaced & hung well on. Waiting on electric service. RDPU.

•

## **ROD DETAIL**

- $1 6' \times 7/8''$  sub
- 1 8' x 7/8" sub
- 74 7/8" steel rods
- 160 3/4" steel rods
  - 9 7/8" steel rods
  - 1 4' x 7/8" sub w/guides
  - 1 Tap tool
  - 1 1 1/2" x 20' pump