Submit 1 Copy To Appropriate District	State of New Mexi	co	Form C-103
Office District I – (575) 393-6161	Energy, Minerals and Natural Resources		Revised August 1, 2011
1625 N. French Dr , Hobbs, NM 882402566 APR		l	L API NO.
District II – (575) 748-1283 811 S. First St., Artesia, NM 88210 OIL CONSERVATION DIVISION			5-35562 dicate Type of Lease
1000 C / C P		is Dr.	STATE S FEE
District III - (505) 334-6178 1000 Rio Brazos Rd , Aztec, NM 87440 1 8 2012 District IV - (505) 476-3460 Santa Fe, NM 87505		05 6. Sta	ate Oil & Gas Lease No.
1220 S. St Francis Dr., Santa Fe, NM	,	0.5	
87505 DECEL	VED DEPONTS ON WELLS	7.1.	Name of Unit Agreement Name
SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A			ase Name or Unit Agreement Name JUM GRAYBURG SAN ANDRES
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH			
PROPOSALS.) 1. Type of Well: Oil Well Gas Well INJECTOR			
1. Type of Well: Oil Well Gas Well INJECTOR		8. W	ell Number 235
2. Name of Operator		9. OC	GRID Number 4323
CHEVRON U.S.A. INC.			
3. Address of Operator			ool name or Wildcat
15 SMITH ROAD, MIDLAND, TEXAS 79705		VAC	JUM GRAYBURG SAN ANDRES
4. Well Location			
Unit Letter H: 2610 feet from	om the NORTH line and 660 fee		
Section 1 Township 18-S Range 34-E NMPM County LEA			
11. Elevation (Show whether DR, RKB, RT, GR, etc.)			
			P. B. String Supple A. D. March Co. C. 1 Jan. St. 25, 1 And D. L. Anderson, P. C. 4.
12 Check Apr	propriate Boy to Indicate Nat	ure of Notice Repor	t or Other Data
12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data			
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:			
PERFORM REMEDIAL WORK ☑ PLUG AND ABANDON ☐ REMEDIAL WORK ☐ ALTERING CASING ☐			
TEMPORARILY ABANDON			
PULL OR ALTER CASING MULTIPLE COMPL CASING/CEMENT JOB			
DOWNHOLE COMMINGLE			
OTHER:		OTHER:	
13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date			
of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Completions: Attach wellbore diagram of			
proposed completion or recom	pletion.		
Wall has failed the annulus pressure test	t. Chevron plans to investigate the	cause of the leak and re	store the mechanical integrity of the
Well has failed the annulus pressure test. Chevron plans to investigate the cause of the leak and restore the mechanical integrity of the well.			
Woll.			
		•	
Spud Date:	Rig Release Date	:	
	 ;		
I hereby certify that the information abo	is two and complete to the heat	of my knowledge and h	aliaf
Thereby certify that the information abo		of my knowledge and be	ener.
SIGNATURE CHICAGO IN	上化りし TITLE: REGUL	ATORY SPECIALIST	DATE: 01-16-2012
The second of th			
Type or print name: DENISE PINKERTON E-mail address: leakejd@cvhevron.com PHONE: 432-687-7375			
(ا.ب. ۱۸	RTON E-mail address: <u>leakejd@</u>	@cvhevron.com	PHONE: 432-687-7375
APPROVED BY: Wahah	RTON E-mail address: leakejd@	Objana Office	PHONE: 432-687-7375 DATE 1-20-2012