



# NEW MEXICO ENERGY, MINERALS and NATURAL RESOURCES DEPARTMENT

**Susana Martinez**  
Governor

**John H. Bemis**  
Cabinet Secretary

**Jami Bailey**  
Division Director  
Oil Conservation Division

**\*Response Required – Deadline Enclosed\***

*Field Inspection Program*

*"Preserving the Integrity of Our Environment"*

03-Feb-12

**KEVIN O BUTLER & ASSOC INC**  
550 W. TEXAS STE 660  
MIDLAND TX 79701

## LETTER OF VIOLATION - Inspection

Dear Operator

The following inspection(s) indicate that the well, equipment, location or operational status of the well(s) failed to meet standards of the New Mexico Oil Conservation Division as described in the detail section below. To comply with standards imposed by Rules and Regulations of the Division, corrective action must be taken immediately and the situation brought into compliance. The detail section indicates preliminary findings and/or probable nature of the violation. This determination is based on an inspection of your well or facility by an inspector employed by the Oil Conservation Division on the date(s) indicated.

Please notify the proper district office of the Division, in writing, of the date corrective actions are scheduled to be made so that arrangements can be made to reinspect the well and/or facility.

### INSPECTION DETAIL SECTION

EAST EK UNIT No.003				K-22-18S-34E	30-025-02357-00-00		
Inspection Date	Type Inspection	Inspector	Violation?	<sup>1</sup> Significant Non-Compliance?	Corrective Action Due By:	Inspection No.	
02/02/2012	Complaint Response	Maxey Brown	Yes	No	5/8/2012	iMGB1203424159	
Comments on Inspection:		RULE 19 15 25 10 NEED TO REMOVE DISCONNECT THAT IS NOT ATTACHED TO POLE ALSO REMOVE OR CONTACT ELECTRICAL PROVIDER AND HAVE SECONDARY POLES AND WIRE REMOVED THIS IS 1ST LETTER OF NON-COMPLIANCE. MGB					

EAST EK UNIT No.002				J-22-18S-34E	30-025-02361-00-00		
Inspection Date	Type Inspection	Inspector	Violation?	<sup>1</sup> Significant Non-Compliance?	Corrective Action Due By:	Inspection No.	
02/02/2012	Complaint Response	Maxey Brown	Yes	No	5/7/2012	iMGB1203422502	
Comments on Inspection:		RULE 19 15 25 10 CONTROL PANEL HAS BEEN LEFT ON POLE AND SECONDARY POLE IS DAMAGED CAUSING LINE TO DROP DOWN VERY CLOSE TO THE GROUND IN ADDITIONAL 1 TALL POLE NO WIRING HAS BEEN LEFT AT PREVIOUS BATTERY SITE PLEASE REMOVE EQUIPMENT AND POWER POLES OR CONTACT ELECTRICAL PROVIDER AND HAVE POLES REMOVED. THIS IS 1ST LETTER OF NON-COMPLIANCE. MGB					

## EAST EK UNIT No.007

G-22-18S-34E

30-025-22362-00-00

Inspection Date	Type Inspection	Inspector	Violation?	Significant Non-Compliance?	Corrective Action Due By:	Inspection No.
02/02/2012	Complaint Response	Maxey Brown	Yes	No	5/7/2012	iMGB1203424650

Comments on Inspection: RULE 19 15 25 10. NEED TO REMOVE DISCONNECT AND SECONDARY POWER POLE OR CONTACT ELECTRICAL PROVIDER TO REMOVE. THIS IS 1ST LETTER OF NON-COMPLIANCE MGB

## EAST EK UNIT No.012

F-22-18S-34E


30-025-27948-00-00

Inspection Date	Type Inspection	Inspector	Violation?	Significant Non-Compliance?	Corrective Action Due By:	Inspection No.
02/02/2012	Complaint Response	Maxey Brown	Yes	No	5/7/2012	iMGB1203426873

Comments on Inspection: RULE 19 15 25 10. NEED TO REMOVE TRANSFORMERS, DISCONNECT AND METER BASE AND SECONDARY POWER POLES OR CONTACT ELECTRICAL PROVIDER AND HAVE REMOVED. THIS IS 1ST LETTER OF NON-COMPLIANCE MGB

In the event that a satisfactory response is not received to this letter of direction by the "Corrective Action Due By:" date shown above, further enforcement will occur. Such enforcement may include this office applying to the Division for an order summoning you to a hearing before a Division Examiner in Santa Fe to show cause why you should not be ordered to permanently plug and abandon this well. Such a hearing may result in imposition of CIVIL PENALTIES for your violation of OCD rules.


Sincerely,


**COMPLIANCE OFFICER**

Hobbs OCD District Office

Note: Information in Detail Section comes directly from field inspector data entries - not all blanks will contain data  
 \* Significant Non-Compliance events are reported directly to the EPA, Region VI, Dallas, Texas

EMNRD  
OIL CONSERVATION DIVISION  
1625 N FRENCH DRIVE  
HOBBS NM 88240



015H14150977

**\$0.65**


02/03/12

Mailed From 88240

HASLER


US POSTAGE

KEVIN O BUTLER & ASSOC INC  
550 W. TEXAS STE 660  
MIDLAND, TX 79701







02/02/2012

EAST EK QUEEN #2














WEST OF WELL # 2  
PREVIOUS BATTERY SITE



EAST EK QUEEN #12  
02/02/2012



