

## NEW MEXICO ENERGY, MINERALS and NATURAL RESOURCES DEPARTMENT

Susana Martinez	Z		Jami Bailey
Governor	k k		Division Director
			Oil Conversation Division
John H. Bemis Cabinet Secretary	(	*Response Required - Deadline Enclosed*	
Capiller Secretary		field Inspection Program	
		"Preserving my English of Our Englishment"	

03-Feb-12

KEVIN O BUTLER & ASSOC INC

550 W TEXAS STE 660 MIDLAND TX 79701

**LETTER OF VIOLATION - Inspection** 

Dear Operator:

The following inspection(s) indicate that the well, equipment, location or operational status of the well(s) failed to meet standards of the New Mexico Oil Conservation Division as described in the detail section below. To comply with standards imposed by Rules and Regulations of the Division, corrective action must be taken immediately and the situation brought into compliance. The detail section indicates preliminary findings and/or probable nature of the violation. This determination is based on an inspection of your well or facility by an inspector employed by the Oil Conservation Division on the date(s) indicated.

Please notify the proper district office of the Division, in writing, of the date corrective actions are scheduled to be made so that arrangements can be made to reinspect the well and/or facility.

			INSPECTIO	N DETAIL	SECTION		
EAST EK U Inspection Date	JNIT No.003  Type Inspection	1	Inspector	Violation?	K-22-18S-34E *Significant Non-Compliance?	30-025-02357-00 Corrective Action Due By:	-00 Inspection No.
02/02/2012	Complaint Re	sponse	Maxey Brown	Yes	No	5/8/2012	iMGB1203424159
Comments	on Inspection:	POLE ALSO I	REMOVE OR CON POLES AND WIRE	TACT ELEC	ONNECT THAT IS N TRICAL PROVIDER THIS IS IST LETT	AND HAVE	)
EAST EK U	JNIT No.002  Type Inspection		Inspector	Violation?	J-22-18S-34E *Significant Non-Compliance?	30-025-02361-00 Corrective Action Due By:	-00 Inspection No.
02/02/2012	Complaint Re	sponse	Maxey Brown	Yes	No	5/7/2012	iMGB1203422502
Comments	on Inspection:	POLE IS DAM. IN ADDITIONA SITE PLEASE	AGED CAUSING L AL 1 TALL POLE I E REMOVE EQUII ND HAVE POLES I	JNE TO DRO NO WIRING PMENT AND	BEEN LEFT ON POL DP DOWN VERY CL HAS BEEN LEFT AT POWER POLES OR THIS IS 1ST LETTE	OSE TO THE GROU PREVIOUS BATT CONTACT ELECT	JND. ERY

EAST EK UNIT No.007

G-22-18S-34E

30-025-22362-00-00

Inspection Date

02/02/2012

Type Inspection

Inspector

Violation?

Significant Non-Compliance?

Corrective Action Due By:

Inspection No.

Complaint Response Maxey Brown Yes

5/7/2012

iMGB1203424650

Comments on Inspection:

RULE 19 15 25 10. NEED TO REMOVE DISCONNECT AND SECONDARY POWER POLE OR CONTACT ELECTRICAL PROVIDER TO REMOVE THIS IS 1ST LETTER OF NON-

COMPLIANCE MGB

EAST EK UNIT No.012

F-22-18S-34E

30-025-27948-00-00

Inspection Date

Type Inspection

Inspector

Significant Violation? Non-Compliance?

Corrective Action Due By:

Inspection No.

02/02/2012

Complaint Response

Maxey Brown

Yes

No

5/7/2012

iMGB1203426873

Comments on Inspection:

RULE 19 15.25 10. NEED TO REMOVE TRANSFORMERS, DISCONNECT AND METER BASE AND SECONDARY POWER POLES OR CONTACT ELECTRICAL PROVIDER AND

HAVE REMOVED. THIS IS 1ST LETTER OF NON-COMPLIANCE. MGB

In the event that a satisfactory response is not received to this letter of direction by the "Corrective Action Due By:" date shown above, further enforcement will occur. Such enforcement may include this office applying to the Division for an order summoning you to a hearing before a Divison Examiner in Santa Fe to show cause why you should not be ordered to permanently plug and abandon this well. Such a hearing may result in imposition of CIVIL PENALTIES for your violation of OCD rules.

Sincerely.

Hobbs OCD District Office

Note: Information in Detail Section comes directly from field inspector data entries - not all blanks will contain data Significant Non-Compliance events are reported directly to the EPA, Region VI, Dallas, Texas

OIL CONSERVATION DIVISION 1625 N FRENCH DRIVE HOBBS NM 88240 EMNRD

KEVIN O BUTLER & ASSOC INC 550 W. TEXAS STE 660 MIDLAND, TX 79701


BOATROG SU


\$0.65 015H14150977


Mailed From 88240

02/03/12


in the state of









lage 2015



02/02/2012







JEST OF WELL# 2 PREVIOUS PATTERY SITE

EAST EK QUEEN #12 02/02/2012

