Submit 3 Copies To Appropriate District  Office District I  1625 N French Dr, Hobbs, NM-87240 District II  OIL CONSERVATION DIVISION	Form C-103 October 25, 2007 WELL API NO. 30-025-30489
1301 W. Grand Ave., Artesia, NM 88210 2012 1220 South St. Francis Dr. 1000 Rio Brazos Rd., Aztec, NM 87410 Santa Fe, NM 87505 District IV	5. Indicate Type of Lease  STATE FEE   6. State Oil & Gas Lease No.
1220 S. St. Francis Dr., Santa Fe, NECENED	6. State Off & Gas Lease No.
SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)	7. Lease Name or Unit Agreement Name: Snyder C
1. Type of Well: X Oil Well Gas Well ) Other	8. Well Number
2. Name of Operator	9. OGRID Number
Energen Resources Corporation	162928
3. Address of Operator 3300 N."A" St., Bldq 4, Ste. 100, Midland, TX 79705 4. Well Location	10. Pool name or Wildcat  Townsend, Permo Upper Penn
Unit Letter <u>E</u> : 2006 feet from the <u>North</u> line and <u>990</u> feet from the <u>WEst</u> line	
Section 5 , Township 16s Range 36E NMPM	County Lea
11. Elevation (Show whether DR, RKB, RT, GR, etc.) 3945.2	
12. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data	
NOTICE OF INTENTION TO:   SUBSEQUENT REPORT OF:	
PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK ALTERING CASING	
TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLING OPNS. P AND A	
PULL OR ALTER CASING  MULTIPLE COMPL  CASING/CEMENT	JOB 📋
OTHER:	eady for OCD inspection after P&A
All pits have been remediated in compliance with OCD rules and the terms of the Operator's pit permit and closure plan.  Rat hole and cellar have been filled and leveled. Cathodic protection holes have been properly abandoned.  A steel marker at least 4" in diameter and at least 4' above ground level has been set in concrete. It shows the	
OPERATOR NAME, LEASE NAME, WELL NUMBER, API NUMBER, QUARTER/QUARTER LOCATION OR	
UNIT LETTER, SECTION, TOWNSHIP, AND RANGE. All INFORMATION HAS BEEN WELDED OR PERMANENTLY STAMPED ON THE MARKER'S SURFACE.	
The location has been leveled as nearly as possible to original ground contour and has been cleared of all junk, trash, flow lines and other production equipment.	
Anchors, dead men, tie downs and risers have been cut off at least two feet below ground level.	
If this is a one-well lease or last remaining well on lease, the battery and pit location(s) have been remediated in compliance with	
OCD rules and the terms of the Operator's pit permit and closure plan. All flow lines, profrom lease and well location.	duction equipment and junk have been removed
All metal bolts and other materials have been removed. Portable bases have been removed. (Poured onsite concrete bases do not have	
to be removed.)  All other environmental concerns have been addressed as per OCD rules.	
Pipelines and flow lines have been abandoned in accordance with 19.15.9.714.B(4)(non-retrieved flow lines and pipelines.	b) NMAC. All fluids have been removed from
When all work has been completed, return this form to the appropriate District office to schedule an inspection. If more than one inspection has to be made to a P&A location because it does not meet the criteria above, a penalty may be assessed.	
SIGNATURE Regula	Foreman
	sorley@energen.com PHONE 432-818-1732
For State Use Only	011
Conditions of Approval, if any:	DATE 4/21/2012
	/ 1. mg -