Form 3160-5 (August 2007)

UNITED STATES
DEPARTMENT OF THE INTERIOR APR 1 2012 **BUREAU OF LAND MANAGEMENT**

Col 625 N. French Drivem APPROVED
Hot bs, NAL 832 OMB No. 1004-0137
Evalues: Inity 31, 2016

SUNDRY NOTICES AND REPORTS ON WEDLS

Do not use this form for proposals to drill or to re-entire an

. ,	Expires: July 31, 2010	
. Lease Serial No.		
NM-03927		
. If Indian, Allotte	e or Tribe Name	

abandoned well.	Use Form 3160-3 (A	(PD) for such proposa	is.	l			
SUBMIT IN TRIPLICATE – Other instructions on page 2.				7. If Unit of CA/Agreement, Name and/or No.			
1. Type of Well			Drickey Queen Sand Unit				
Oil Well Gas Well Other In -			,	8. Well Name and No. Drickey Queen Sand Unit #7			
2. Name of Operator Celero Energy II, LP				9. API Well No. 30-005-00902			
3a. Address	3b. Phone No. (include area code)		ode)	10. Field and Pool or Exploratory Area			
400 W. Illinois, Ste. 1601 Midland TX 7,9701 (432)686-1883			Caprock; Quee	:n			
4. Location of Well (Footage, Sec., T.,R.,M., or Survey Description) 1980' FSL & 660' FWL UL: L. Sec 34, T13S, R31E			11. Country or Parish, S Chaves		NM V		
		OX(ES) TO INDICATE NATUR	E OF NOTI		R DATA		
TYPE OF SUBMISSION		TY	YPE OF ACT	NON			
X Notice of Intent	Acidize Alter Casing	Deepen Fracture Treat		duction (Start/Resume)	Water Shut-		
Subsequent Report	Casing Repair	New Construction	Reco	omplete	Other		
Final Abandonment Notice	Change Plans Convert to Injection	Plug and Abandon Plug Back		iporarily Abandon er Disposal			
13. Describe Proposed or Completed O	peration: Clearly state all pe		d starting da	ite of any proposed work	and approximate	duration thereof. If	

the proposal is to deepen directionally or recomplete horizontally, give subsurface locations and measured and true vertical depths of all pertinent markers and zones. Attach the Bond under which the work will be performed or provide the Bond No. on file with BLM/BIA. Required subsequent reports must be filed within 30 days following completion of the involved operations. If the operation results in a multiple completion or recompletion in a new interval, a Form 3160-4 must be filed once testing has been completed. Final Abandonment Notices must be filed only after all requirements, including reclamation, have been completed and the operator has determined that the state of the completed services ready for final inspection.)

Request 14 Status. Subject well is part of the Caprock Queen field where wtr injection at this time is not needed.

However, the well may have future utility as an injection well in the event that the Rock Queen Unit CO2 pilot to the northeast is succussful.

1. POOH w/ injection equipment.

2. Set CIBP @ 2837'. Cap w/ min of 35' of cmt.

3. Circ hole w/inhibited fluid & perform MIT.

APPROVED FOR 3 MONTH PERIOD ENDING ___ JUL 0 2 2012

14. I hereby certify that the foregoing is true and correct. Name (Printed/Typed)						
Lisa Hunt	Title Regulatory Analyst					
Signature Lux Hunt	Date 04/02/2012					
THIS SPACE FOR FEDERAL OR STATE OFFICE USE						
/S/ DAVID R. GLASS	PETROLEUM ENGINEER Date APR 0 2 2012					
Conditions of approval, if any, are attached. Approval of this notice does not warrant or that the applicant holds lengt or contable title to those eights in the subject lease which we entitle the applicant to contact operations thereon.	tify					
Title 18 U.S.C. Section 1001 and Title 43 U.S.C. Section 1212, make it a crime for any particular of raudulent statements or representations as to any matter within its jurisdiction.	person knowingly and willfully to make to any department or agency of the United States any fals					

(Instructions on page 2) ATTACHED FOR **CONDITIONS OF APPROVAL**

BUREAU OF LAND MANAGEMENT Roswell Field Office 2909 West Second Street Roswell, New Mexico 88201 575-627-0272

Temporary Abandonment of Wells on Federal Lands Conditions of Approval

A temporary abandoned well is defined as a completion that is not capable of production in paying quantities but may have value as a service well. Pursuant to 43 CFR 3162.3-4(c), no well may be temporarily abandoned for more than 30 days without the prior approval of the authorized officer.

Temporary Abandonment (TA) status approval requires a successful casing integrity test as follows:

- A Notice of Intent (NOI) Sundry Notice (Form 3160-5) requesting approval to run a mechanical integrity test (MIT) or casing integrity test (CIT).
- 2. A description of the temporary abandonment procedure.
- A. A bridge plug or packer must be installed as close to 50 feet above any open perforations or open hole as possible. If a cement plug is used, the top of the cement must be verified by tagging.
- B. The wellbore must be filled with corrosion inhibited fluid and pressure tested to 500 psi. The casing shall be capable of holding this pressure for at least 30 minutes with a 10% allowable leakoff.
- C. All downhole production/injection equipment (tubing, rods, etc.) shall be removed from the casing if they are not isolated by a packer.
- D. A bradenhead test must be conducted. If the test indicates a problem exists, a remedial plan and time frame for remediation shall be submitted within ninety (90) days of the test.
- E. Contact the BLM Roswell Field Office at least 24 hours prior to the scheduled Casing Integrity Test. For wells in Chaves and Roosevelt County, during office hours or after office hours call (575) 627-0205. Engineer on call during office hours phone (575) 627-0275 or phone (after hours) call (575) 626-5749.

Wells that successfully pass the casing integrity test may be approved for Temporary Abandonment (TA) status up to 12 months.

- 1. Submits a subsequent Sundry Notice (Form 3160-5) requesting TA approval.
- 2. Attaches a clear copy of the original pressure test chart.
- 3. Provided justification why the well should be temporarily abandoned rather than permanently plugged and abandoned and an estimated date that the well will be returned to beneficial use or plugged and abandoned.
- 4. Describes the temporary abandonment procedure.

The TA status could be extended without another casing integrity test provided there was no leak-off during the test and the test was witnesses by a BLM representative.

If the well does not pass the casing integrity test, then the operator shall within 30 days submit to BLM for approval one of the following:

- 1. A procedure to repair the casing so that a TA approval can be granted.
- 2. A procedure to plug and abandon the well.

Ref: IM: NM-95-022 (12/16/1994)