Submit 3 Copies To Appropriate District	0	. N.A		Form C-103
Office District I	State of Ne	i i	WELL API NO.	October 25, 2005
1625%. French Dr.,Hobbs, NM 88240	Energy, Minerals and	Natural Resources		5-06602
District II	OIL CONSERVA	TION DIVISION		
1301 W Grand Ave., Artesia, NM 88210 Disrtict III			5. Indicate Type of Leas	
1000 Pio Brazos Pd. Aztec NM 87410 1220 South St. Francis Dr			STATE [☐ FEE ☑
District IV Santa Fe, NM 87505			6. State Oil & Gas Leas	e No.
District IV 1220 S. St. Francis Dr., Santa Fe, WAY 0 3 2012 87505				
		LS	7. Lease Name or Unit	Agreement Name
SUNDRY NOTICES MIND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR DEEPEN OR PLUG BACK TO			Northeast Drinkard Unit	
A DIFFERENT RESERVIOR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)			/	
1. Type of Well: Oil Well ☑ Gas Well ☐ Other /			8. Well Number	705
2. Name of Operator			9. OGRID Number	03
Apache Corporation				873
3. Address of Operator			10. Pool Name	
303 Veterans Airpark Ln., S	te. 3000, Midland, TX	(, 79705	Eunice; Blinebry-	-Tubb-Drinkard, N.
4. Well Location Unit Letter N	330 feet from the	S line and	2310 feet from the	. W line V
		Range 37E	NMPM	County Lea
, 11. Ele	evation (Show whether D	R, RKB,RT, GR, etc.)		
	34	117' GR		S Panen as a continuous
12. Check Appropriate Box To Indicate Na	ature of Notice, Report	, or Other Data		
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:				
	= 1	REMEDIAL WORK COMMENCE DRILLING OF	L ALTERING (NS. □ PANDA	CASING [7]
	= 1	CASING/CEMENT JOB		ŭ
DOWNHOLE COMMINGLE				
OTHER:		✓ Location is r	eady for OCD inspection a	ofter D&A
✓ All pits have been remediated in compliance w	rith OCD rules and the term)
Rat hole and cellar have been filled and leveled Cathodic protection holes have been properly abandoned.				
A steel marker at least 4" in diameter and at least 4' above ground level has been set in concrete. It shows the				
OPERATOR NAME, LEASE NAME, WELL NUMBER, API NUMBER, QUARTER / QUARTER LOCATION OR				
UNIT LETTER, SECTION, TOWNSHIP, AND RANGE. ALL INFORMATION HAS BEEN WELDED OR				
PERMANENTLY STAMPED ON THE MARKER'S SURFACE.				
The location has been leveled as nearly as possible to the original ground contour and has been cleared of all junk, trash, flow lines and				
other production equipment.				
Anchors, dead men, tie downs and risers have been cut off at least two feet below ground level				
If this is a one-well lease or last remaining well on lease, the battery and pit location(s) have been remediated in compliance with OCD rules and the terms of the Operator's pit permit and closure plan. All flow lines, production equipment and junk have been removed				
from the lease and well location				
All metal bolts and other materials have been removed Portable bases have been removed (Poured onsite concrete bases do not have				
to be removed) All other environmental concrens have been addressed as per OCD rules.				
Pipelines and flow lines have been abandoned in accordance with 19.15.9.714.B(4)(b) NMAC. All fluids have been removed from				
non-retrieved flow lines and pipelines.				
When all work has been completed, return this form to the appropriate District office to schedule an inspection. If more than one				
inspection has to be made to a P&A location b			- ·	
SIGNATURE SUMM SULLAS	TITLE _	Reclamation For	eman DATE	5/1/12
TYPE OR PRINT NAME Guinn Burl	ks E-MAIL	guinn burka@anacha	corp.com DUONE	120 EEG 0440
For State Use Only	19 E-IVIAIL	guinn.burks@apache	PHONE:	432-556-9143
	1.le _	Cm1- 1	\mathcal{L}^{2}	15/21/2000
APPROVED BY:	TITLE	why shance U	TICOT DATE	02/04/2012
Conditions of Approval (if any):		. •		1