HOBBS OCD

2012	
Submit One Copy To Appropriate District State of New Mexico Office State of New Mexico	Form C-103
District I	Revised November 3, 2011 WELL API NO.
1625 N. French Dr., Hobbs, NM 88240 District II 811 S. First St., Artesia, NM 88210 HOBBS OCE IL CONSERVATION DIVISION	VELE ATTRO.
District III 1220 South St. Evensia Dr.	3. Maleute Type of Bease
1000 Rio Brazos Rd, Aztec, NM 87410, District IV 1000 Rio Brazos Rd, Aztec, NM 87410, MAY 0 9 2012 Santa Fe, NM 87505	STATE FEE 6. State Oil & Gas Lease No.
1220 S. St. Francis Dr , Santa Fe, NM 87505	5. 5 5 2 2 5 1.0.
SUNDRY N ORCH SE ND REPORTS ON WELLS	7. Lease Name or Unit Agreement Name
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)	02 / 2./ 10 / 2.10 @ 22./ 0./ 1./
1. Type of Well: ☐ Oil Well ☐ Gas Well ☐ Other INJECTION	8. Well Number 037
2. Name of Operator LINN OPERATING, INC	9. OGRID Number 269234
3. Address of Operator	10. Pool name or Wildcat
600 TRAVIS STREET, SUITE 5100 HOUSTON, TX 77002	EUNICE;SEVEN RIVERS-QUEEN,
4. Well Location	300111
Unit Letter O: 990 feet from the SOUTH line and 2310 feet from the EAST line	
Section 34 Township 22S Range 36E NMPM County LEA	
11. Elevation (Show whether DR, RKB, RT, GR 3,496'	
12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data	
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:	
PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL V	_
TEMPORARILY ABANDON	E DRILLING OPNS. □ P AND A □
FOLL ON ALTER CASING MOLTIFLE COMPL CASING/CEI	INIENT JOB
	n is ready for OCD inspection after P&A
 ✓ All pits have been remediated in compliance with OCD rules and the terms of the Operator's pit permit and closure plan. ✓ Rat hole and cellar have been filled and leveled. Cathodic protection holes have been properly abandoned. 	
A steel marker at least 4" in diameter and at least 4' above ground level has been set in concrete. It shows the	
OPERATOR NAME, LEASE NAME, WELL NUMBER, API NUMBER, QUARTER/QUARTER LOCATION OR	
UNIT LETTER, SECTION, TOWNSHIP, AND RANGE. All INFORMATION HAS BEEN WELDED OR	
PERMANENTLY STAMPED ON THE MARKER'S SURFACE.	
The location has been leveled as nearly as possible to original ground contour and has been cleared of all junk, trash, flow lines and	
other production equipment. Anchors, dead men, tie downs and risers have been cut off at least two feet below ground level.	
If this is a one-well lease or last remaining well on lease, the battery and pit location(s) have been remediated in compliance with	
OCD rules and the terms of the Operator's pit permit and closure plan. All flow lines, production equipment and junk have been removed	
from lease and well location. All metal bolts and other materials have been removed. Portable bases have been removed. (Poured onsite concrete bases do not have	
to be removed.)	
 ✓ All other environmental concerns have been addressed as per OCD rules. ✓ Pipelines and flow lines have been abandoned in accordance with 19.15.35.10 NMAC. All fluids have been removed from non- 	
retrieved flow lines and pipelines.	
If this is a one-well lease or last remaining well on lease: all electrical service poles and lines have been removed from lease and well	
location, except for utility's distribution infrastructure.	7
When all work has been completed, return this form to the appropriate District office to schedule an inspection.	
SIGNATURE:	
TYPE OR PRINT NAME: TERRY B. CALLAHAN E-MAIL: tcallahan@linnenergy.com PHONE: 281-840-4272	
APPROVED BY: Wash White TITLE Complian	Le Officer DATE 05-16-2012
Conditions of Approval (if any):	

MAY 1 6 2012