HOBBS OCD

Submit One Copy To Appropriate DMAN 11 2012 State of New N	•
Enguery Minarala and No	atural Resources Revised November 3, 2011 WELL API NO.
District I 1625 N. French Dr., Hobbs, NM 88240 RECEIVED OIL CONSERVATIO District III 811 S. First St., Artesia, NM 88210 District III 1220 South St. Fr	30-025-28683
811 S. First St., Artesia, NM 88210 OIL CONSERVATION District III 1220 South St. Fi	5. Indicate Type of Lease
1000 Rio Brazos Rd, Aztec, NM 87410 District IV Santa Fe, NM	STATE FEE X
District IV 1220 S St Francis Dr , Santa Fe, NM	6. State Oil & Gas Lease No.
87505	
SUNDRY NOTICES AND REPORTS ON WEL (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR	
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101)	
PROPOSALS.) 1. Type of Well: Oil Well Gas Well Other	8. Well Number 062
2. Name of Operator	9. OGRID Number
LINN OPERATING, INC	269234
3. Address of Operator	10. Pool name or Wildcat
600 TRAVIS STREET, SUITE 5100	EUNICE; SEVEN RIVERS-QUEEN,
HOUSTON, TX 77002 4. Well Location	SOUTH
Unit Letter \underline{K} : 1555 feet from the <u>SOUTH</u> line and <u>2480</u> feet from the <u>WEST</u> line	
Section 34 Township 22S Range 36E NMPM County LEA	
11. Elevation (Show whether DR, RKB, RT, GR, etc.)	
11. Elevation (Show whether DR, RKB, RT, GR, etc.) 3,499'	
12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data	
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:	
PERFORM REMEDIAL WORK PLUG AND ABANDON	REMEDIAL WORK ALTERING CASING
TEMPORARILY ABANDON	COMMENCE DRILLING OPNS. □ P AND A □
PULL OR ALTER CASING MULTIPLE COMPL	CASING/CEMENT JOB
OTUED .	M Location is made to COD investigation of the DDA
OTHER:	
Rat hole and cellar have been filled and leveled. Cathodic protection holes have been properly abandoned.	
A steel marker at least 4" in diameter and at least 4' above ground level has been set in concrete. It shows the	
OPERATOR NAME, LEASE NAME, WELL NUMBER, API NUMBER, QUARTER/QUARTER LOCATION OR	
UNIT LETTER, SECTION, TOWNSHIP, AND RANGE. All INFORMATION HAS BEEN WELDED OR	
PERMANENTLY STAMPED ON THE MARKER'S SURFACE.	
☐ The location has been leveled as nearly as possible to original ground contour and has been cleared of all junk, trash, flow lines and other production equipment.	
Anchors, dead men, tie downs and risers have been cut off at least two feet below ground level.	
If this is a one-well lease or last remaining well on lease, the battery and pit location(s) have been remediated in compliance with	
OCD rules and the terms of the Operator's pit permit and closure plan. All flow lines, production equipment and junk have been removed from lease and well location.	
All metal bolts and other materials have been removed. Portable bases have been removed. (Poured onsite concrete bases do not have	
to be removed.)	
All other environmental concerns have been addressed as per OCD rules.	
☑ Pipelines and flow lines have been abandoned in accordance with 19.15.35.10 NMAC. All fluids have been removed from non-retrieved flow lines and pipelines.	
If this is a one-well lease or last remaining well on lease: all electrical service poles and lines have been removed from lease and well	
location, except for utility's distribution infrastructure.	
When all work has been completed, return this form to the appropriate District office to schedule an inspection.	
SIGNATURE MULA PORT TITLE: REGULATORY SPECIALIST III DATE: 010017	
TYPE OR PRINT NAME: TERRY B. GALLAHAN E-MAIL: tcallahan@linnenergy.com PHONE: 281-840-4272	
APPROVED BY: Wash With TITLE Compliance Officer DATE 5-16-2012	
Conditions of Approval (if any):	
	MAY 1 6 2012