HOBBS OCD

APR 2 4 2012

Submit One Copy To Appropriate District State of New Mexico	Form C-103
Office <u>District I</u> Energy, Minerals and Natural Resource EIVI	Revised November 3, 2011 WELL API NO.
1625 N French Dr., Hobbs, NM 88240 District II \$11.5 First St. Artesia NM 88210 OIL CONSERVATION DIVISION	30-025-24154
District III 1220 South St. Francis Dr.	5. Indicate Type of Lease STATE FEE X
1000 Rio Brazos Rd., Aztec, NM 87410 District IV Santa Fe, NM 87505	6. State Oil & Gas Lease No.
1220 S St. Francis Dr , Santa Fe, NM 87505	
SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A	7. Lease Name or Unit Agreement Name
DIFFERENT RESERVOIR USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH	VANCE 30
PROPOSALS) 1. Type of Well: ⊠Oil Well ☐ Gas Well ☐ Other	8. Well Number 3
2. Name of Operator WHITING OIL & GAS CORP.	9. OGRID Number 25078
3. Address of Operator	10. Pool name or Wildcat
400 W. ILLINOIS AVE., SUITE 1300, MIDLAND, TX 79	01 DOLLARHIDE/DEVONIAN
4. Well Location Unit Letter M : 660 feet from the S line and 990 feet from the V	V line
Section 30 Township 24 - SRange 38 - E NMPM County LI	EA
11. Elevation (Show whether DR, RKB, RT, GR, etc.)	
12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data	
	SEQUENT REPORT OF:
PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WOR TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRI	
PULL OR ALTER CASING MULTIPLE COMPL CASING/CEMEN	
OTHER:	eady for OCD inspection after P&A
All pits have been remediated in compliance with OCD rules and the terms of the Operator's pit permit and closure plan.	
Rat hole and cellar have been filled and leveled. Cathodic protection holes have been properly abandoned. A steel marker at least 4" in diameter and at least 4' above ground level has been set in concrete. It shows the	
OPERATOR NAME, LEASE NAME, WELL NUMBER, API NUMBER, QUARTER/QUARTER LOCATION OR	
UNIT LETTER, SECTION, TOWNSHIP, AND RANGE. All INFORMATION HAS BEEN WELDED OR	
PERMANENTLY STAMPED ON THE MARKER'S SURFACE.	
The location has been leveled as nearly as possible to original ground contour and has other production equipment.	been cleared of all junk, trash, flow lines and
Anchors, dead men, tie downs and risers have been cut off at least two feet below ground level.	
If this is a one-well lease or last remaining well on lease, the battery and pit location(s) have been remediated in compliance with OCD rules and the terms of the Operator's pit permit and closure plan. All flow lines, production equipment and junk have been removed	
from lease and well location. All metal bolts and other materials have been removed. Portable bases have been removed.	wed (Poured ansite concrete bases do not have
to be removed.)	ved. (1 outed offsite concrete bases do not have
 □ All other environmental concerns have been addressed as per OCD rules. □ Pipelines and flow lines have been abandoned in accordance with 19.15.35.10 NMAC 	All fluids have been removed from non-
retrieved flow lines and pipelines.	
If this is a one-well lease or last remaining well on lease: all electrical service poles an location, except for utility's distribution infrastructure.	d lines have been removed from lease and well
When all work has been completed, return this form to the appropriate District office to schedule an inspection.	
Mar Ha Park	
SIGNATURE / WarTha Garth TITLE Engineering	Tech. DATE <u>04/23/201</u> 2
TYPE OR PRINT NAME Martha Starek E-MAIL: mstarek@whi	ting.com PHONE: 432/6866758
APPROVED BY: Mark Whitelen TITLE Compliance	Officer DATE 05-22-2012

MAY 2.3 2012