06/14/2012 22:31	5057489720		DCD ARTESIA		PAGE 01/0
	HOBBS OCD			RECEIVED	Fl
JUN 1'8 2012				JUN 3 2012	
Submit One Copy To Appropriate E	District	State of New Me	xico	MMOCD ARTESI	Form C-10
Office District I 1625 N. French Dr., Hobbs, NM 88:	RECEIVED	Minerals and Natu	ral Resources	WELT 21 NO.	Rc ised November 3, 201
District U. Bill S First St., Artesia, NM 88210 OIL CONSERVATION DIVISION				30-025-23977	
District III 1220 South St. Francis Dr.			5. Indicate Type of STATE	Lease .	
District IV Santa Fe, NM 87505				6. State Oil & Gas I	
87505	NOTICES AND RE	PORTS ON WELLS		7 Lesse Name or L	Init Agrocment Name
(DO NOT USE THIS FORM FOR I DIFFERENT RESERVOID USE " PROPOSALS)	PROPOSALS TO DRILL	OR TO DEEPEN OR PL	JG BACK TO A	Vivian	
Type of Well: Oil Well Gas Well Other Ame of Operator				8. Well Number 3	
RKI Exploration & Production, LLC				9. OGRID Number 246289	1
 Address of Operator 3817 NW Expressway, Suite 950, Oklahoma City, OK 73112 				10. Pool name or W South Brunson Drin	
4. Well Location					
	0feet from the <u>Sout</u>			line	
Section <u>30</u> Tow	nship <u>22 South</u> Ran	gc <u>38 East</u> NMPN (Show whether DR,			
	3329 foot GF		· · · · · · · · · · · · · · · · · · ·		
12. Check Appropriate B			•		
NOTICE C)FINTENTION T RK□ PLUG AND A		SL REMEDIAL WO		DRT OF LTERING CASI NG []
TEMPORARILY ABANDON		ANS	COMMENCE D		
PULL OR ALTER CASING			CASING/CEME	INT JOB	
OTHER: All pits have been remedi	read in compliance w	ith OCD miles and th		ready for OCD inspect	io 1 after P&A
Rat hole and cellar have been filled and leveled. Cathodic protection holes have been properly abandoned.					
A steel marker at least 4"	in diameter and at lea	ast 4' above ground l	evel has been set	in concrete. It shows th	e
	<u>CTION, TOWNSHI</u>	P, AND RANGE.	<u>AII INFORMA</u> I	<u>DUARTER/QUARTER</u> ION HAS BEEN WEL	
The location has been leveled as nearly as possible to original ground contour and has been cleared of all junk, rash, flow lines and other production equipment.					
 Anchors, dead men, the downs and risers have been cut off at least two feet below ground level. If this is a one-well lease or last remaining well on lease, the battery and pit location(s) have been remediated in compliance with 					
OCD rules and the terms of the Operator's pit permit and closure plan All flow lines, production equipment and junk have been removed from lease and well location.					
🛛 All metal bolts and other materials have been removed. Portable bases have been removed. (Poured onsite concrete bases do not hav.					
to be removed.)					
Pipelines and flow lines have been abandoned in accordance with 19.15.35.10 NMAC. All fluids have been removed from 1 on-					
retrieved flow lines and pipelines.					
location, except for utility's dis	stribution infrastructu	re.			
When all work has been completed, return this form to the appropriate District office to schedule an inspection.					
SIGNATURE Charles	K. A.	TITLE_E	IS&E/Regulatory	/ ManagerDA	NT3_6/12/2012
TYPE OR PRINT NAME	Charles K. Ahn	E-MAI	L: <u>cahn@rkixp</u>	.com P	PH DNE: <u>405-99</u> 5-577)
For State Use Only	Whitel	_ (molia	Africa	
APPROVED BY: Mail			- pri one	<u>eciner</u>	DA FE 06-19-2012 JUN 20 2012

.