

Submit 3 Copies To Appropriate District Office

State of New Mexico
Energy, Minerals and Natural Resources

District I
1625 N French Dr, Hobbs, NM 88240
District II
1301 W. Grand Ave., Artesia, NM 88210
District III
1000 Rio Brazos Rd. Aztec, NM 87410
District IV
1220 S. St Francis Dr., Santa Fe, NM 87505

HOBBS OCD

OIL CONSERVATION DIVISION

JUL 02 2012

1220 South St. Francis Dr.
Santa Fe, NM 87505

RECEIVED

WELL API NO.

30-025-06996

5. Indicate Type of Lease

STATE ☐

FEE ☒

6. State Oil & Gas Lease No.

7. Lease Name or Unit Agreement Name

Owen "B"

8. Well Number

1

9. OGRID Number

00873

10. Pool Name

Blinebry O&G (Pro Gas)

SUNDY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR DEEPEN OR PLUG BACK TO A DIFFERENT RESERVIOR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well: Oil Well ☒ Gas Well ☐ Other ☐

2. Name of Operator

Apache Corporation

3. Address of Operator

303 Veterans Airpark Lane, Ste. 3000, Midland, TX, 79705

4. Well Location

Unit Letter

M

990

feet from the

S

line and

330

feet from the

W

line

Lea

Section

34

Township

21S

Range

37E

NMPM

County

11. Elevation (Show whether DR, RKB, RT, GR, etc.)

3440' GL

12. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK ☐

PLUG AND ABANDON ☐

REMEDIAL WORK ☐

ALTERING CASING ☐

☐

TEMPORARILY ABANDON ☐

CHANGE PLANS ☐

COMMENCE DRILLING OPNS ☐

P AND A ☐

☒

PULL OR ALTER CASING ☐

MULTIPLE COMPL ☐

CASING/CEMENT JOB ☐

☐

DOWNHOLE COMMINGLE ☐

OTHER ☐

☒ Location is ready for OCD inspection after P&A

☒ All pits have been remediated in compliance with OCD rules and the terms of the Operator's pit permit and closure plan

☒ Rat hole and cellar have been filled and leveled. Cathodic protection holes have been properly abandoned

☒ A steel marker at least 4" in diameter and at least 4' above ground level has been set in concrete It shows the

OPERATOR NAME, LEASE NAME, WELL NUMBER, API NUMBER, QUARTER / QUARTER LOCATION OR
UNIT LETTER, SECTION, TOWNSHIP, AND RANGE. ALL INFORMATION HAS BEEN WELDED OR
PERMANENTLY STAMPED ON THE MARKER'S SURFACE.

☒ The location has been leveled as nearly as possible to the original ground contour and has been cleared of all junk, trash, flow lines and other production equipment.

☒ Anchors, dead men, tie downs and risers have been cut off at least two feet below ground level

☒ If this is a one-well lease or last remaining well on lease, the battery and pit location(s) have been remediated in compliance with OCD rules and the terms of the Operator's pit permit and closure plan All flow lines, production equipment and junk have been removed from the lease and well location

☒ All metal bolts and other materials have been removed Portable bases have been removed. (Poured onsite concrete bases do not have to be removed.)

☒ All other environmental concerns have been addressed as per OCD rules

☒ Pipelines and flow lines have been abandoned in accordance with 19 15.9.714.B(4)(b) NMAC. All fluids have been removed from non-retrieved flow lines and pipelines

When all work has been completed, return this form to the appropriate District office to schedule an inspection. If more than one inspection has to be made to a P&A location because it does not meet the criteria above, a penalty may be assessed.

SIGNATURE Guinn Burks TITLE Reclamation Foreman DATE 6/25/12

TYPE OR PRINT NAME Guinn Burks E-MAIL guinn.burks@apachecorp.com PHONE: 432-556-9143

For State Use Only

APPROVED BY: Mark Whitman TITLE Compliance Officer DATE 7-11-2012

Conditions of Approval (if any):

JUL 11 2012