HOBBS OCD

Submit 2 Copies To Appropriate District 2 4 2012 State of New Mexico Office District 1 Energy, Minerals and Natural Resources 1625 N. French Dr., Hobbs, NM 8824 FECEIVED District III 1301 W. Grand Ave., Artesia, NM 88210 District III 1000 Rio Brazos Rd., Aztec, NM 87410 Sente Fo. NIM 87505	Form C-103 October 25, 2007 WELL API NO. 30-025-00109 5. Indicate Type of Lease STATE FEE
District IV 1220 S. St. Francis Dr., Santa Fe, NM 87505 Santa Fe, NM 87505	6. State Oil & Gas Lease No.
SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH	7. Lease Name or Unit Agreement Name New Mexico BB State
PROPOSALS.) 1. Type of Well: ☐ Oil Well ☐ Gas Well ☒ Other	8. Well Number 001
2. Name of Operator PALADIN ENERGY CORP.	9. OGRID Number 164070
3. Address of Operator	10. Pool name or Wildcat
10290 Monroe Drive, Suite 301, Dallas, TX 75229	SWD; Devonian
4. Well Location Unit Letter K: 1989 feet from the South line and 1985 feet from the Westline	
11. Elevation (Show whether DR, RKB, RT, GR, etc.)	
12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data	
	SEQUENT REPORT OF:
PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRIL	_
PULL OR ALTER CASING MULTIPLE COMPL CASING/CEMENT	<u> </u>
	A second second
OTHER: Description Descri	
Rat hole and cellar have been filled and leveled. Cathodic protection holes have been properly abandoned.	
A steel marker at least 4" in diameter and at least 4' above ground level has been set in concrete. It shows the	
OPERATOR NAME, LEASE NAME, WELL NUMBER, API NUMBER, QUARTER/QUARTER LOCATION OR	
UNIT LETTER, SECTION, TOWNSHIP, AND RANGE. All INFORMATION HAS BEEN WELDED OR PERMANENTLY STAMPED ON THE MARKER'S SURFACE.	
The location has been leveled as nearly as possible to original ground contour and has been cleared of all junk, trash, flow lines and	
other production equipment.	
Anchors, dead men, tie downs and risers have been cut off at least two feet below ground level. If this is a one-well lease or last remaining well on lease, the battery and pit location(s) have been remediated in compliance with	
If this is a one-well lease or last remaining well on lease, the battery and pit location(s) have been remediated in compliance with OCD rules and the terms of the Operator's pit permit and closure plan. All flow lines, production equipment and junk have been removed	
from lease and well location.	
All metal bolts and other materials have been removed. Portable bases have been removed. (Poured onsite concrete bases do not have	
to be removed.)	
 ✓ All other environmental concerns have been addressed as per OCD rules. ✓ Pipelines and flow lines have been abandoned in accordance with 19.15.9.714.B(4)(b) NMAC. All fluids have been removed from 	
non-retrieved flow lines and pipelines.	
When all work has been completed, return this form to the appropriate District office to schedule an inspection. If more than one inspection has to be made to a P&A location because it does not meet the criteria above, a penalty may be assessed.	
SIGNATURE TITLE Manager, Corporate Support DATE 08/21/12	
TYPE OR PRINT NAMEAnn WestberryE-MAIL: awestberry@paladinenergy.co For State Use Only	m PHONE: 214-054-0132
$M \rightarrow M + M + M + M + M + M + M + M + M + $	
Conditions of Approval (if any)	4/
	AUG 2. 9 2012

AUG 2.9 2012