Submit 3 Copies To Appropriate District	Ctata of N	lavy Marrian		Form C-103
Office District I		New Mexico nd Natural Resources	WELL API NO.	October 25, 2005
1625 N French Di Hobbs, NM 88240				05 05070
District II ** HOB	BS OC DIL CONSERV	ATION DIVISION		25-05870
1301 W. Grand Ave , Artesia, NM 88210 Disrtict III			Indicate Type of Lea	<u> </u>
1000 Rio Brazos Rd Aztec, NM 87410 SEP 2 8 2012 1220 South St. Francis Dr.			STATE	☐ FEE ☑ /
District IV Santa Fe, NM 87505			6. State Oil & Gas Lea	se No.
1220 S. St. Francis Dr., Santa Fe, NM		,		
	NED	ELLO	7 Legge Name or Uni	t Agraement Nama
SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR DEEPEN OR PLUG BACK TO			7. Lease Name or Unit Agreement Name North Monument Grayburg/SA/ Unit Blk	
A DIFFERENT RESERVIOR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH			1	
PROPOSALS.)			8. Well Number	
1. Type of Well: Oil Well · 🗹 Gas Well 🗌 Other				2
2. Name of Operator	/	·	9. OGRID Number	
Apache Corporation				00873
3. Address of Operator 303 Veterans Airpark Lane, Ste. 3000, Midland, TX, 79705			10. Pool Name Eunice Monument; Grayburg/SA	
4. Well Location	ine, Ste. 3000, Milalana,	17, 13103	Lume Honan	itelit, Grayburgion
Unit Letter B	: 330 feet from the	N line and	1648 feet from th	ne E line
Section 3	Township 20S	Range 37E	NMPM	County Lea
1	1. Elevation (Show whether			
		3550' GR	* *	
12. Check Appropriate Box To Indica	te Nature of Notice. Repo	ort, or Other Data		
	HANGE PLANS	COMMENCE DRILLING OF CASING/CEMENT JOB		
OTHER:			eady for OCD inspection	after P&A
All pits have been remediated in complia				
Rat hole and cellar have been filled and A steel marker at least 4" in diameter an				
	SE NAME, WELL NUMBER , TOWNSHIP, AND RANGE			
· · · · · · · · · · · · · · · · · · ·	ED ON THE MARKER'S SU			_
The location has been leveled as nearly as possible to the original ground contour and has been cleared of all junk, trash, flow lines and				
other production equipment. Anchors, dead men, tie downs and risers	s have been cut off at least two	feet below around level		
If this is a one-well lease or last remaining well on lease, the battery and pit location(s) have been remediated in compliance with				
OCD rules and the terms of the Operato	r's pit permit and closure plan.	All flow lines, production equi	pment and junk have beer	removed
from the lease and well location. All metal bolts and other materials have	hoon romayad Dortable hases	have been removed. (Bours	d anaita aanarata hasaa d	a not have
All metal bolts and other materials have to be removed.)	been lemoved. Foliable bases	nave been lemoved (Foule	d onsite concrete bases d	o not nave
All other environmental concrens have b	een addressed as per OCD rule	es		
Pipelines and flow lines have been abandoned in accordance with 19.15.9.714.B(4)(b) NMAC. All fluids have been removed from				
non-retrieved flow lines and pipelines				
When all work has been completed, retuinspection has to be made to a P&A location.	• • • •			e
~ n nn			<i>y</i> == == <i>x</i> ======	
SIGNATURE Zem Sillus	TITLE	P&A Technic	an DATE	9/26/12
	Sellers E-MAIL	leon.sellers@apache	ecorp.com PHONE:	432-208-0349
For State Use Only	7.1.	1	(C	
APPROVED BY: Conditions of Approval (if any):	nitchen_ TITLE	Louis Lance O	Holer DATE	10-01-2012