Submit 1 Copy To Appropriate District Office	State of New Me Energy, Minerals and Natur	<b>₩</b>	Form C-103 October 13, 2009
District I 1625 N French Dr , Hobbs, NM 882	Energy, witherars and reach	rai resources	WELL: API NO.
District II	OIL CONSERVATION	DIVISION	30-025-20630
1301 W. Grand Ave., Artesia, NM 88210 District III	1220 South St. Fran	MARS OCD	5. Indicate Type of Lease
1000 Dis Des on Del Asses NIM 97 MIN			STATE FEE
District IV 1220 S. St Francis Dr , Santa Fe, NM	RECENED Santa Fe, NM 87	OCT 22 2012	6. State Oil & Gas Lease No.
87505	RECE		58102
SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACKENED)			7. Lease Name or Unit Agreement Name
(DO NOT USE THIS FORM FOR PROPOS	ALS TO DRILL OR TO DEEPEN OR PLU	JG BACKERINED	,
DIFFERENT RESERVOIR, USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS )			FLYING M SAN ANDRES UNIT
1. Type of Well: Oil Well Gas Well Other INJ			8. Well Number
2. Name of Operator			9. OGRID Number
SOUTHWEST ROYALTIES, INC.			21355
3. Address of Operator 6 DESTA DRIVE, STE 2100, MIDLAND, TEXAS 79705			10. Pool name or Wildcat FLYING M SAN ANDRES UNIT
			FLIING M SAN ANDRES UNIT
4. Well Location			
Unit Letter_N:_659_feet from theSline and1996feet from theWline			
Section 16 Township 9S Range 33E NMPM LEA County			
11. Elevation (Show whether DR, RKB, RT, GR, etc.)			
10 10 10 10 10 10 10 10 10 10 10 10 10 1	4374' GL		
12. Check A	ppropriate Box to Indicate Na	ature of Notice,	Report or Other Data
		1	_
NOTICE OF IN			SEQUENT REPORT OF:
PERFORM REMEDIAL WORK [] TEMPORARILY ABANDON []	PLUG AND ABANDON  CHANGE PLANS	REMEDIAL WORK	<del>-</del>
PULL OR ALTER CASING	MULTIPLE COMPL	COMMENCE DRII	<del></del>
DOWNHOLE COMMINGLE	MOLTIFLE COMPL	CASING/CEMENT	I JOB
DOWNTOLL COMMITTEE			
OTHER:			over & MIT
13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date			
of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.			
proposed completion of recompletion.			
Work Summary: AD-1 pkr sheared, ran new DL tension pkr			
Oct 2, 2012 RU WS; WH cap loose and stripped; found AD-1 pkr, unset, dug out around WH; PIH w/tbg & pkr and found pkr			
sheared. RIH w/1 stand tbg & SION. Oct 3, 2012 POOH W/ 1-std tbg; dug out around WH and unscrewed WH; put on new			
4 1/2 X 8 5/8 X 2 3/8 Larkin WH and RIH w/new DL tension pkr & 107 jts 2 3/8 tbg; stacked out @ 3440'. POOH w/tbg and			
pkr; tallied tbg; NU 8 5/8 X 2 3/8 BOP. RIH w/bit, scrapper, tbg w/139 jts to 4356' did not tag. POOH w/tbg and bit & came up			
hole 1 jt still unable to set pkr; SION. Oct 4, 2012 Pmpd 30 BFW dwn csg; hit little press; pmpd another 50 Bbls; unable to			
circ. SD pm well on vac; unable to set pkr; LD 2 jts still unable to set pkr @ 4292' or 159' above top perf @ 4451'. SI due to			
high winds. Oct 5, 2012 POOH w/tbg and pkr; found pkr sheared; put on redressed AD-1 pkr and RIH w/ 2 jts tbg. Unable to set pkr; pkr would set in BOP; RIH w/ 2 jts unable to set; POH; RIH w/DL tension pkr w2 jts tbg set pkr; released; RIH			
w/pkr & 139 JTS 2 3/8 PC tbg total. Set pkr @ 4356'; released; ND BOP; pmpd 52 BFW w/pkr fluid; set pkr w/10 pts @ 4356'			
and pressured to 300#. Bled down; pulled 13 pts in to pkr; press to 460# and ran attached chart. Bled dwn to 450# in 36			
mins. Successful test. RD MO; N	flaxie Brown w/NMOCD was pre	sent on location b	out had to leave early.
CHART ATTACHED.			
Spud Date: 4/22/64	Rig Release Da	5/5/64	
Spud Date.	Kig Kelease Da	ite.	
I hereby certify that the information a	above is true and complete to the be	est of my knowledge	e and belief
,,		is or my mic wiedge	t and belief.
SIGNATURE TITLE Operations Asst DATE_10/1712			
Type or print name Dawn M. Howard E-mail address: dhoward@claytonwilliams.com PHONE: 432/688-3267			
For State Use Only			
Conditions of Approval (il any):			
	•		OCT 2 2 2012 \

