Submit One Copy To Appropriate District Office State of New Me		Form C-103
District I  811 S. First St., Grand Ave., Artesia, NM 88210  District III  1000 Rio Brazos Rd Aztec NM 87410  District III  1000 Rio Brazos Rd Aztec NM 87410  Energy, Minerals and Natural Resources  Energy, Minerals and Natural Resources  1220 South St. Francis Dr.  Santa Fe, NM 87505		WELL API NO. 30-025-03031
		5. Indicate Type of Lease
		STATE X FEE
District IV 1220 S. St. Francis Dr., Santa Fe, NM 87410 87505  Santa Fe, NM 87410 2012 Santa Fe, NM 87410		o. State on & Gas Lease No.
87505 SUNDRY NOTICE REPORTS ON WELLS		7. Lease Name or Unit Agreement Name
SUNDRY NOTICE REPORTS ON WELLS  (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)		EAST VACUUM (GSA) ÜNIT
1. Type of Well: XOil Well Gas Well Other OIL /		8. Well Number 040
2. Name of Operator CONOCOPHILLIPS COMPANY		9. OGRID Number 217817
3. Address of Operator 3300 N A ST, BLDG 6 MIDLAND,TX ZIP 79705		10. Pool name or Wildcat VACUUM GB/SA
4. Well Location		
Unit Letter D : 660 feet from the North line and 660 feet from the WESTine  Section 35 Township 17S Range 35E NMPM County LEA		
11. Elevation (Show whether DR, RKB, RT, GR, etc.) 3918 (GL)		
12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data		
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:		
PERFORM REMEDIAL WORK DPLUG AND ABANDON	REMEDIAL WORK	
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐ PULL OR ALTER CASING ☐ MULTIPLE COMPL ☐	COMMENCE DRIL CASING/CEMENT	<u></u>
		. —
OTHER:     \times \text{ Location is ready for OCD inspection after P&A}     \times \text{ All pits have been remediated in compliance with OCD rules and the terms of the Operator's pit permit and closure plan.}		
Rat hole and cellar have been filled and leveled. Cathodic protection holes have been properly abandoned.  A steel marker at least 4" in diameter and at least 4' above ground level has been set in concrete. It shows the		
·		
OPERATOR NAME, LEASE NAME, WELL NUMBER, API NUMBER, QUARTER/QUARTER LOCATION OR UNIT LETTER, SECTION, TOWNSHIP, AND RANGE. All INFORMATION HAS BEEN WELDED OR		
PERMANENTLY STAMPED ON THE MARKER'S SURFACE.		
The location has been leveled as nearly as possible to original ground contour and has been cleared of all junk, trash, flow lines and other production equipment.		
Anchors, dead men, tie downs and risers have been cut off at least two feet below ground level.		
OCD rules and the terms of the Operator's pit permit and closure plan. All flow lines, production equipment and junk have been removed		
from lease and well location.  All metal bolts and other materials have been removed. Portable bases have been removed. (Poured onsite concrete bases do not have		
to be removed.)		
All other environmental concerns have been addressed as per OCD rules.  Pipelines and flow lines have been abandoned in accordance with 19.15.35.10 NMAC. All fluids have been removed from non-		
retrieved flow lines and pipelines.		
When all work has been completed, return this form to the appropriate District office to schedule an inspection.		
SIGNATURE TITLE RI		NAME TO THE TOTAL POST OF THE
	g feiervary@conoc	
TYPE OR PRINT NAME GUSTAVO FEJERVARY  E-MAIL: g_fejervary@conocophillips.com  PHONE: (432)688-9012		
APPROVED BY: Y Mey & Drown TITLE Compliance Office DATE 10/31/2017 Conditions of Approval (if arly):		
V		067 3 1 2012 V