Submit One Copy To Appropriate District Office	State of New Mexico	Form C-103 Revised August 1, 2011
	Energy, Minerals and Natural Resources	WELL API NO. 30-005-21133
District II 811 S. First St., Grand Ave., Artesia, NAOBBS O 88210	SPL CONSERVATION DIVISION 1220 South St. Francis Dr. Santa Fe, NM 87505	5. Indicate Type of Lease
District III 1000 Rio Brazos Rd., Aztec, NM 87410	2012 Santa Fe, NM 87505	STATE X FEE 6. State Oil & Gas Lease No.
District IV 1220 S. St. Francis Dr., Santa Fe, NM		
87505	ND REPORTS ON WELLS	7. Lease Name or Unit Agreement Name
(DO NOT USE THIS FORM FOR PROPOSALS TO DIFFERENT RESERVOIR. USE "APPLICATION	D DRILL OR TO DEEPEN OR PLUG BACK TO A	Drickey Queen Sand Unit
PROPOSALS.) 1. Type of Well: XOil Well Gas W	Vell Other	8. Well Number 145
2. Name of Operator Celero Energy II,		9. OGRID Number 247128
3. Address of Operator 400 W. Illinois, S	Ste. 1601 Midland, TX 79701	10. Pool name or Wildcat
4. Well Location	-	Caprock; Queen
Unit Letter K: 1440 feet from the S line and 2620 feet from the W line		
Section 35 Township 13S Range 31E NMPM County Chaves		
11. E	Elevation (Show whether DR, RKB, RT, GR, e	tc.)
12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data		
NOTICE OF INTEN	TION TO: SU	BSEQUENT REPORT OF:
	G AND ABANDON REMEDIAL WO	
<u></u>	NGE PLANS ☐ COMMENCE D TIPLE COMPL ☐ CASING/CEME	PRILLING OPNS.□ PANDA □
	_	_
OTHER: All pits have been remediated in comp	liance with OCD rules and the terms of the O	perator's pit permit and closure plan.
Rat hole and cellar have been filled and leveled. Cathodic protection holes have been properly abandoned. A steel marker at least 4" in diameter and at least 4' above ground level has been set in concrete. It shows the		
OPERATOR NAME, LEASE NAME, WELL NUMBER, API NUMBER, QUARTER/QUARTER LOCATION OR		
UNIT LETTER, SECTION, TOWNSHIP, AND RANGE. All INFORMATION HAS BEEN WELDED OR		
PERMANENTLY STAMPED ON THE MARKER'S SURFACE.		
The location has been leveled as nearly as possible to original ground contour and has been cleared of all junk, trash, flow lines and other production equipment.		
Anchors, dead men, tie downs and risers have been cut off at least two feet below ground level.		
If this is a one-well lease or last remaining well on lease, the battery and pit location(s) have been remediated in compliance with OCD rules and the terms of the Operator's pit permit and closure plan. All flow lines, production equipment and junk have been removed		
from lease and well location. All metal bolts and other materials have been removed. Portable bases have been removed. (Poured onsite concrete bases do not have		
to be removed.)		
All other environmental concerns have been addressed as per OCD rules. Pipelines and flow lines have been abandoned in accordance with 19.15.35.10 NMAC. All fluids have been removed from non-		
retrieved flow lines and pipelines.		
When all work has been completed, return this form to the appropriate District office to schedule an inspection.		
φ \cdot \checkmark		
SIGNATURE Jua Hun	TITLE Regulatory Analyst	DATE <u>10/25/2012</u>
TYPE OR PRINT NAME Lisa Hunt	E-MAIL: <u>lhunt@celeroen</u>	ergy.com PHONE: (432)686-1883
For State Use Only		
APPROVED BY: Y W (14 AND) Conditions of Approval (if any)	wr title Complian	relifice DATE 11/1/2018
<u> </u>		