Submit One Copy To Appropriate District Office	State of New Me Energy, Minerals and Natu			Form C-103 Revised August 1,2011
District I 1625 N. French Dr., Hobbs, NM 88240			WELL API NO.	30-025-00287
District II 811 S. First St., Grand Ave., Artesia, NABS OF RESIDENT AND ARTESIA PROPERTY OF THE PROPERTY OF T	DIL CONSERVATION	DIVISION	5. Indicate Type	
			STATE	X FEE
1000 Rio Brazos Rd., Aztec, NM 87410 District IV	2012 Santa Fe, NM 8	7303	6. State Oil & G	as Lease No.
1220 S. St. Francis Dr., Santa Fe, NM 87505				•
SUNDRY NOTIFICE AND REPORTS ON WELLS			7. Lease Name or Unit Agreement Name	
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)			Rock Queen Unit	
1. Type of Well: XOil Well Gas Well Other			8. Well Number 1	
2. Name of Operator Celero Energy II, LP			9. OGRID Number 247128	
3. Address of Operator 400 W. Illinois, Ste. 1601 Midland, TX 79701			10. Pool name or Wildcat	
			Caprock; Queen	
4. Well Location Unit Letter G: 2310 feet from the N line and 1650 feet from the E line				
Section 19 - Township 13S Range 32E NMPM County Lea				
11. Elevation (Show whether DR, RKB, RT, GR, etc.)				
12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data				
NOTICE OF INTE			SEQUENT RE	PORT OF: ALTERING CASING □
PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐ REMEDIAL WOR TEMPORARILY ABANDON ☐ CHANGE PLANS ☐ COMMENCE DRI				P AND A
·	JLTIPLE COMPL	CASING/CEMENT		
OTHER:	П		ady for OCD insp	ection after P&A
All pits have been remediated in compliance with OCD rules and the terms of the Operator's pit permit and closure plan.				
Rat hole and cellar have been filled and leveled. Cathodic protection holes have been properly abandoned. A steel marker at least 4" in diameter and at least 4' above ground level has been set in concrete. It shows the				
OPERATOR NAME, LEASE NAME, WELL NUMBER, API NUMBER, QUARTER/QUARTER LOCATION OR UNIT LETTER, SECTION, TOWNSHIP, AND RANGE. All INFORMATION HAS BEEN WELDED OR				
PERMANENTLY STAMPED ON THE MARKER'S SURFACE.				
The location has been leveled as nearly as possible to original ground contour and has been cleared of all junk, trash, flow lines and				
other production equipment.				
Anchors, dead men, tie downs and risers have been cut off at least two feet below ground level. If this is a one-well lease or last remaining well on lease, the battery and pit location(s) have been remediated in compliance with				
OCD rules and the terms of the Operator's pit permit and closure plan. All flow lines, production equipment and junk have been removed				
from lease and well location. X All metal bolts and other materials have been removed. Portable bases have been removed. (Poured onsite concrete bases do not have				
to be removed.)	ive been removed. Portable of	ises have been remov	rea. (Poured onsid	e concrete bases do not have
All other environmental concerns ha			411.00 - 1 1 1 1	1.0
Pipelines and flow lines have been a retrieved flow lines and pipelines.	bandoned in accordance with	19.15.35.10 NMAC.	All fluids have be	een removed from non-
• •				
When all work has been completed, return this form to the appropriate District office to schedule an inspection.				
SIGNATURE LUR H	ent TITLE R	egulatory Analyst		_DATE <u>10/25/2012</u>
TYPE OR PRINT NAME Lisa Hunt	E-MAIL:	lhunt@celeroenerg	y.com	PHONE: <u>(432)686-1883</u>
For State Use Only	1000	./\ `	(L)) '	11/1-01
APPROVED BY: Y Conditions of Approval (if any):	TITLE C	ompliance	yuce	_DATE 11 /1 / 2012
* V				<i></i>