Submit One Copy To Appropriate District	State of New Mex	ico	Form C-103
Office District I Energy, Minerals and Natural Resources		l Resources	January 20, 2011
1625 N French Dr., Hobbs, NM 88240			WELL API NO.
OIL CONCEDVATION DIVICION			30-025-35424
District III NOV 0 1 7017 1220 South St. Francis Dr.		ic Dr	5. Indicate Type of Lease STATE FEE FEE FEE
1000 Rio Brazos Rd., Aztec, NM 87410 V V 7 20121220 South St. 17 and S DT. District IV 1220 S St. Francis Dr., Santa Fe, NM 87505 87505		05	6. State Oil & Gas Lease No.
87505			
SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A		BACK TO A	7. Lease Name or Unit Agreement Name
DIFFERENT RESERVOIR USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)		L	Outland State Unit
1. Type of Well: Oil Well Gas Well Other			8. Well Number 6
Name of Operator DEVON ENERGY PRODUCTION CO LP			9. OGRID Number 6137
3. Address of Operator			10. Pool name or Wildcat
PO BOX 250, ARTESIA, NM 88211			Wildcat Wolfcamp
4. Well Location The Location the SOUTH line and 000 feet from the FAST View			
Unit Letter <u>1650</u> feet from the <u>SOUTH</u> line and <u>990</u> feet from the <u>EAST</u> line Section <u>2</u> Township <u>21S</u> Range <u>34E</u> NMPM County <u>LEA</u>			
11. Elevation (Show whether DR, RKB, RT, GR, etc.)			
3720' KB; 3703' GL			
12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data			
NOTICE OF INTENTIO	1		EQUENT REPORT OF:
' PERFORM REMEDIAL WORK ☐ PLUG AN · TEMPORARILY ABANDON ☐ CHANGE		REMEDIAL WORK COMMENCE DRILI	
<u>=</u>	_ ,	CASING/CEMENT	- , , , —
-	_ '		
OTHER:			
Rat hole and cellar have been filled and leveled. Cathodic protection holes have been properly abandoned.			
A steel marker at least 4" in diameter and at least 4' above ground level has been set in concrete. It shows the			
OPERATOR NAME, LEASE NAME, WELL NUMBER, API NUMBER, QUARTER/QUARTER LOCATION OR UNIT LETTER, SECTION, TOWNSHIP, AND RANGE. All INFORMATION HAS BEEN WELDED OR			
PERMANENTLY STAMPED ON THE MARKER'S SURFACE.			
✓ The book of the book of the control of the contr			
The location has been leveled as nearly as possible to original ground contour and has been cleared of all junk, trash, flow lines and other production equipment.			
Anchors, dead men, tie downs and risers have been cut off at least two feet below ground level.			
If this is a one-well lease or last remaining well on lease, the battery and pit location(s) have been remediated in compliance with OCD rules and the terms of the Operator's pit permit and closure plan. All flow lines, production equipment and junk have been removed			
from lease and well location.			
🛛 All metal bolts and other materials have been removed. Portable bases have been removed. (Poured onsite concrete bases do not have			
to be removed.) All other environmental concerns have been addressed as per OCD rules.			
An other environmental concerns have been addressed as per OCD thies. Pipelines and flow lines have been abandoned in accordance with 19.15.35.10 NMAC. All fluids have been removed from non-			
retrieved flow lines and pipelines.			
If this is a one-well lease or last remaining well on lease, all electrical service, poles and lines, not to include primary service company equipment, has been removed from lease and well location.			
When all work has been completed, return this form to the appropriate District office to schedule an inspection.			
(PLEASE SEE ATTACHED COMMENTS)			
SIGNATURE Lun Hulling TITLE Asst. Construction Foreman DATE 11/1/2012			
TYPE OR PRINT NAMEKevin PhillipsE-MAIL:Kevin.Phillips@dvn.com PHONE: 575-390-5085 (cell)			
For State Use Only			
APPROVED BY: Male With TITLE Compliance Officer DATE 11-02-2012 Conditions of Approval (if any): NOV 0 5 2012			
Conditions of Approval (if any):			
			110.

Outland State Unit # 6

DCP has been contacted on removing the meter run, once they remove it we will knock down the caliche under it.

The flow line on the corner of location is diconnected and has been given to rancher.