NEW MEXICO OIL CONSERVATION COMMISS Santa Fe, New Mexico

MISCELLANEOUS REPORTS ON V

Submit this report in TRIPLICATE to the District Office, Oil Conservation Commission, within 10 days after the special is completed. It should be signed and filed as a report on Beginning Drilling Operations, Results of test of casing shut-off, result of plurging of well, result of well repair, and other important operations, even though the work was witnessed by an agent of the Commission. See additional instructions in the Rules and Regulations of the Commission.

REPORT ON BEGINNING	REPORT ON RESULT OF	TEST	REPORT ON REPAIRING WELL	T
RILLING OPERATIONS	OF CASING SHUT-OFF		REPAIRING WELL	-
EPORT ON RESULT F PLUGGING WELL	REPORT ON RECOMPLET OPERATION	TION	REPORT ON (Other)	<u> </u>
	' May 25, 195	3	Seminole, Texas	
	(Date)		(Place)	
Following is a report on the work	done and the results obtained under	tne heading not	ind above at the	
larren Petroleum Corporat			Duke	
(Company or O)		,	(Leane)	מו
Sharp Drilling Company	n , Well I	No *	in the NE 14 SE 14 of Sec.	77
95 R 36E NMPM U	ndesignated	Pool,	Lea	County
•				
he Dates of : is work were as follows:	May 24, 1953	'		
lation of intention to do the work (we	ARRITHM submitted on Forms C 102	~~	May 23	ıa 53
otice of intention to no the work (was	s) ###### submitted on Form C-102	0.10	Cross out incorrect words	13
nd approval of the proposed plan (was	. 1			
in approvator the proposed man (was	i) (was not) obtained.			
DETA	LEU SCOUNT OF WORK DONE	AND RESULT	rs obtained	
Washed well with 50	U.EU ACCOUNT OF WORK DONE O gallons of mud acid.			
DETA Washed well with 50	U.EU ACCOUNT OF WORK DONE O gallons of mud acid.		Wisen.	
DETA Washed well with 50	U.EU ACCOUNT OF WORK DONE O gallons of mud acid.		Wisen.	
DETA Washed well with 50	U.EU ACCOUNT OF WORK DONE O gallons of mud acid.		Wisen.	
DETA Washed well with 50	U.EU ACCOUNT OF WORK DONE O gallons of mud acid.		Wisen.	
DETA Washed well with 50	U.EU ACCOUNT OF WORK DONE O gallons of mud acid.		Wisen.	
DETA Washed well with 50	U.EU ACCOUNT OF WORK DONE O gallons of mud acid.			
Washed well with 50 Results - cleaned u	DED ACCOUNT OF WORK DONE O gallons of mud acid. p bored hole.	on con	Wisen.	
Washed well with 50 Results - cleaned u	U.EU ACCOUNT OF WORK DONE O gallons of mud acid.	on cons	JUN 1 1953	/
Washed well with 50. Results - cleaned u Witnessed by Eugene Jowers (Name)	O gallons of mud acid. p bored hole. Sharp Drilling	On con-	Tool Pusher	
Washed well with 50 Results - cleaned u Witnessed by	O gallons of mud acid. p bored hole. Sharp Drilling	On con-	Tool Pusher (Title)	f complete
Washed well with 50. Results - cleaned u Witnessed by Eugene Jowers (Name)	O gallons of mud acid. p bored hole. Sharp Drilling	CO.	Tool Pusher (Title)	f complete
Washed well with 50. Results - cleaned u Witnessed by Eugene Jowers (Name)	O gallons of mud acid. p bored hole. Sharp Drilling	CO.	Tool Pusher (Title)	f complete
Washed well with 50. Results - cleaned u Witnessed by	O gallons of mud acid. p bored hole. Sharp Drilling	CO.	Tool Pusher (Title) the information given above is true and owledge.	