

Submit 3 Copies To Appropriate District Office
District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Ave., Artesia, NM 88210
District III
1000 Rio Brazos Rd., Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy, Minerals and Natural Resources

Form C-103
May 27, 2004

OIL CONSERVATION DIVISION
1220 South St. Francis Dr.
Santa Fe, NM 87505

WELL API NO.	30-025-24168
5. Indicate Type of Lease STATE <input type="checkbox"/> FEE <input checked="" type="checkbox"/>	
6. State Oil & Gas Lease No.	
7. Lease Name or Unit Agreement Name SOUTH JUSTIS UNIT	
8. Well Number "G" 13	
9. OGRID Number	
10. Pool name or Wildcat JUSTIS-BLBRY-TUBB-DRINKARD	

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well: Oil Well ☒ Gas Well ☐ Other ☐

2. Name of Operator
HENRY PETROLEUM LP

3. Address of Operator 3525 ANDREWS HWY. - MIDLAND TX 79703-5000

4. Well Location
Unit Letter J : 1750 feet from the SOUTH line and 2310 feet from the EAST line
Section 12 Township 25S Range 37E NMPM County LEA

11. Elevation (Show whether DR, RKB, RT, GR, etc.)
3091 GR

Pit or Below-grade Tank Application ☐ or Closure ☐

Pit type _____ Depth to Groundwater _____ Distance from nearest fresh water well _____ Distance from nearest surface water _____

Pit Liner Thickness: _____ mil Below-Grade Tank: Volume _____ bbls; Construction Material _____

12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐
PULL OR ALTER CASING ☐ MULTIPLE COMPL ☐

OTHER: ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☒ ALTERING CASING ☐
COMMENCE DRILLING OPNS. ☐ P AND A ☐
CASING/CEMENT JOB ☐

OTHER: RETURN TO PRODUCTION ☐

13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.

No pit needed

6-10-05 MIRU SU

6-13-05 8 5/8" wellhead had fallen approx 18in. Dug out cellar. Found 8-5/8" csg bad.

6-14-05 At 10' down 8 5/8" csg is OK w/cmt behind it.

6-16-05 MIRU PU. ND WH. POOH w/ 2- 3/8" tbg. Ran RBP & 16 jts 2-3/8" tbg. Set RBP at 498' RU pump truck. Pressured up on 5 1/2" csg from surface to 500' to 500#. Held for 30 minutes. Pulled & LD 16 jts 2 3/8" tbg. & rel head.

6-17-05 ND 8 5/8" csg head. Cut off bad 8 5/8" csg. Welded on slip collar and 28" of 8 5/8" csg head. Cut off 5 1/2" bell nip & 6" of 5 1/2" csg due to pitting. Replaced bell nipple.

6-21-05 MIRU PU. PU on 5 1/2" csg. Set slips. NU 8 5/8" csg head and 5 1/2" csg head. ran ret. head and 16 jts 2-3/8" tbg. Released RBP. POOH w.RBP. TIH w/2 3/8" prod. tbg.

6-22-05 Replaced TAC. TIH w/2 3/8" tbg. Set TAC. NU WH. TIH pump and rods. Hung rods on. Hooked up flowline.

6-23-05 Spaced out rods. RD PU.

Returned well to production

Form C-104 will be sent after testing the well.

I hereby certify that the information above is true and complete to the best of my knowledge and belief. I further certify that any pit or below-grade tank has been/will be constructed or closed according to NMOCD guidelines ☐, a general permit ☐ or an (attached) alternative OCD-approved plan ☐.

SIGNATURE Shirley Houchins TITLE REGULATORY SPECIALIST DATE 07/14/2005

Type or print name SHIRLEY HOUCHINS

For State Use Only

APPROVED BY: Gary W. Wink

Conditions of Approval (if any):

E-mail address: shirley@henrypetroleum.com Telephone No. (915)694-3000

ORIGINAL SIGNED BY

GARY W. WINK

OC FIELD REPRESENTATIVE W/STAFF MANAGER

AUG 25 2005
DATE