INCLINATION REPORT

1. FIELD NAME	2. LEASE NAME
	Forty Niner Rridge #6

3. OPERATOR
Strata Production

4. ADDRESS
P.O. Box 1030, Roswll, N.M. 88202

5. LOCATION (Section, Block, and Survey)
Sec 22, T-23-S, R-30-E, Eddy, N.M.

RECORD OF INCLINATION

*11. Measured Depth (feet)	12. Course Length (Hundreds of feet)	*13. Angle of Inclination (Degrees)	14. Displacement per Hundred Feet (Sine of Angle x 100)	15. Course Displacement (feet)	16. Accumulative Displacement (feet)
385	385	0.25	.44	1.69	1.69
828	440	0.25	.44	1.93	3.62
1327	499	0.25	.44	2.19	5.81
1826	499	0.50	.87	4.34	1015.00
2336	510	0.75	1.31	6.68	16.83
2839	503	0.75	1.31	6.58	23.41
3390	551	3.75	6.54	36.03	59.44
3475	85	4.00	6.98	5.93	65.37
3569	94	3.25	5.67	5.32	70.69
3643	74	2.25	3.93	2.90	73.59
3865	222	2.00	3.49	7.74	81.33
3919	54	1.50	2.62	1.41	82.74
4433	514	1.25	2.18	11.20	93.96
4938	505	0.75	1.31	6.61	100.55
5416	478	1.00	1.75	8.36	108.91
5921	505	0.25	.44	2.22	111.13
6396	475	1.25	2.18	10.35	121.48
6905	509	1.00	1.75	8.90	130.38
7417	512	1.25	2.18	11.16	141.54
7890	473	1.25	2.18	10.31	151.85

Accumulative total displacement of well bore at total depth of 7890' 151.85'

Inclination measurements were made in : ☐ Tubing ☐ Casing Open Hole ☒

Signature of Authorized Representative	Signature of Authorized Representative
L.V. Bohannon	
Name of Person and Title (type or print)	Name of Person and Title (type or print)
Adobe Drilling	
Name of Company	Name of Company
Telephone 432-552-5553	Telephone
Area Code	Area Code

Certified By _____ *Date* _____

Rhonda Fullton 3-21-05