

4/11/2005

Wellbore Diagram

r263

30-015-33843-00-00

EAST SHUGART DELAWARE UNIT No. 023

Company Name: ST. MARY LAND & EXPLORATION COMPANY

Location: Sec: 24 T: 18S R: 31E Spot:

String Information

Lat: 32.7339708254494 Long: -103.815318232159

Property Name: EAST SHUGART DELAWARE U

County Name: Eddy

Cement Information

Perforation Information

Top (ft sub)	Bottom (ft sub)	Shts/Ft	No Shts	Dt Sqz
0	0			

Formation Information

St Code	Formation	Depth
Psal	Salado	1065
Pbslt	Base of Salt	2204
Psrbs	Bowers Sand	3290
Pqu	Queen	3520
Pqpen	Penrose	3759
Pgb	Grayburg	3937
Pdel	Delaware	4504

Hole: Unknown

TD:

TVD: 0

PBTD: