Submit 3 Copies To Appropriate District Office	State of New Mexico			Form C-103		
District I	Energy, Minerals and Natural Resources					arch 25, 1999
1625 N. French Dr., Hobbs, NM 88240				WELL API NO.		
<u>District II</u> 1301 W. Grand Ave., Artesia, NM 88210	OIL CONSERVATION DIVISION			30-025-10483		
District III	1220 South St. Francis Dr.			5. Indicate Type STATE		□ P
1000 Rio Brazos Rd., Aztec, NM 87410 District IV	Santa Fe, NM 87505				& Gas Lease No.	
1220 S. St. Francis Dr., Santa Fe, NM 87505				o. State On 6	e Gas Loase 110.	
SUNDRY NOTION (DO NOT USE THIS FORM FOR PROPOSE DIFFERENT RESERVOIR. USE "APPLIC PROPOSALS.)		EPEN OR PLU	JG BACK TO A	7. Lease Name	e or Unit Agreen	ent Name:
1. Type of Well: Oil Well Gas Well Other Water Injection Well				Langlie Mattix Penrose Sand Unit		
2. Name of Operator				8. Well No.		
Pecos Production Company				9. Pool name or Wildcat		
3. Address of Operator 400 W. Illinois, Ste 1070, Midland, TX 79701				Langlie Mattix; 7 RVRS-Q-Grayburg		
4. Well Location						
Unit LetterB_:880	feet from the _Nor	th	_ line and1980	feet from the	eEast	_line
Section 27	Township 22S	Re	inge 37E	NMPM Le	ea Count	v
Section 27	10. Elevation (Show				A COUNT	,
11 01 1	3335' DF	. 4:		D O41-	Dete	
	ppropriate Box to In	ndicate N			ier Data REPORT OF:	
NOTICE OF IN' PERFORM REMEDIAL WORK	PLUG AND ABANDON	V 🗆	REMEDIAL WOR		_	
TEMPORARILY ABANDON	CHANGE PLANS		COMMENCE DRI	LLING OPNS.	PLUG AND ABANDONM	MENT
PULL OR ALTER CASING	MULTIPLE COMPLETION		CASING TEST AI	ND [-	
OTHER:			OTHER:			
12. Describe proposed or completed starting any proposed work). SE recompilation.	l operations. (Clearly st E RULE 1103. For Mu	ate all perti iltiple Com	nent details, and gi pletions: Attach we	ve pertinent date ellbore diagram o	s, including estin of proposed comp	nated date of pletion or
Repairs as follows:						
5/21/03- MIRU PU. POOH w/tl	og & RIH w/bit. Tag fil	l at 3559'.			19202	12
5/21/03- MIRU PU. POOH w/tl 5/22/03- Clean out fill. 5/23/03- Circ well clean. POOH				,	167170	(553)
5/23/03- Circ well clean. POOH	I. RIH hydrotesting IPC	tbg – no f	ailures. Replaced to	op jt. Displace/a	nnulus w/pkr flu	id. Set AD-1
pkr at 3399'. LD & tes	t annulus to 500 psi – he	eld good. N	ND BOP & NU WH	I. RD PU. 🕸		262
5/29/03- Attempt MIT test (faile	ed). Test witnessed by I	NM OCD B	uddy Hill.	712		272
6/2/03- Conduct MIT test (350)	psi for 30 mins) – good	test. Buddy	Hill w/OCD unab	le to witness test	Chart enclosed	Í. 🐇
6/3/03- Return well to injection.	, -	-				E.G.
· · · · · · · · · · · · · · · · · · ·					12345	
I hereby certify that the information	above is true and comple	ete to the b	est of my knowledg	e and belief.		
SIGNATURE LOCA BANG	toment	_TITLE	Engineer Asst.	DA	TE_6 <u>/03/03</u>	
Type or print name Dora Bustam	ante	Telephon	e No. (915) 620-8	3480		
(This space for State use)	, · / 0	C FIELD R	EPRESENTATIVE I	I/STAFF MANA	GER JU	IN 1 7 200
APPPROVED BY SAME OF CONDITIONS OF APPPROVED BY	'Dark	TITLE		<u> </u>	DATE	

