Submit One Copy To Appropriate District State of New Mexico Office District I HOBBS OCD Energy, Minerals and Natural Resources	Form C-103 Revised November 3, 2011
Office District I 1625 N. French Dr., Hobbs, NM 88240 District II 811 S. First St., Artesia, NM 88210 District III 1220 South St. Francis Dr.	WELL API NO. 30-025-06192 5. Indicate Type of Lease STATE FEE
1000 Rio Brazos Rd., Aztec, NM 87410 District IV 1220 S. St. Francis Dr., Santa Fe, NM ECEIVED 87505	6. State Oil & Gas Lease No.
SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)	7. Lease Name or Unit Agreement NameState A 208. Well Number
 Type of Well: Oil Well Gas Well Other Name of Operator Cimarex Energy Co. of Colorado 	002 9. OGRID Number 162683
 Address of Operator 600 N Marienfeld, Ste 600; Midland, TX 79701 	10. Pool name or Wildcat Eumont; Monument, Grayburg, SA.
4. Well Location Unit Letter J :2310 feet from the South line and 2100 feet from the East line	
Section 20 Township 20S Range 37E NMPM Lea County Image: County In Elevation (Show whether DR, RKB, RT, GR, etc.) 3524' GR	
12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data	
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF: PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK ALTERING CASING TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLING OPNS. P AND A PULL OR ALTER CASING MULTIPLE COMPL CASING/CEMENT JOB	
OTHER: Image: Construction is ready for OCD inspection after P&A Image: All pits have been remediated in compliance with OCD rules and the terms of the Operator's pit permit and closure plan. Image: Rat hole and cellar have been filled and leveled. Cathodic protection holes have been properly abandoned. Image: Rat hole and cellar have been filled and leveled. Cathodic protection holes have been properly abandoned. Image: Rat hole and cellar have been filled and leveled. Cathodic protection holes have been properly abandoned. Image: Rat hole and cellar have been and at least 4' above ground level has been set in concrete. It shows the	
OPERATOR NAME, LEASE NAME, WELL NUMBER, API NUMBER, QUARTER/QUARTER LOCATION OR UNIT LETTER, SECTION, TOWNSHIP, AND RANGE. All INFORMATION HAS BEEN WELDED OR PERMANENTLY STAMPED ON THE MARKER'S SURFACE.	
The location has been leveled as nearly as possible to original ground contour and has been cleared of all junk, trash, flow lines and other production equipment.	
 Anchors, dead men, tie downs and risers have been cut off at least two feet below ground level. If this is a one-well lease or last remaining well on lease, the battery and pit location(s) have been remediated in compliance with OCD rules and the terms of the Operator's pit permit and closure plan. All flow lines, production equipment and junk have been removed from lease and well location. 	
All metal bolts and other materials have been removed. Portable bases have been removed. (Poured onsite concrete bases do not have to be removed.)	
 All other environmental concerns have been addressed as per OCD rules. Pipelines and flow lines have been abandoned in accordance with 19.15.35.10 NMAC. All fluids have been removed from non-retrieved flow lines and pipelines. If this is a one wall laces or last remaining wall or laces all electrical environmental concerns have been up to the second sec	
If this is a one-well lease or last remaining well on lease: all electrical service poles and lines have been removed from lease and well location, except for utility's distribution infrastructure.	
When all work has been completed, return this form to the appropriate District office to schedule an inspection.	
SIGNATURE TITLE Assistant Foreman DATE 1-4-13 TYPE OR PRINT NAME Ronnic Hayes E-MAIL: rhayes @ cimarex.com PHONE: 575-390-0157	
For State Use Only.	
APPROVED BY: Machhitaken	
	< chm