Submit One Conv To Appropriate District	Form C-103		
Submit One Copy To Appropriate District Office District L HOBBS OCD Energy, Minerals and Natural Resources	Revised November 3, 2011		
	WELL API NO. 30-025-04696		
1625 N. French Dr., Hobbs, NM 88240 <u>District II</u> 811 S. First St., Artesia, NM 88210 FEB 11 2013 OIL CONSERVATION DIVISION	5. Indicate Type of Lease		
District III 1220 South St. Francis Dr.	$STATE \square FEE x$		
1000 Rio Brazos Rd., Aztec, NM 87410 Interference District IV RECEIVED 1220 S. St. Francis Dr., Santa Fe, NM	6. State Oil & Gas Lease No.		
87505 SUNDRY NOTICES AND REPORTS ON WELLS	7. Lease Name or Unit Agreement Name		
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH	Eunice Monument South Unit		
PROPOSALS.) 1. Type of Well: Dil Well Gas Well X Other Injection	8. Well Number #406		
2. Name of Operator XTO ENERGY, INC.	9. OGRID Number 005380		
3. Address of Operator	10. Pool name or Wildcat		
200 N. LORAINE, SUITE 800, MIDLAND, TEXAS 79701	Eunice Monument; Grayburg/San Andres		
4. Well Location			
Unit Letter j _: <u>1670</u> feet from the <u>South</u> line and <u>1650</u>	_feet from the <u>East</u> line		
Section <u>17</u> Township <u>21S</u> Range <u>36E</u> NMPM <u>County LEA</u>			
11. Elevation (Show whether DR, RKB, RT, GR, etc.) 3,640' - GR			
12. Check Appropriate Box to Indicate Nature of Notice, Report or Other	Data		
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF: PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK ALTERING CASING TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLING OPNS. P AND A X PULL OR ALTER CASING MULTIPLE COMPL CASING/CEMENT JOB I			
OTHER: Image: Content of the conten			
 X Rat hole and cellar have been filled and leveled. Cathodic protection holes have been properly abandoned. 			
X A steel marker at least 4" in diameter and at least 4' above ground level has been set in concrete. It shows the			
<u>OPERATOR NAME, LEASE NAME, WELL NUMBER, API NUMBER, QUARTER/QUARTER LOCATION OR</u>			
UNIT LETTER, SECTION, TOWNSHIP, AND RANGE. All INFORMATION HAS BEEN WELDED OR			
PERMANENTLY STAMPED ON THE MARKER'S SURFACE.			
X The location has been leveled as nearly as possible to original ground contour and has been cleared of all junk, trash, flow lines and			
other production equipment.			
 Anchors, dead men, tie downs and risers have been cut off at least two feet below ground level. X If this is a one-well lease or last remaining well on lease, the battery and pit location(s) have been remediated in compliance with 			
OCD rules and the terms of the Operator's pit permit and closure plan. All flow lines, production equipment and junk have been removed			
from lease and well location.			
X All metal bolts and other materials have been removed. Portable bases have been removed. (Poured onsite concrete bases do not have			
to be removed.) X All other environmental concerns have been addressed as per OCD rules.			
 X Pipelines and flow lines have been abandoned in accordance with 19.15.35.10 NMAC. All fluids have been removed from non- 			
retrieved flow lines and pipelines.			
X If this is a one-well lease or last remaining well on lease: all electrical service poles and lines have been removed from lease and well location, except for utility's distribution infrastructure.			
When all work has been completed, return this form to the appropriate District office to schedule an inspection.			
SIGNATURE	or DATE 02-11-13		
TYPE OR PRINT NAME John Robinson E-MAIL:john_robinson For State Use Only	@xtoenergy.com PHONE: _441-5199		

APPROVED BY: Wah Whiteken	TITLE Compliance Officar	DATE 02-12-2013